

YOUR VEHICLE DATA

Scrapped

Exported

Imported

Plate Change

Colour Change

Mileage

Taxi

Recall

Keepers

4

Keeper

25-Aug-25
12-Feb-09
07-Sep-01
01-Sep-01

Taxed

Tax due: 01-Apr-27

Vehicle Make	MITSUBISHI
Fuel Type	PETROL
Cylinder Capacity	2000
Vehicle Colour	SILVER
Euro Stats	***
Co2 Emissions	***
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

MOT Status

Expires 13-Aug-26


Year Of Manufacture	1995
Date Of First Registration	Sep-01
Date Of Last V5C (logbook) Issued	07-Apr-26
Export Marker	***
Vehicle Type Approval	***
Revenue Weight	***
Vehicle Status	Taxed
MOT Status	Valid





Mot & Mileage Summary

Total Test	23	✗ Pass Rate	52%
✓ Test Passed	12	! Pass Rate With Advisory	75%
! Passed With Advisory	9	✓ Pass Rate Without Advisory	25%
! Total Items Advised	77	✓ Mileage Issues	No
! Advisory Average/Per MOT	6.42	Last MOT Mileage	157327 MI
✗ Test Failed	11	Est Current Mileage	157439 MI
✗ Total Items Failed	62	Average Mileage	5244 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✓ Mileage Status	Below Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
25-Aug-25	! KEEPER 4				
14-Aug-25	✓ PASS	157327 MI	25	22	Failures(0) Advisories(20)
23-Jul-25	✗ FAIL	157302 MI	166	383	Failures(4) Advisories(12)
05-Jul-24	✓ PASS	157136 MI	0	0	Failures(0) Advisories(7)
05-Jul-24	✗ FAIL	157136 MI	2224	380	Failures(0) Advisories(7)
21-Jun-23	✓ PASS	154912 MI	0	0	Failures(0) Advisories(9)
21-Jun-23	✗ FAIL	154912 MI	2386	609	Failures(0) Advisories(9)

20-Oct-21	 PASS	152526 MI	27	54	Failures(0) Advisories(4)
27-Aug-21	 FAIL	152499 MI	4467	371	Failures(4) Advisories(2)
21-Aug-20	 PASS	148032 KM	0	0	Failures(0) Advisories(2)
21-Aug-20	 FAIL	148032 KM	4184	373	Failures(0) Advisories(2)
14-Aug-19	 PASS	143848 MI	0	0	Failures(0) Advisories(7)
14-Aug-19	 FAIL	143848 MI	2492	349	Failures(0) Advisories(7)
30-Aug-18	 PASS	141356 MI	17	15	Failures(0) Advisories(3)
15-Aug-18	 FAIL	141339 MI	877	2072	Failures(9) Advisories(4)
12-Dec-12	 PASS	140462 MI	4	21	Failures(0) Advisories(11)
21-Nov-12	 FAIL	140458 MI	841	987	Failures(16) Advisories(10)
10-Mar-10	 PASS	139617 MI	6	12	Failures(0) Advisories(14)
26-Feb-10	 FAIL	139611 MI	17	15	Failures(6) Advisories(19)
11-Feb-10	 FAIL	139594 MI	10248	364	Failures(2) Advisories(1)
12-Feb-09	 PASS	129346 MI	0	0	Failures(0) Advisories(0)
12-Feb-09	 FAIL	129346 MI	2824	532	Failures(2) Advisories(3)
12-Feb-09	 KEEPER 3				

30-Aug-07	 PASS	126522 KM	5040	370	Failures(0) Advisories(0)
25-Aug-06	 PASS	121482 KM	0	0	Failures(0) Advisories(0)
07-Sep-01	 KEEPER 2				
01-Sep-01	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
Keeper	25-Aug-25			
21	14-Aug-25	157327 MI	25 MI	22
20	23-Jul-25	157302 MI	166 MI	383
19	05-Jul-24	157136 MI	0	0
18	05-Jul-24	157136 MI	2224 MI	380
17	21-Jun-23	154912 MI	0	0
16	21-Jun-23	154912 MI	2386 MI	609
15	20-Oct-21	152526 MI	27 MI	54
14	27-Aug-21	152499 MI	4467 MI	371
13	21-Aug-20	148032 KM	0	0
12	21-Aug-20	148032 KM	4184 MI	373
11	14-Aug-19	143848 MI	0	0
10	14-Aug-19	143848 MI	2492 MI	349
9	30-Aug-18	141356 MI	17 MI	15

8	15-Aug-18	141339 MI	877 MI	2072
7	12-Dec-12	140462 MI	4 MI	21
6	21-Nov-12	140458 MI	841 MI	987
5	10-Mar-10	139617 MI	6 MI	12
4	26-Feb-10	139611 MI	17 MI	15
3	11-Feb-10	139594 MI	10248 MI	364
2	12-Feb-09	129346 MI	0	0
1	12-Feb-09	129346 MI	2824 MI	532
Keeper	12-Feb-09			
0	30-Aug-07	126522 KM	5040 MI	370
-1	25-Aug-06	121482 KM		0
Keeper	07-Sep-01			
Keeper	01-Sep-01			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Miles / KMs Warning

A mixture of Miles and KMs has been detected in the MOT history.

Vehicle Information

Vehicle Registration Mark	M985MYR	Make & Model	MITSUBISHI
Make	MITSUBISHI	Model	
Engine Capacity	***	Year of Manufacture	1995
Fuel	***	Date First Registered	01-Sep-01
Premium Vehicle Year 2 to 6 - Twelve Month	***	Date of 1st Registration in UK	01-Sep-01
Colour	SILVER	Year-Month 1st Registered	2001-09
CO2 Emissions	***	Transmission	***
Gear Count	***	Transmission Type	***
Engine Number	NOT KNOWN	Transmission Code	***
Gross Weight	***	Door Plan Code	***
Maximum Permissible Mass	***	MVRIS Model Code	***
Seating Capacity	***	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	***	Vin Confirmation Flag	***
Date Of Last Update	04-Feb-26 07:22:11		

General Information

Make	***	Euro Status	***
Aspiration	***	Fuel System	
Number Of Cylinders	***	Fuel Delivery	
Valves Per Cylinder	***	Fuel Catalyst	***
Cylinder Arrangement	***	Stroke	***
Valve Gear	***	Location	***
Description	***	Bore	***
Power Delivery	Normal	Type Approval Category	***
Driving Axle	***	Primary Fuel Flag	***
Series Description	***	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	4	Keeper Data Count	3
Keeper 4 (Current Keeper)			25-Aug-25
Keeper 3			12-Feb-09
Keeper 2			07-Sep-01
Keeper 1 (First Keeper)			01-Sep-01

V5C Certificate issue details

V5C Certificate Count	2	Certificate Dates	15-Sep-25 13-Feb-21
-----------------------	---	-------------------	------------------------

Vehicle Tax & CO2 Emissions

Standard Six Month	***	Per Month	0
Standard Twelve Month	0	Per Month	0
First Year Six Month	---	Per Month	---
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	---	Per Month	---
Premium Vehicle Year 2 to 6 - Twelve Month	---	Per Month	---
VED CO? Emissions	N/A	VED Band	N/A
VED CO? Band	N/A		

Performance Information

Torque FtLb	***	Power Rpm	***
Torque Rpm	***	Power Bhp	***
Torque Nm	***	Power Kw	***
Co?	***	NoiseLevel	***
Max Speed Mph	***	Particles	***
Max Speed Kph	***	Data Version Number	***
Acceleration Zero To 60Mph	***	Acceleration Mph	***
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	***	Combined Lkm	***
ExtraUrban Mpg	***	ExtraUrban Lkm	***
UrbanCold Mpg	***	UrbanCold Lkm	***

✓ Plate Change History

Plate Change Count ***

✗ Import/Export

Exported	No	Export Date	***
Imported	Yes		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	SILVER	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	SILVER		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	***	Height	***
Gross Combined Weight	***	Width	***
Kerb Weight	***	Car Length	***
Unladen Weight	***	Wheel Base	***
Fuel Tank Capacity	***	Pay Load Weight	***
Number Of Doors	***	Gross Train Weight	***
Number Of Seats	***	Payload Volume	***
Rigid Artic	***	Load Length	***
Number Of Axles	***	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	***	DVLA Make	***	MITSUBISHI
SMMT Range	***	DVLA Model		
SMMT Trim	***	Is Electric Vehicle		
SMMT Mvris MakeCode	***	Is GB General Format	***	
SMMT Mvris ModelCode	***	Is NI General Format	***	

Smmt Details

Marque	***	Range	***
Model Variant	***	Fuel Type	***
Nominal Engine Capacity	***	Transmission	***
Engine Capacity	***	Number Of Doors	***
Body Style	***	Number Of Gears	***
DriveType	***	SysSetup Date	***
Country Of Origin	***	Visibility Date	***
Series	***	TerminateDate	***
Marque Code	***	Cab Type	NA
Market Sector Code	***	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

14-Aug-25



PASS

157327 MI

447906179706

Advisories

- ADVISORY** emissions erratic
- ADVISORY** wipers worn
- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Coolant leak
- ADVISORY** brake pedal rubber worn
- ADVISORY** fuel cap seal perished
- ADVISORY** Offside Rear Upper Vehicle structure is repaired but structural rigidity is not significantly reduced (6.1.1 (d) (i))
- ADVISORY** Nearside Rear Upper Vehicle structure is repaired but structural rigidity is not significantly reduced (6.1.1 (d) (i))
- ADVISORY** Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced wheel arch (6.1.1 (c) (i))
- ADVISORY** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- ADVISORY** rear inner sills corroded
- ADVISORY** slight susp knock n/s/f
- ADVISORY** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MINOR** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- MINOR** Nearside Front Outer Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

23-Jul-25



FAIL

157302 MI

869299449226

Advisories

- ADVISORY** fuel cap seal perished
- ADVISORY** Oil leak, but not excessive engine (8.4.1 (a) (i))
- ADVISORY** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
- ADVISORY** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- ADVISORY** Nearside Rear Vehicle structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
- ADVISORY** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- ADVISORY** Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- ADVISORY** sill panels corroded
- MINOR** Nearside Rear Outer Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Failures

- MAJOR** Brake pedal anti-slip provision missing (1.1.2 (c))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits emissions test aborted (8.2.1.2 (a))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Offside Rear Inner Vehicle structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting wheel arch susp mounting (6.2.2 (d) (i))

05-Jul-24



PASS

157136 MI

248146194797

Advisories

- ADVISORY** radiator mounting panel corroded
- ADVISORY** o/s/f and n/s/f upper spring cups corroded
- ADVISORY** engine oil leak evident/frontal area
- ADVISORY** front tyres perished deeply
- ADVISORY** front floors / chassis rail corroded
- ADVISORY** rear floor chassis and inner sills corroded
- ADVISORY** n/s/r brake slight binding

05-Jul-24



FAIL

157136 MI

403876029922

Advisories

- ADVISORY** radiator mounting panel corroded
- ADVISORY** o/s/f and n/s/f upper spring cups corroded
- ADVISORY** engine oil leak evident/frontal area
- ADVISORY** front tyres perished deeply
- ADVISORY** front floors / chassis rail corroded
- ADVISORY** rear floor chassis and inner sills corroded
- ADVISORY** n/s/r brake slight binding

Failures

- PRS** Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

21-Jun-23



PASS

154912 MI

920834688679

Advisories

- ADVISORY** eml light on
- ADVISORY** fuel cap seal perished/neck corroded
- ADVISORY** engine oil leaking
- ADVISORY** arb links worn front
- ADVISORY** n/s/f tyre low on edges
- ADVISORY** front tyres perished sidewalls
- ADVISORY** front floor pans and chassis corroded
- ADVISORY** rear inner sills corroded
- ADVISORY** rear brake discs corroded

21-Jun-23



FAIL

154912 MI

702138032466

Advisories

- ADVISORY** eml light on
- ADVISORY** fuel cap seal perished/neck corroded
- ADVISORY** engine oil leaking
- ADVISORY** arb links worn front
- ADVISORY** n/s/f tyre low on edges
- ADVISORY** front tyres perished sidewalls
- ADVISORY** front floor pans and chassis corroded
- ADVISORY** rear inner sills corroded
- ADVISORY** rear brake discs corroded

Failures

- PRS** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

20-Oct-21



PASS

152526 MI

528143182244

Advisories

- ADVISORY** eml int on
- ADVISORY** engine oil leaking rear cam cover area
- ADVISORY** parking brake performance poor
- ADVISORY** emissions erratic/eml on and off

27-Aug-21



FAIL

152499 MI

997362000167

Advisories

- ADVISORY** engine oil leaking rear cam cover area
- ADVISORY** parking brake performance poor

Failures

- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- MAJOR** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))

21-Aug-20



PASS

148032 KM

526060161487

Advisories

- ADVISORY** fuel cap seal perished
- ADVISORY** brake pedal rubber worn

21-Aug-20



FAIL

148032 KM

807028214620

Advisories

- ADVISORY** fuel cap seal perished
- ADVISORY** brake pedal rubber worn

Failures

- PRS** Exhaust hydrocarbon content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- PRS** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

14-Aug-19



PASS

143848 MI

642379324840

Advisories

- ADVISORY** rear chassis corroded
- ADVISORY** front floor pans chassis rails corroded/damaged
- ADVISORY** engine oil sump damaged
- ADVISORY** engine oil leaking frontal areas bank 1 and bank 2
- ADVISORY** fuel cap seal deeply perished
- ADVISORY** Offside Front steering rack boot perished/slightly split
- ADVISORY** eml lamp int on

14-Aug-19



FAIL

143848 MI

358581185541

Advisories

- ADVISORY** rear chassis corroded
- ADVISORY** front floor pans chassis rails corroded/damaged
- ADVISORY** engine oil sump damaged
- ADVISORY** engine oil leaking frontal areas bank 1 and bank 2
- ADVISORY** fuel cap seal deeply perished
- ADVISORY** Offside Front steering rack boot perished/slightly split
- ADVISORY** eml lamp int on

Failures

- PRS** Offside Front Headlamp aim too high (4.1.2 (a))
- PRS** Nearside Front Headlamp aim too low (4.1.2 (a))

30-Aug-18



PASS

141356 MI

254464247712

Advisories

- ADVISORY** brake pedal rubber worn
- ADVISORY** Nearside Non obligatory mirror damaged
- ADVISORY** battery positive terminal insecure

15-Aug-18



FAIL

141339 MI

151166834609

Advisories

- ADVISORY** brake pedal rubber worn
- ADVISORY** Nearside Non obligatory mirror damaged
- ADVISORY** battery positive terminal insecure
- ADVISORY** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Failures

- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Rear Registration plate inscription illegible (0.1 (b))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- MAJOR** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (ii))
- MAJOR** Nearside Front Suspension component mounting prescribed area is inadequately repaired (5.3.6 (a) (ii))
- MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (ii))
- MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (ii))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

12-Dec-12



PASS

140462 MI

115487942328

Advisories

- ADVISORY** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- ADVISORY** Outer Rear Suspension arm has slight play in a pin/bush (2.4.G.2)
- ADVISORY** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- ADVISORY** Nearside Rear Vehicle structure has slight corrosion (6.1.A.1)
- ADVISORY** Offside Rear Vehicle structure has slight corrosion (6.1.A.1)
- ADVISORY** Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- ADVISORY** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- USER ENTERED** Nearside headlamp beam slightly weak
- USER ENTERED** Battery insecure

21-Nov-12



FAIL

140458 MI

456326622455

Advisories

- ADVISORY** Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- ADVISORY** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- ADVISORY** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- ADVISORY** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- ADVISORY** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- ADVISORY** Nearside Rear Vehicle structure has slight corrosion (6.1.A.1)
- ADVISORY** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Nearside Rear rear brake grabbing slightly (3.7.A.5b)
- USER ENTERED** Rear exhaust bracket fouling on the floor

Failures

- Failed** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Failed** Direction indicators not working (1.4.A.2c)
- Failed** Side repeater not working (1.4.A.2c)
- Failed** Hazard warning lamps inoperative (1.4.B.1b)
- Failed** Hazard warning tell tale not working correctly (1.4.B.1e)
- Failed** Rear registration plate missing (6.3.1a)
- Failed** Front registration plate missing (6.3.1a)
- Failed** Nearside Headlamp not working on dipped beam (1.7.5a)
- Failed** Offside Headlamp excessively damaged so that the light output is severely reduced (1.7.5a)
- Failed** Offside Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Failed** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Failed** Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)
- Failed** Nearside Steering locking device missing (2.2.C.1g)
- Failed** Front Wheel nut(s) missing (4.2.A.1e)
- Failed** Nearside Rear Wheel nut(s) missing (4.2.A.1e)
- Failed** Service brake: efficiency below requirements (3.7.B.7)

10-Mar-10



PASS

139617 MI

541289560079

Advisories

- ADVISORY** Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)
- ADVISORY** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- ADVISORY** Front Exhaust has part of the system slightly deteriorated (7.1.1a)
- ADVISORY** Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- ADVISORY** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- USER ENTERED** brake pedal anti slip wearing thin
- USER ENTERED** Oil leak
- USER ENTERED** offside front inner cv boot split
- USER ENTERED** Nearside outer track rod end joint cover split/missing
- USER ENTERED** Suspension joint nearside lower dust cover split/missing
- USER ENTERED** Suspension joint offside upper dust cover split/missing
- USER ENTERED** rear number plate cracked
- USER ENTERED** underside rusty and previous repairs.
- USER ENTERED** high level brake light only 50% working

26-Feb-10



FAIL

139611 MI

764437950061

Advisories

- ADVISORY** Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- ADVISORY** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- ADVISORY** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- ADVISORY** Offside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)
- ADVISORY** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- ADVISORY** Front Exhaust has part of the system slightly deteriorated (7.1.1a)
- ADVISORY** Nearside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- ADVISORY** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)
- USER ENTERED** brake pedal anti slip wearing thin
- USER ENTERED** Oil leak
- USER ENTERED** offside front inner cv boot split
- USER ENTERED** damage on tyre sidewalls
- USER ENTERED** no air filter or housing fitted
- USER ENTERED** Nearside outer track rod end joint cover split/missing
- USER ENTERED** Suspension joint nearside lower dust cover split/missing
- USER ENTERED** Suspension joint offside upper dust cover split/missing
- USER ENTERED** rear number plate cracked
- USER ENTERED** underside rusty and previous repairs.
- USER ENTERED** high level brake light only 50% working

Failures

- Failed** Nearside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)
- Failed** Offside Rear Suspension component mounting prescribed area is fractured (2.4.A.3)
- Failed** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Failed** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Failed** Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)
- Failed** Front Headlamps matched pair are not the same colour (1.7.6)

11-Feb-10



FAIL

139594 MI

600332740089

Advisories

- ADVISORY** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Failures

- Failed** Exhaust engine idle speed too high (7.3.D.1)
- Failed** Offside Rear Registration plate lamp not working (1.1.C.1d)

12-Feb-09



PASS

129346 MI

731913949031

12-Feb-09



FAIL

129346 MI

860393049006

Advisories

ADVISORY Front brake disc slightly pitted (3.5.1h)

ADVISORY Rear brake disc slightly scored (3.5.1h)

USER ENTERED ADVISED FRONT AND REAR SUSPENSION NOISEY

Failures

Failed Offside Front Steering rack gaiter split (2.2.D.2d)

Failed Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)

30-Aug-07



PASS

126522 KM

513862247204

25-Aug-06



PASS

121482 KM

541107036230

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.