

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✗	Taxi	✓	Recall	✓	Keepers	3	Keeper	18-Dec-25 30-Aug-06 23-Mar-06

**Taxed**

Tax due: 01-Dec-26

Vehicle Make	SEAT
Fuel Type	DIESEL
Cylinder Capacity	1896
Vehicle Colour	BLACK
Euro Stats	***
Co2 Emissions	132 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

**MOT Status**

Expires 03-Aug-26

Year Of Manufacture	2006
Date Of First Registration	Mar-06
Date Of Last V5C (logbook) Issued	18-Dec-25
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	***
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	30	✗ Pass Rate	56%
✓ Test Passed	17	! Pass Rate With Advisory	70%
! Passed With Advisory	12	✓ Pass Rate Without Advisory	30%
! Total Items Advised	39	✗ Mileage Issues	Yes
! Advisory Average/Per MOT	2.29	Last MOT Mileage	116670 MI
✗ Test Failed	13	Est Current Mileage	118774 MI
✗ Total Items Failed	52	Average Mileage	6140 Miles/Year
✓ Taxi/Rent a Car Use	Might not	icon Mileage Status	Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
18-Dec-25	! KEEPER 3				
28-Jul-25	✓ PASS	116670 MI	-2000	0	Failures(0) Advisories(3)
28-Jul-25	✗ FAIL	118670 MI	4433	363	Failures(4) Advisories(3)
30-Jul-24	✓ PASS	114237 MI	0	1	Failures(0) Advisories(3)
29-Jul-24	✗ FAIL	114237 MI	5224	375	Failures(8) Advisories(1)
20-Jul-23	✓ PASS	109013 MI	0	1	Failures(0) Advisories(5)
19-Jul-23	✗ FAIL	109013 MI	4512	359	Failures(6) Advisories(5)

25-Jul-22	 PASS	104501 MI	2	0	Failures(0) Advisories(8)
25-Jul-22	 FAIL	104499 MI	4225	364	Failures(5) Advisories(8)
26-Jul-21	 PASS	100274 MI	1	0	Failures(0) Advisories(3)
26-Jul-21	 FAIL	100273 MI	3733	367	Failures(2) Advisories(3)
24-Jul-20	 PASS	96540 MI	170	7	Failures(0) Advisories(2)
17-Jul-20	 FAIL	96370 MI	4173	351	Failures(4) Advisories(2)
01-Aug-19	 PASS	92197 MI	1	0	Failures(0) Advisories(4)
01-Aug-19	 FAIL	92196 MI	5053	374	Failures(2) Advisories(5)
23-Jul-18	 PASS	87143 MI	0	0	Failures(0) Advisories(0)
23-Jul-18	 FAIL	87143 MI	4692	363	Failures(1) Advisories(0)
25-Jul-17	 PASS	82451 MI	2	1	Failures(0) Advisories(1)
24-Jul-17	 FAIL	82449 MI	6182	362	Failures(5) Advisories(1)
27-Jul-16	 PASS	76267 MI	5987	372	Failures(0) Advisories(3)
21-Jul-15	 PASS	70280 MI	0	0	Failures(0) Advisories(0)
21-Jul-15	 FAIL	70280 MI	5729	351	Failures(5) Advisories(0)
04-Aug-14	 PASS	64551 MI	1	0	Failures(0) Advisories(0)

04-Aug-14	 FAIL	64550 MI	5913	367	Failures(4) Advisories(0)
02-Aug-13	 PASS	58637 MI	6531	365	Failures(0) Advisories(2)
02-Aug-12	 PASS	52106 MI	0	0	Failures(0) Advisories(2)
02-Aug-12	 FAIL	52106 MI	-388288	371	Failures(4) Advisories(4)
28-Jul-11	 PASS	440394 MI	403565	359	Failures(0) Advisories(3)
03-Aug-10	 PASS	36829 MI	8039	364	Failures(0) Advisories(0)
04-Aug-09	 FAIL	28790 MI	0	0	Failures(0) Advisories(0)
04-Aug-09	 PASS	28790 MI	0	0	Failures(0) Advisories(0)
30-Aug-06	 KEEPER 2				
23-Mar-06	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
Keeper	18-Dec-25			
30	28-Jul-25	116670 MI	-2000 MI	0
29	28-Jul-25	118670 MI	4433 MI	363
28	30-Jul-24	114237 MI	0	1
27	29-Jul-24	114237 MI	5224 MI	375
26	20-Jul-23	109013 MI	0	1

25	19-Jul-23	109013 MI	4512 MI	359
24	25-Jul-22	104501 MI	2 MI	0
23	25-Jul-22	104499 MI	4225 MI	364
22	26-Jul-21	100274 MI	1 MI	0
21	26-Jul-21	100273 MI	3733 MI	367
20	24-Jul-20	96540 MI	170 MI	7
19	17-Jul-20	96370 MI	4173 MI	351
18	01-Aug-19	92197 MI	1 MI	0
17	01-Aug-19	92196 MI	5053 MI	374
16	23-Jul-18	87143 MI	0	0
15	23-Jul-18	87143 MI	4692 MI	363
14	25-Jul-17	82451 MI	2 MI	1
13	24-Jul-17	82449 MI	6182 MI	362
12	27-Jul-16	76267 MI	5987 MI	372
11	21-Jul-15	70280 MI	0	0
10	21-Jul-15	70280 MI	5729 MI	351
9	04-Aug-14	64551 MI	1 MI	0
8	04-Aug-14	64550 MI	5913 MI	367
7	02-Aug-13	58637 MI	6531 MI	365
6	02-Aug-12	52106 MI	0	0
5	02-Aug-12	52106 MI	-388288 MI	371
4	28-Jul-11	440394 MI	403565 MI	359

3	03-Aug-10	36829 MI	8039 MI	364
2	04-Aug-09	28790 MI	0	0
1	04-Aug-09	28790 MI		0
Keeper	30-Aug-06			
Keeper	23-Mar-06			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Mileage Reverse

A discrepancy in mileage has been detected in the MOT history.

Vehicle Information

Vehicle Registration Mark	KP06VLA	Make & Model	SEAT IBIZA SPORT TDI
Make	SEAT	Model	IBIZA SPORT TDI
Engine Capacity	1896	Year of Manufacture	2006
Fuel Type	DIESEL	Date First Registered	23-Mar-06
Door Plan	3 DOOR HATCHBACK	Date of 1st Registration in UK	23-Mar-06
Colour	BLACK	Year-Month 1st Registered	2006-03
CO2 Emissions	132 g/km	Transmission	MANUAL 5 GEARS
Gear Count	5	Transmission Type	Manual
Engine Number	ATD767438	Transmission Code	M
Gross Weight	1682	Door Plan Code	13
Maximum Permissible Mass	1682	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	04-Feb-26 04:02:51		

General Information

Make	Seat	Euro Status	4
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	2	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	96
Valve Gear	SOHC	Location	FRONT
Description	AT/D	Bore	80
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	6L	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	3	Keeper Data Count	2
Keeper 3 (Current Keeper)			18-Dec-25
Keeper 2			30-Aug-06
Keeper 1 (First Keeper)			23-Mar-06

V5C Certificate issue details

V5C Certificate Count	2	Certificate Dates	18-Dec-25 01-Mar-12
-----------------------	---	-------------------	------------------------

Vehicle Tax & CO2 Emissions

Standard Six Month	110	Per Month	18.33
Standard Twelve Month	200	Per Month	16.67
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	132 g/km	VED Band	E
VED CO2 Band	E		

Performance Information

Torque FtLb	177.1	Power Rpm	4000
Torque Rpm	1800	Power Bhp	99.2
Torque Nm	240	Power Kw	74
CO2	***	NoiseLevel	***
Max Speed Mph	118	Particles	***
Max Speed Kph	190	Data Version Number	***
Acceleration Zero To 60Mph	10.8	Acceleration Mph	10.8
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	56.5	Combined Lkm	5
ExtraUrban Mpg	68.9	ExtraUrban Lkm	4.1
UrbanCold Mpg	43.5	UrbanCold Lkm	6.5

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	BLACK	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	BLACK		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1682	Height	1441
Gross Combined Weight	1682	Width	1698
Kerb Weight	1169	Car Length	3953
Unladen Weight	1169	Wheel Base	2460
Fuel Tank Capacity	45	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Seat	DVLA Make	SEAT
SMMT Range	Ibiza	DVLA Model	IBIZA SPORT TDI
SMMT Trim	Ibiza Sport TDI	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Seat	Range	Ibiza
Model Variant	Ibiza Sport TDI	Fuel Type	Diesel
Nominal Engine Capacity	1.9	Transmission	Manual
Engine Capacity	1896	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	5
DriveType	4x2	SysSetup Date	17-Dec-04
Country Of Origin	Spain	Visibility Date	17-Dec-04
Series	6L	Terminate Date	29-Sep-06
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

28-Jul-25	 PASS	116670 MI	788313058364
-----------	---	-----------	--------------

Advisories

- ADVISORY** Offside Front Tyre slightly damaged/cracking or perishing Inner wall split (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- ADVISORY** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

28-Jul-25	 FAIL	118670 MI	233284559470
-----------	---	-----------	--------------

Advisories

- ADVISORY** Offside Front Tyre slightly damaged/cracking or perishing Inner wall split (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- ADVISORY** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Failures

- MAJOR** Nearside Headlamp light intensity severely reduced (4.1.4 (a))
- MAJOR** Offside Headlamp light intensity severely reduced (4.1.4 (a))
- MAJOR** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))

30-Jul-24	 PASS	114237 MI	265845618366
-----------	---	-----------	--------------

Advisories

- ADVISORY** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- MINOR** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- MINOR** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

29-Jul-24	 FAIL	114237 MI	981399440339
-----------	---	-----------	--------------

Advisories

ADVISORY Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Failures

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Inner wall (5.2.3 (d) (i))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Inner wall (5.2.3 (d) (i))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover missing (5.3.4 (b) (ii))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Headlamp light intensity severely reduced (4.1.4 (a))

MAJOR Offside Headlamp light intensity severely reduced (4.1.4 (a))

20-Jul-23



PASS

109013 MI

810565495713

Advisories

ADVISORY Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MINOR Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MINOR Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

19-Jul-23



FAIL

109013 MI

719606765924

Advisories

ADVISORY Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MINOR Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MINOR Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Failures

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure Inner sidewall (5.2.3 (d) (ii))

MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))

MAJOR Nearside Headlamp light intensity severely reduced (4.1.4 (a))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

25-Jul-22



PASS

104501 MI

791781376113

Advisories

- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Nail in tyre
- ADVISORY** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- ADVISORY** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- ADVISORY** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- ADVISORY** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- MINOR** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- MINOR** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

25-Jul-22



FAIL

104499 MI

414654103000

Advisories

- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Nail in tyre
- ADVISORY** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- ADVISORY** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- ADVISORY** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- ADVISORY** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- MINOR** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- MINOR** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Failures

- MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))
- MAJOR** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Exhaust emissions exceed level of metered smoke for a turbo charged engine 1.13 (8.2.2.2 (b))

26-Jul-21



PASS

100274 MI

756277826525

Advisories

- ADVISORY** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- ADVISORY** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

26-Jul-21



FAIL

100273 MI

834516696154

Advisories

- ADVISORY** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- ADVISORY** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Failures

- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

24-Jul-20



PASS

96540 MI

692878812784

Advisories

- ADVISORY** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- ADVISORY** Driver's door catch deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

17-Jul-20



FAIL

96370 MI

657629855852

Advisories

- ADVISORY** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- ADVISORY** Driver's door catch deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))

Failures

- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

01-Aug-19



PASS

92197 MI

521774204516

Advisories

- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MINOR** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MINOR** Rear Windscreen wiper blade defective (3.4 (b) (i))

01-Aug-19



FAIL

92196 MI

103122192843

Advisories

- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MINOR** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MINOR** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- MINOR** Rear Windscreen wiper blade defective (3.4 (b) (i))

Failures

- MAJOR** Rear Registration plate inscription illegible (0.1 (b))
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

23-Jul-18



PASS

87143 MI

956094192047

23-Jul-18



FAIL

87143 MI

452180215303

Failures

- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

25-Jul-17



PASS

82451 MI

806091784399

Advisories

- ADVISORY** Offside front brake fluctuating, but not excessively (3.7.B.3)

24-Jul-17



FAIL

82449 MI

919584289410

Advisories

- ADVISORY** Offside front brake fluctuating, but not excessively (3.7.B.3)

Failures

- Failed** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Failed** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Failed** Offside rear brake binding (3.7.B.1)
- Failed** Nearside Front coil spring broken (2.4.C.1a)
- Failed** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

27-Jul-16



PASS

76267 MI

967990695022

Advisories

- ADVISORY** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- ADVISORY** Offside front brake fluctuating, but not excessively (3.7.B.3)
- ADVISORY** Offside rear brake binding slightly

21-Jul-15



PASS

70280 MI

865552505247

21-Jul-15



FAIL

70280 MI

359942405241

Failures

- Failed** Nearside Rear Stop lamp adversely affected by the operation of another lamp (1.2.1f)
- Failed** Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)
- Failed** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Failed** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Failed** Nearside Front position lamp(s) not working (1.1.A.3b)

04-Aug-14



PASS

64551 MI

398246914215

04-Aug-14



FAIL

64550 MI

337586414243

Failures

- Failed** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Failed** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Failed** Offside Stop lamp not working (1.2.1b)
- Failed** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

02-Aug-13



PASS

58637 MI

216234313272

Advisories

- ADVISORY** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- ADVISORY** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

02-Aug-12



PASS

52106 MI

849075212264

Advisories

- ADVISORY** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- ADVISORY** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

02-Aug-12



FAIL

52106 MI

118275512215

Advisories

- ADVISORY** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- ADVISORY** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Failures

- Failed** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Failed** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Failed** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
- Failed** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

28-Jul-11



PASS

440394 MI

347619501411

Advisories

- ADVISORY** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- ADVISORY** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- USER ENTERED** Some wear to both front brake discs

03-Aug-10



PASS

36829 MI

492435410204

04-Aug-09



FAIL

28790 MI

554496619261

Failures

- PRS** Offside Rear position lamp(s) excessively deteriorated so that it is not visible from a reasonable distance (1.1.A.3d)
- PRS** Offside Headlamp not in good working order adversely affecting beam image (1.2.4a)

04-Aug-09



PASS

28790 MI

451966519215

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.