

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✗	Taxi	✓	Recall	✓	Keepers	9	Keeper	03-Feb-24 26-Mar-22 31-Jan-22 18-Sep-18 01-Mar-06

✓ Taxed Tax due: 01-Feb-27		✓ MOT Status Expires 10-Jan-27	
Vehicle Make	TOYOTA	Year Of Manufacture	2006
Fuel Type	PETROL	Date Of First Registration	Mar-06
Cylinder Capacity	1296	Date Of Last V5C (logbook) Issued	15-Nov-25
Vehicle Colour	SILVER	Export Marker	***
Euro Stats	***	Vehicle Type Approval	M1
Co2 Emissions	136 g/km	Revenue Weight	***
Real Driving Emissions (RDE)	***	Vehicle Status	Taxed
Wheelplan	2 AXLE RIGID BODY	MOT Status	Valid
Ulez Compliance	Check TFL		

Mot & Mileage Summary

Total Test	27	✖ Pass Rate	62%
✔ Test Passed	17	! Pass Rate With Advisory	58%
! Passed With Advisory	10	✔ Pass Rate Without Advisory	42%
! Total Items Advised	33	✖ Mileage Issues	Yes
! Advisory Average/Per MOT	1.94	Last MOT Mileage	149853 MI
✖ Test Failed	10	Est Current Mileage	152621 MI
✖ Total Items Failed	50	Average Mileage	7492 Miles/Year
✔ Taxi/Rent a Car Use	Might not	icon Mileage Status	Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
08-Jan-26	✔ PASS	149853 MI	5	0	Failures(0) Advisories(4)
08-Jan-26	✖ FAIL	149848 MI	6830	385	Failures(5) Advisories(4)
19-Dec-24	✔ PASS	143018 MI	6	0	Failures(0) Advisories(9)
19-Dec-24	✖ FAIL	143012 MI	47	23	Failures(2) Advisories(9)
26-Nov-24	✖ FAIL	142965 MI	5033	320	Failures(17) Advisories(12)
03-Feb-24	! KEEPER 9				
11-Jan-24	✔ PASS	137932 MI	10037	367	Failures(0) Advisories(8)

09-Jan-23	 PASS	127895 MI	6457	391	Failures(0) Advisories(2)
26-Mar-22	 KEEPER 8				
31-Jan-22	 KEEPER 7				
14-Dec-21	 PASS	121438 MI	1	5	Failures(0) Advisories(2)
09-Dec-21	 FAIL	121437 MI	4817	351	Failures(8) Advisories(2)
23-Dec-20	 PASS	116620 MI	8378	372	Failures(0) Advisories(0)
17-Dec-19	 PASS	108242 MI	13794	355	Failures(0) Advisories(0)
27-Dec-18	 PASS	94448 MI	1	0	Failures(0) Advisories(1)
27-Dec-18	 FAIL	94447 MI	7324	364	Failures(5) Advisories(1)
18-Sep-18	 KEEPER 6				
28-Dec-17	 PASS	87123 MI	0	0	Failures(0) Advisories(2)
28-Dec-17	 FAIL	87123 MI	13120	537	Failures(0) Advisories(2)
09-Jul-16	 PASS	74003 MI	0	0	Failures(0) Advisories(1)
09-Jul-16	 FAIL	74003 MI	8142	378	Failures(0) Advisories(1)
27-Jun-15	 PASS	65861 MI	0	0	Failures(0) Advisories(0)
27-Jun-15	 FAIL	65861 MI	11289	541	Failures(5) Advisories(0)

02-Jan-14	 FAIL	54572 MI	9066	577	Failures(0) Advisories(3)
02-Jan-14	 PASS	54572 MI	0	0	Failures(0) Advisories(3)
04-Jun-12	 PASS	45506 MI	477	143	Failures(0) Advisories(1)
13-Jan-12	 PASS	45029 MI	45029	1	Failures(0) Advisories(0)
12-Jan-12	 FAIL	0	-39520	363	Failures(3) Advisories(0)
14-Jan-11	 PASS	39520 MI	5591	343	Failures(0) Advisories(0)
05-Feb-10	 PASS	33929 MI	6176	364	Failures(0) Advisories(0)
06-Feb-09	 PASS	27753 MI	0	0	Failures(0) Advisories(0)
01-Mar-06	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
27	08-Jan-26	149853 MI	5 MI	0
26	08-Jan-26	149848 MI	6830 MI	385
25	19-Dec-24	143018 MI	6 MI	0
24	19-Dec-24	143012 MI	47 MI	23
23	26-Nov-24	142965 MI	5033 MI	320
Keeper	03-Feb-24			
22	11-Jan-24	137932 MI	10037 MI	367

21	09-Jan-23	127895 MI	6457 MI	391
Keeper	26-Mar-22			
Keeper	31-Jan-22			
20	14-Dec-21	121438 MI	1 MI	5
19	09-Dec-21	121437 MI	4817 MI	351
18	23-Dec-20	116620 MI	8378 MI	372
17	17-Dec-19	108242 MI	13794 MI	355
16	27-Dec-18	94448 MI	1 MI	0
15	27-Dec-18	94447 MI	7324 MI	364
Keeper	18-Sep-18			
14	28-Dec-17	87123 MI	0	0
13	28-Dec-17	87123 MI	13120 MI	537
12	09-Jul-16	74003 MI	0	0
11	09-Jul-16	74003 MI	8142 MI	378
10	27-Jun-15	65861 MI	0	0
9	27-Jun-15	65861 MI	11289 MI	541
8	02-Jan-14	54572 MI	0	577
7	02-Jan-14	54572 MI	9066 MI	0
6	04-Jun-12	45506 MI	477 MI	143
5	13-Jan-12	45029 MI	45029 MI	1
4	12-Jan-12	0	-39520 MI	363
3	14-Jan-11	39520 MI	5591 MI	343

2	05-Feb-10	33929 MI	6176 MI	364
1	06-Feb-09	27753 MI		0
Keeper	01-Mar-06			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Mileage Reverse

A discrepancy in mileage has been detected in the MOT history.

Vehicle Information

Vehicle Registration Mark	LN06XAR	Make & Model	TOYOTA YARIS T SPIRIT S-A
Make	TOYOTA	Model	YARIS T SPIRIT S-A
Engine Capacity	1296	Year of Manufacture	2006
Fuel Type	PETROL	Date First Registered	01-Mar-06
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	01-Mar-06
Colour	SILVER	Year-Month 1st Registered	2006-03
CO2 Emissions	136 g/km	Transmission	AUTO 4 GEARS
Gear Count	4	Transmission Type	Semi Auto
Engine Number	2SZD577705	Transmission Code	S
Gross Weight	1480	Door Plan Code	14
Maximum Permissible Mass	1480	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	04-Feb-26 05:19:33		

General Information

Make	Toyota	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	80
Valve Gear	DOHC	Location	FRONT
Description	2SZ-FE/E4	Bore	72
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	XP90	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	9	Keeper Data Count	4
Keeper 9 (Current Keeper)			03-Feb-24
Keeper 8			26-Mar-22
Keeper 7			31-Jan-22
Keeper 6			18-Sep-18
Keeper 1 (First Keeper)			01-Mar-06

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	15-Nov-25 26-Mar-22 31-Jan-22 20-Sep-18
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	110	Per Month	18.33
Standard Twelve Month	200	Per Month	16.67
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	136 g/km	VED Band	E
VED CO2 Band	E		

Performance Information

Torque FtLb	89.3	Power Rpm	6000
Torque Rpm	4200	Power Bhp	85.8
Torque Nm	121	Power Kw	64
CO2	136	NoiseLevel	***
Max Speed Mph	106	Particles	***
Max Speed Kph	171	Data Version Number	***
Acceleration Zero To 60Mph	13.1	Acceleration Mph	13.1
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	48.7	Combined Lkm	5.8
ExtraUrban Mpg	53.3	ExtraUrban Lkm	5.3
UrbanCold Mpg	42.2	UrbanCold Lkm	6.7

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	SILVER	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	SILVER		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1480	Height	1530
Gross Combined Weight	1480	Width	1695
Kerb Weight	1010	Car Length	3750
Unladen Weight	1010	Wheel Base	2460
Fuel Tank Capacity	42	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Toyota	DVLA Make	TOYOTA
SMMT Range	Yaris	DVLA Model	YARIS T SPIRIT S-A
SMMT Trim	Yaris T Spirit Semi-Auto	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Toyota	Range	Yaris
Model Variant	Yaris T Spirit Semi-Auto	Fuel Type	Petrol
Nominal Engine Capacity	1.3	Transmission	Semi Automatic
Engine Capacity	1296	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	4
DriveType	4x2	SysSetup Date	22-Dec-05
Country Of Origin	France	Visibility Date	22-Dec-05
Series	XP90	Terminate Date	17-Mar-09
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
08-Jan-26	 PASS	149853 MI	802533380554

Advisories

- ADVISORY** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- ADVISORY** Nearside Front Steering linkage ball joint has slight play inner rack (2.1.3 (b) (i))
- ADVISORY** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Exhaust has a minor leak of exhaust gases rear box flange (6.1.2 (a))

08-Jan-26	 FAIL	149848 MI	173527127100
-----------	---	-----------	--------------

Advisories

- ADVISORY** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- ADVISORY** Nearside Front Steering linkage ball joint has slight play inner rack (2.1.3 (b) (i))
- ADVISORY** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Exhaust has a minor leak of exhaust gases rear box flange (6.1.2 (a))

Failures

- MAJOR** Offside Direction indicator not working side repeater (4.4.1 (a) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Offside Front Steering linkage ball joint has excessive play inner rack (2.1.3 (b) (i))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

19-Dec-24	 PASS	143018 MI	670303973493
-----------	---	-----------	--------------

Advisories

- ADVISORY** Offside repeater cover missing
- ADVISORY** Play in steering rack inner joint(s)
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- ADVISORY** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** rear chassis has surface corrosion

19-Dec-24



FAIL

143012 MI

710206392653

Advisories

- ADVISORY** Offside repeater cover missing
- ADVISORY** Play in steering rack inner joint(s)
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- ADVISORY** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** rear chassis has surface corrosion

Failures

- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

26-Nov-24



FAIL

142965 MI

416008660494

Advisories

- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- ADVISORY** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** Offside repeater cover missing
- ADVISORY** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- ADVISORY** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** rear chassis has surface corrosion
- ADVISORY** Play in steering rack inner joint(s)
- MINOR** Nearside Windscreen wiper blade defective (3.4 (b) (i))

Failures

- DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Headlamp aim unable to be tested (4.1.2 (b))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Nearside Headlamp insecure (4.1.1 (c))
- MAJOR** Offside Headlamp insecure (4.1.1 (c))
- MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- MAJOR** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Front Brake pipe excessively corroded to rear at rear (1.1.11 (c))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- MAJOR** Offside Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

11-Jan-24



PASS

137932 MI

651817536231

Advisories

- ADVISORY** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))
- ADVISORY** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- ADVISORY** Nearside Front Lower Suspension rod ball joint has slight play (5.3.4 (a) (i))
- ADVISORY** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MINOR** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MINOR** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

09-Jan-23



PASS

127895 MI

896000303010

Advisories

- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- ADVISORY** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

14-Dec-21



PASS

121438 MI

415527904241

Advisories

- ADVISORY** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MINOR** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

09-Dec-21



FAIL

121437 MI

945612399095

Advisories

- ADVISORY** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MINOR** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Failures

- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Rear Seat belt buckle missing (7.1.2 (d))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

23-Dec-20



PASS

116620 MI

714708646706

17-Dec-19



PASS

108242 MI

874013986143

27-Dec-18



PASS

94448 MI

169350785484

Advisories

MINOR Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

27-Dec-18



FAIL

94447 MI

857867666517

Advisories

MINOR Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Failures

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Rear Seat belt buckle missing (7.1.2 (d))

MAJOR Offside Rear Seat belt buckle missing (7.1.2 (d))

28-Dec-17



PASS

87123 MI

654542406736

Advisories

ADVISORY Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

ADVISORY Front Brake pad(s) wearing thin (3.5.1g)

28-Dec-17



FAIL

87123 MI

587015722856

Advisories

ADVISORY Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)

ADVISORY Front Brake pad(s) wearing thin (3.5.1g)

Failures

PRS Nearside Rear Stop lamp not working (1.2.1b)

PRS Offside Front Headlamp not working on main beam (1.7.5a)

09-Jul-16



PASS

74003 MI

634514041907

Advisories

ADVISORY Nearside Front Obligatory mirror obscured but not seriously affecting the rear view (8.1.2a)

09-Jul-16



FAIL

74003 MI

713650159706

Advisories

ADVISORY Nearside Front Obligatory mirror obscured but not seriously affecting the rear view (8.1.2a)

Failures

PRS Registration plate lamp not working (1.1.C.1d)

27-Jun-15

**PASS**

65861 MI

499228775188

27-Jun-15

**FAIL**

65861 MI

326038075158

Failures

- Failed** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Failed** Front registration plate character(s) likely to be misread (6.3.4b)
- Failed** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Failed** Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Failed** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

02-Jan-14

**FAIL**

54572 MI

765622904025

Advisories

- ADVISORY** Front Brake pad(s) wearing thin (3.5.1g)
- ADVISORY** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- USER ENTERED** Gearbox mounting defective

Failures

- PRS** Offside Headlamp not working on main beam (1.7.5a)

02-Jan-14

**PASS**

54572 MI

726492804082

Advisories

- ADVISORY** Front Brake pad(s) wearing thin (3.5.1g)
- ADVISORY** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- USER ENTERED** Gearbox mounting defective

04-Jun-12

**PASS**

45506 MI

336326352188

Advisories

- ADVISORY** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

13-Jan-12

**PASS**

45029 MI

727913612079

12-Jan-12

**FAIL**

206532912059

Failures

- Failed** Nearside Rear Stop lamp not working (1.2.1b)
- Failed** Parking brake lever has no reserve travel (3.1.6b)
- Failed** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

14-Jan-11



PASS

39520 MI

386144011053

05-Feb-10



PASS

33929 MI

643046430002

06-Feb-09



PASS

27753 MI

234617139033

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.