

YOUR VEHICLE DATA



| | | | | | | | | | |
|----------|---|----------|---|----------|---|--------------|---|---------------|------------------------|
| Scrapped | ✓ | Exported | ✓ | Imported | ✓ | Plate Change | ! | Colour Change | ✓ |
| Mileage | ✓ | Taxi | ✓ | Recall | ✗ | Keepers | 5 | Keeper | 30-Dec-16 20-Apr-06 |

| | |
|---|---|
| <div>✓</div> Taxed Tax due: 01-Jan-27 | <div>✓</div> MOT Status Expires 04-Sep-26 |
| Vehicle Make | HONDA |
| Fuel Type | PETROL |
| Cylinder Capacity | 1339 |
| Vehicle Colour | RED |
| Euro Stats | *** |
| Co2 Emissions | 139 |
| Real Driving Emissions (RDE) | *** |
| Wheelplan | 2 AXLE RIGID BODY |
| Ulez Compliance | Check TFL |
| Year Of Manufacture | 2006 |
| Date Of First Registration | Apr-06 |
| Date Of Last V5C (logbook) Issued | 08-Jun-17 |
| Export Marker | *** |
| Vehicle Type Approval | M1 |
| Revenue Weight | *** |
| Vehicle Status | Taxed |
| MOT Status | Valid |

Mot & Mileage Summary

| | | | |
|----------------------------|-----------|------------------------------|-----------------|
| Total Test | 24 | ! Pass Rate | 70% |
| ✓ Test Passed | 17 | ! Pass Rate With Advisory | 52% |
| ! Passed With Advisory | 9 | ✓ Pass Rate Without Advisory | 48% |
| ! Total Items Advised | 18 | ✓ Mileage Issues | No |
| ! Advisory Average/Per MOT | 1.06 | Last MOT Mileage | 116896 MI |
| ✗ Test Failed | 7 | Est Current Mileage | 117891 MI |
| ✗ Total Items Failed | 13 | Average Mileage | 6152 Miles/Year |
| ✓ Taxi/Rent a Car Use | Might not | icon Mileage Status | Average |



MOT Test List

| Date | Result | Mileage | Difference | Days | Reason |
|-----------|--|-----------|------------|------|------------------------------|
| 23-Aug-25 |  PASS | 116896 MI | 0 | 0 | Failures(0) Advisories(1) |
| 23-Aug-25 |  FAIL | 116896 MI | 1347 | 357 | Failures(0) Advisories(1) |
| 31-Aug-24 |  PASS | 115549 MI | 0 | 0 | Failures(0) Advisories(0) |
| 31-Aug-24 |  FAIL | 115549 MI | 1411 | 374 | Failures(0) Advisories(0) |
| 23-Aug-23 |  PASS | 114138 MI | 0 | 0 | Failures(0) Advisories(0) |
| 23-Aug-23 |  FAIL | 114138 MI | 1358 | 356 | Failures(0) Advisories(0) |
| 01-Sep-22 |  PASS | 112780 MI | 0 | 0 | Failures(0) Advisories(1) |
| 01-Sep-22 |  FAIL | 112780 MI | 1772 | 369 | Failures(0) Advisories(1) |
| 28-Aug-21 |  PASS | 111008 MI | 1765 | 357 | Failures(0) Advisories(0) |
| 05-Sep-20 |  PASS | 109243 MI | 0 | 0 | Failures(0) Advisories(0) |
| 05-Sep-20 |  FAIL | 109243 MI | 1979 | 477 | Failures(0) Advisories(0) |
| 17-May-19 |  PASS | 107264 MI | 1882 | 351 | Failures(0) Advisories(2) |
| 31-May-18 |  PASS | 105382 MI | 2819 | 390 | Failures(0) Advisories(0) |
| 06-May-17 |  PASS | 102563 MI | 3380 | 339 | Failures(0) Advisories(0) |

| | | | | | |
|-----------|--------------|---|-------|-----|------------------------------|
| 30-Dec-16 | ! KEEPER 5 | | | | |
| 01-Jun-16 | ✓ PASS | 99183 MI | 0 | 1 | Failures(0) Advisories(3) |
| 31-May-16 | ✗ FAIL | 99183 MI | 14773 | 371 | Failures(2) Advisories(3) |
| 26-May-15 | ✓ PASS | 84410 MI | 0 | 0 | Failures(0) Advisories(1) |
| 26-May-15 | ✗ FAIL | 84410 MI | 9159 | 364 | Failures(3) Advisories(1) |
| 24-Jul-14 | ! PLATE | <div> <div>GB</div> <div>K2TMY</div> </div> → <div> <div>GB</div> <div>DE06MGO</div> </div> | | | |
| 27-May-14 | ✓ PASS | 75251 MI | 7687 | 300 | Failures(0) Advisories(2) |
| 31-Jul-13 | ✓ PASS | 67564 MI | 16544 | 418 | Failures(0) Advisories(3) |
| 08-Jun-12 | ✓ PASS | 51020 MI | 19587 | 368 | Failures(0) Advisories(1) |
| 06-Jun-11 | ✓ PASS | 31433 MI | 11958 | 364 | Failures(0) Advisories(4) |
| 07-Jun-10 | ✓ PASS | 19475 MI | 5450 | 380 | Failures(0) Advisories(0) |
| 23-May-09 | ✓ PASS | 14025 MI | 0 | 0 | Failures(0) Advisories(0) |
| 20-Apr-06 | ! KEEPER 1 | | | | |

Mileage History

| S No. | Date | Mileage | Difference | Days |
|-------|-----------|-----------|------------|------|
| 25 | 23-Aug-25 | 116896 MI | 0 | 0 |
| 24 | 23-Aug-25 | 116896 MI | 1347 MI | 357 |

| | | | | |
|-----------------|-----------|---|----------|-----|
| 23 | 31-Aug-24 | 115549 MI | 0 | 0 |
| 22 | 31-Aug-24 | 115549 MI | 1411 MI | 374 |
| 21 | 23-Aug-23 | 114138 MI | 0 | 0 |
| 20 | 23-Aug-23 | 114138 MI | 1358 MI | 356 |
| 19 | 01-Sep-22 | 112780 MI | 0 | 0 |
| 18 | 01-Sep-22 | 112780 MI | 1772 MI | 369 |
| 17 | 28-Aug-21 | 111008 MI | 1765 MI | 357 |
| 16 | 05-Sep-20 | 109243 MI | 0 | 0 |
| 15 | 05-Sep-20 | 109243 MI | 1979 MI | 477 |
| 14 | 17-May-19 | 107264 MI | 1882 MI | 351 |
| 13 | 31-May-18 | 105382 MI | 2819 MI | 390 |
| 12 | 06-May-17 | 102563 MI | 3380 MI | 339 |
| Keeper30-Dec-16 | | | | |
| 11 | 01-Jun-16 | 99183 MI | 0 | 1 |
| 10 | 31-May-16 | 99183 MI | 14773 MI | 371 |
| 9 | 26-May-15 | 84410 MI | 0 | 0 |
| 8 | 26-May-15 | 84410 MI | 9159 MI | 364 |
| 7 | 24-Jul-14 |  K2TMY →  DE06MGO | | |
| 6 | 27-May-14 | 75251 MI | 7687 MI | 300 |
| 5 | 31-Jul-13 | 67564 MI | 16544 MI | 418 |
| 4 | 08-Jun-12 | 51020 MI | 19587 MI | 368 |
| 3 | 06-Jun-11 | 31433 MI | 11958 MI | 364 |

| | | | | |
|-----------------|-----------|----------|---------|-----|
| 2 | 07-Jun-10 | 19475 MI | 5450 MI | 380 |
| 1 | 23-May-09 | 14025 MI | | 0 |
| Keeper20-Apr-06 | | | | |



Km / Mileage



Mileage Reverse



Taxi MOT gaps

| Vehicle Information | | | |
|--|--------------------|--------------------------------|----------------------|
| Vehicle Registration Mark | DE06MGO | Make & Model | HONDA JAZZ SE CVT |
| Make | HONDA | Model | JAZZ SE CVT |
| Engine Capacity | 1339 | Year of Manufacture | 2006 |
| Fuel | *** | Date First Registered | 20-Apr-06 |
| Premium Vehicle Year 2 to 6 - Twelve Month | *** | Date of 1st Registration in UK | 20-Apr-06 |
| Colour | RED | Year-Month 1st Registered | 2006-04 |
| CO2 Emissions | 139 | Transmission | AUTO VARIABLE 1 GEAR |
| Gear Count | 1 | Transmission Type | Automatic |
| Engine Number | L13A15011606 | Transmission Code | A |
| Gross Weight | 1510 | Door Plan Code | *** |
| Maximum Permissible Mass | *** | MVRIS Model Code | *** |
| Seating Capacity | 5 | MVRIS Make Code | *** |
| Wheel Plan | 2 AXLE RIGID BODY | Used Before First Registration | No |
| Vehicle Class | Car | Vin Confirmation Flag | *** |
| Date Of Last Update | 09-May-24 01:23:11 | | |

| General Information | | | |
|------------------------|---------------------|------------------------|-------|
| Make | Honda Cars | Euro Status | 4 |
| Aspiration | Naturally Aspirated | Fuel System | |
| Number Of Cylinders | 4 | Fuel Delivery | |
| Valves Per Cylinder | 2 | Fuel Catalyst | C |
| Cylinder Arrangement | I | Stroke | 80 |
| Valve Gear | SOHC | Location | FRONT |
| Description | L13A1 | Bore | 73 |
| Power Delivery | Normal | Type Approval Category | M1 |
| Driving Axle | FWD | Primary Fuel Flag | *** |
| Series Description | GD/GE | Driver Position | R |
| Data Version Number | *** | Is Limited Edition | No |
| EV Battery Capacity | *** | EV Battery Charge Port | *** |
| EV Battery Charge Time | *** | EV Battery Type | *** |

| Previous Keepers | | | |
|---------------------------|---|-------------------|-----------|
| Total Keepers | 5 | Keeper Data Count | 1 |
| Keeper 5 (Current Keeper) | | | 30-Dec-16 |
| Keeper 1 (First Keeper) | | | 20-Apr-06 |

| V5C Certificate issue details | | | |
|-------------------------------|---|-------------------|-----------|
| V5C Certificate Count | 1 | Certificate Dates | 08-Jun-17 |

| Vehicle Tax & CO2 Emissions | | | |
|--|-----|-----------|-------|
| Standard Six Month | 110 | Per Month | 18.33 |
| Standard Twelve Month | 200 | Per Month | 16.67 |
| First Year Six Month | --- | Per Month | --- |
| First Year Twelve Month | 0 | Per Month | 0 |
| Premium Vehicle Year 2 to 6 - Six Month | --- | Per Month | --- |
| Premium Vehicle Year 2 to 6 - Twelve Month | --- | Per Month | --- |
| VED CO? Emissions | 139 | VED Band | E |
| VED CO? Band | E | | |

Performance Information

| | | | |
|-----------------------------|------|---------------------|------|
| Torque FtLb | 87.8 | Power Rpm | 5700 |
| Torque Rpm | 2800 | Power Bhp | 81.8 |
| Torque Nm | 119 | Power Kw | 61 |
| Co? | *** | NoiseLevel | *** |
| Max Speed Mph | 99 | Particles | *** |
| Max Speed Kph | 160 | Data Version Number | *** |
| Acceleration Zero To 60Mph | 14.5 | Acceleration Mph | 14.5 |
| Acceleration Zero To 100Kph | *** | Acceleration Kph | *** |

Consumption

| | | | |
|----------------|------|----------------|-----|
| Combined Mpg | 47.9 | Combined Lkm | 5.9 |
| ExtraUrban Mpg | 55.4 | ExtraUrban Lkm | 5.1 |
| UrbanCold Mpg | 39.2 | UrbanCold Lkm | 7.2 |

! Plate Change History

| | | | |
|--------------------|-----------|---|---|
| Plate Change Count | 1 | | |
| 1 | 24-Jul-14 |  K2TMY | →  DE06MGO |

✓ Import/Export

| | | | |
|----------|----|-------------|-----|
| Exported | No | Export Date | *** |
| Imported | No | | |

✓ Scrap Destructions

| | | | |
|-----------------------------------|----|------------------------|-----|
| Scrapped | No | Date of Scrapped | *** |
| Certificate of Destruction Issued | No | Vehicle ID Check Count | 0 |

✓ Colour Changes

| | | | |
|-----------------|-----|----------------------------|-----|
| Current Colour | RED | Number Of Previous Colours | 0 |
| Last Colour | *** | Date Of Last Colour Change | *** |
| Original Colour | RED | | |

✔ Previous VRM

Previous Northern Ireland

*** Previous UK VRM

K2TMY

Dimensions

| | | | |
|-----------------------|-------|---------------------|------|
| Gross Vehicle Weight | 1510 | Height | 1525 |
| Gross Combined Weight | 1510 | Width | 1675 |
| Kerb Weight | 1066 | Car Length | 3845 |
| Unladen Weight | 1066 | Wheel Base | 2450 |
| Fuel Tank Capacity | 42 | Pay Load Weight | *** |
| Number Of Doors | 5 | Gross Train Weight | *** |
| Number Of Seats | 5 | Payload Volume | *** |
| Rigid Artic | RIGID | Load Length | *** |
| Number Of Axles | 2 | Data Version Number | *** |
| Body Shape | NA | | |

Safety

| | | | |
|------------|-----|-------|-----|
| Adult | *** | Child | *** |
| Pedestrian | *** | | |

Classification Details

| | | | |
|----------------------|-------------|----------------------|-------------|
| SMMT Make | Honda | DVLA Make | HONDA |
| SMMT Range | Jazz | DVLA Model | JAZZ SE CVT |
| SMMT Trim | Jazz SE CVT | Is Electric Vehicle | |
| SMMT Mvris MakeCode | *** | Is GB General Format | *** |
| SMMT Mvris ModelCode | *** | Is NI General Format | *** |

Smmt Details

| | | | |
|-------------------------|-------------|---------------------|-----------|
| Marque | Honda | Range | Jazz |
| Model Variant | Jazz SE CVT | Fuel Type | Petrol |
| Nominal Engine Capacity | 1.3 | Transmission | CVT |
| Engine Capacity | 1339 | Number Of Doors | 5 |
| Body Style | Hatchback | Number Of Gears | 1 |
| DriveType | 4x2 | SysSetup Date | 02-Aug-06 |
| Country Of Origin | Japan | Visibility Date | 02-Aug-06 |
| Series | GD/GE | TerminateDate | 07-Jan-19 |
| Marque Code | *** | Cab Type | NA |
| Market Sector Code | AA | Data Version Number | *** |
| Model Code | *** | | |

MOT Test List

| Date | Result | Mileage | Test Number |
|------|--------|---------|-------------|
|------|--------|---------|-------------|

23-Aug-25



PASS

116896 MI

673131193101

Advisories

ADVISORY nearside front wing dented with no sharp egde

23-Aug-25



FAIL

116896 MI

338083358883

Advisories

ADVISORY nearside front wing dented with no sharp egde

Failures

PRS Windscreen washer provides insufficient washer liquid (3.5 (a))

31-Aug-24



PASS

115549 MI

481739497035

31-Aug-24



FAIL

115549 MI

346002424443

Failures

PRS Nearside Front Body insecure to the extent that stability is seriously impaired wing (6.2.2 (a) (ii))

PRS Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))

PRS Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

23-Aug-23



PASS

114138 MI

676590268209

23-Aug-23



FAIL

114138 MI

194732274386

Failures

PRS Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

01-Sep-22



PASS

112780 MI

456697650925

Advisories

ADVISORY Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

01-Sep-22



FAIL

112780 MI

166313639235

Advisories

ADVISORY Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Failures

PRS Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

28-Aug-21



PASS

111008 MI

139507265037

05-Sep-20



PASS

109243 MI

956718037046

05-Sep-20



FAIL

109243 MI

310783213596

Failures

PRS Nearside Headlamp aim too high (4.1.2 (a))

PRS Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

17-May-19



PASS

107264 MI

556240930684

Advisories

ADVISORY Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

31-May-18



PASS

105382 MI

919445235769

06-May-17



PASS

102563 MI

760625757937

01-Jun-16



PASS

99183 MI

946125803581

Advisories

- ADVISORY** Nearside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

31-May-16



FAIL

99183 MI

154054005800

Advisories

- ADVISORY** Nearside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Failures

- Failed** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Failed** Exhaust has a major leak of exhaust gases centre box (7.1.2)

26-May-15



PASS

84410 MI

707446445146

Advisories

- ADVISORY** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

26-May-15



FAIL

84410 MI

635926045192

Advisories

- ADVISORY** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Failures

- Failed** Nearside Rear Stop lamp not working (1.2.1b)
- Failed** Centre Rear Stop lamp not working (1.2.1b)
- Failed** Offside Front Headlamp aim too low (1.8)

27-May-14



PASS

75251 MI

415987644147

Advisories

- ADVISORY** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- ADVISORY** Rear Tyre worn close to the legal limit (4.1.E.1)

31-Jul-13

**PASS**

67564 MI

525872313219

Advisories**ADVISORY** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**USER ENTERED** anti-slip provision slightly worn**USER ENTERED** Offside Rear bumper slightly damaged

08-Jun-12

**PASS**

51020 MI

945380762172

Advisories**ADVISORY** Rear Brake pad(s) wearing thin (3.5.1g)

06-Jun-11

**PASS**

31433 MI

226677451152

Advisories**ADVISORY** Steering system has slight free play detected at steering wheel (2.2.A.1b)**ADVISORY** Nearside Front Brake pad(s) wearing thin (3.5.1g)**ADVISORY** Offside Front Brake pad(s) wearing thin (3.5.1g)**USER ENTERED** front and rear brake disc slightly worn.

07-Jun-10

**PASS**

19475 MI

971468150108

23-May-09

**PASS**

14025 MI

123773749135

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.