

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✓	Keepers	4	Keeper	13-Sep-22 12-Aug-15 10-Oct-06

**Taxed**

Tax due: 01-Sep-26

Vehicle Make	KIA
Fuel Type	PETROL
Cylinder Capacity	1086
Vehicle Colour	RED
Euro Stats	***
Co2 Emissions	124
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

**MOT Status**

Expires 30-Sep-26

Year Of Manufacture	2006
Date Of First Registration	Oct-06
Date Of Last V5C (logbook) Issued	13-Sep-22
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	***
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	20	✓ Pass Rate	85%
✓ Test Passed	17	! Pass Rate With Advisory	52%
! Passed With Advisory	9	✓ Pass Rate Without Advisory	48%
! Total Items Advised	16	✓ Mileage Issues	No
! Advisory Average/Per MOT	0.94	Last MOT Mileage	94898 MI
✗ Test Failed	3	Est Current Mileage	98933 MI
✗ Total Items Failed	8	Average Mileage	4994 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✓ Mileage Status	Below Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
26-Sep-25	✓ PASS	94898 MI	6666	360	Failures(0) Advisories(3)
01-Oct-24	✓ PASS	88232 MI	6209	391	Failures(0) Advisories(3)
06-Sep-23	✓ PASS	82023 MI	7647	365	Failures(0) Advisories(0)
13-Sep-22	! KEEPER 4				
06-Sep-22	✓ PASS	74376 MI	0	1	Failures(0) Advisories(2)
05-Sep-22	✗ FAIL	74376 MI	7286	398	Failures(3) Advisories(2)
03-Aug-21	✓ PASS	67090 MI	2118	365	Failures(0) Advisories(2)

03-Aug-20	 PASS	64972 MI	1400	369	Failures(0) Advisories(0)
31-Jul-19	 PASS	63572 MI	11	2	Failures(0) Advisories(1)
29-Jul-19	 FAIL	63561 MI	2139	369	Failures(3) Advisories(4)
25-Jul-18	 PASS	61422 MI	11	1	Failures(0) Advisories(0)
24-Jul-18	 FAIL	61411 MI	1923	356	Failures(2) Advisories(3)
02-Aug-17	 PASS	59488 MI	2253	365	Failures(0) Advisories(2)
02-Aug-16	 PASS	57235 MI	2579	358	Failures(0) Advisories(1)
12-Aug-15	 KEEPER 3				
10-Aug-15	 PASS	54656 MI	4411	328	Failures(0) Advisories(1)
16-Sep-14	 PASS	50245 MI	2788	368	Failures(0) Advisories(0)
13-Sep-13	 PASS	47457 MI	6927	359	Failures(0) Advisories(1)
19-Sep-12	 PASS	40530 MI	7014	366	Failures(0) Advisories(0)
19-Sep-11	 PASS	33516 MI	6486	350	Failures(0) Advisories(0)
04-Oct-10	 PASS	27030 MI	8665	362	Failures(0) Advisories(0)
07-Oct-09	 PASS	18365 MI	0	0	Failures(0) Advisories(0)
10-Oct-06	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
20	26-Sep-25	94898 MI	6666 MI	360
19	01-Oct-24	88232 MI	6209 MI	391
18	06-Sep-23	82023 MI	7647 MI	365
Keeper	13-Sep-22			
17	06-Sep-22	74376 MI	0	1
16	05-Sep-22	74376 MI	7286 MI	398
15	03-Aug-21	67090 MI	2118 MI	365
14	03-Aug-20	64972 MI	1400 MI	369
13	31-Jul-19	63572 MI	11 MI	2
12	29-Jul-19	63561 MI	2139 MI	369
11	25-Jul-18	61422 MI	11 MI	1
10	24-Jul-18	61411 MI	1923 MI	356
9	02-Aug-17	59488 MI	2253 MI	365
8	02-Aug-16	57235 MI	2579 MI	358
Keeper	12-Aug-15			
7	10-Aug-15	54656 MI	4411 MI	328
6	16-Sep-14	50245 MI	2788 MI	368
5	13-Sep-13	47457 MI	6927 MI	359
4	19-Sep-12	40530 MI	7014 MI	366
3	19-Sep-11	33516 MI	6486 MI	350

2	04-Oct-10	27030 MI	8665 MI	362
1	07-Oct-09	18365 MI		0
Keeper	10-Oct-06			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information			
Vehicle Registration Mark	LC56UNR	Make & Model	KIA PICANTO LX
Make	KIA	Model	PICANTO LX
Engine Capacity	1086	Year of Manufacture	2006
Fuel	***	Date First Registered	10-Oct-06
Premium Vehicle Year 2 to 6 - Twelve Month	***	Date of 1st Registration in UK	10-Oct-06
Colour	RED	Year-Month 1st Registered	2006-10
CO2 Emissions	124	Transmission	MANUAL 5 GEARS
Gear Count	5	Transmission Type	Manual
Engine Number	G4HG6M84472	Transmission Code	M
Gross Weight	1350	Door Plan Code	***
Maximum Permissible Mass	***	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	12-May-24 13:06:05		

General Information			
Make	Hyundai	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	3	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	77
Valve Gear	SOHC	Location	FRONT
Description	G4HG	Bore	67
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	***
Series Description	SA	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers			
Total Keepers	4	Keeper Data Count	2
Keeper 4 (Current Keeper)			13-Sep-22
Keeper 3			12-Aug-15
Keeper 1 (First Keeper)			10-Oct-06

V5C Certificate issue details			
V5C Certificate Count	2	Certificate Dates	13-Sep-22 24-Aug-15

Vehicle Tax & CO2 Emissions			
Standard Six Month	93.5	Per Month	15.58
Standard Twelve Month	170	Per Month	14.17
First Year Six Month	---	Per Month	---
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	---	Per Month	---
Premium Vehicle Year 2 to 6 - Twelve Month	---	Per Month	---
VED CO? Emissions	124	VED Band	D
VED CO? Band	D		

Performance Information

Torque FtLb	71.7	Power Rpm	5500
Torque Rpm	2800	Power Bhp	64.1
Torque Nm	97.2	Power Kw	47.8
Co?	***	NoiseLevel	***
Max Speed Mph	96	Particles	***
Max Speed Kph	154	Data Version Number	***
Acceleration Zero To 60Mph	15.1	Acceleration Mph	15.1
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	57.7	Combined Lkm	4.9
ExtraUrban Mpg	65.7	ExtraUrban Lkm	4.3
UrbanCold Mpg	46.3	UrbanCold Lkm	6.1

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	RED	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	RED		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions			
Gross Vehicle Weight	1350	Height	1480
Gross Combined Weight	1350	Width	1595
Kerb Weight	966	Car Length	3495
Unladen Weight	966	Wheel Base	2370
Fuel Tank Capacity	35	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety			
Adult	***	Child	***
Pedestrian	***		

Classification Details			
SMMT Make	Kia	DVLA Make	KIA
SMMT Range	Picanto	DVLA Model	PICANTO LX
SMMT Trim	Picanto LX	Is Electric Vehicle	
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details			
Marque	Kia	Range	Picanto
Model Variant	Picanto LX	Fuel Type	Petrol
Nominal Engine Capacity	1.1	Transmission	Manual
Engine Capacity	1086	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	5
DriveType	4x2	SysSetup Date	01-Jan-70
Country Of Origin	South Korea	Visibility Date	01-Jan-70
Series	SA	TerminateDate	01-Jan-70
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

26-Sep-25



PASS

94898 MI

280162388688

Advisories

- ADVISORY** Offside Front Service brake binding but not excessively (1.2.1 (f))
- ADVISORY** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Nearside front wheel and tyre slightly distorted.

01-Oct-24



PASS

88232 MI

900213237751

Advisories

- ADVISORY** Offside Front Service brake binding but not excessively (1.2.1 (f))
- ADVISORY** Offside front inner brake pad wearing low.
- ADVISORY** Both front brake disc inner faces slightly worn with 'lips' on edges.

06-Sep-23



PASS

82023 MI

137153884912

06-Sep-22



PASS

74376 MI

526161527186

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- MINOR** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

05-Sep-22



FAIL

74376 MI

803715332497

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- MINOR** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Failures

- DANGEROUS** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))

03-Aug-21



PASS

67090 MI

372559911761

Advisories

ADVISORY Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

ADVISORY Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

03-Aug-20



PASS

64972 MI

482125545095

31-Jul-19



PASS

63572 MI

679582846823

Advisories

ADVISORY Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

29-Jul-19



FAIL

63561 MI

251444329855

Advisories

ADVISORY Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

ADVISORY Nearside Front Service brake binding but not excessively (1.2.1 (f))

ADVISORY Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MINOR Tyre obviously under inflated ALL TYRES (5.2.3 (l))

Failures

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Offside Front Service brake excessively binding (1.2.1 (f))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

25-Jul-18



PASS

61422 MI

593905480287

24-Jul-18



FAIL

61411 MI

111786426664

Advisories

ADVISORY Offside Front Service brake binding but not excessively (1.2.1 (f))

ADVISORY Nearside Front Service brake binding but not excessively (1.2.1 (f))

ADVISORY Bonnet safety catch stiff

Failures

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

02-Aug-17



PASS

59488 MI

811946774986

Advisories

ADVISORY Oil leak

ADVISORY Slight binding offside rear brake

02-Aug-16



PASS

57235 MI

319594337958

Advisories

ADVISORY Oil leak

10-Aug-15



PASS

54656 MI

608312925288

Advisories

USER ENTERED n/s/r disc rusty inner face

16-Sep-14



PASS

50245 MI

375819254299

13-Sep-13



PASS

47457 MI

376276753284

Advisories

ADVISORY Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

19-Sep-12



PASS

40530 MI

106623762252

19-Sep-11



PASS

33516 MI

675832761265

04-Oct-10



PASS

27030 MI

303627170492

07-Oct-09



PASS

18365 MI

932470489253

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.