

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✓	Keepers	2	Keeper	10-Aug-11 11-Jun-08







✓ Taxed Tax due: 01-Jun-26	✓ MOT Status Expires 08-Jul-26
Vehicle Make VOLKSWAGEN	Year Of Manufacture 2008
Fuel Type DIESEL	Date Of First Registration Jun-08
Cylinder Capacity 1968	Date Of Last V5C (logbook) Issued 14-Oct-11
Vehicle Colour GREY	Export Marker ***
Euro Stats ***	Vehicle Type Approval M1
Co2 Emissions 177	Revenue Weight ***
Real Driving Emissions (RDE) ***	Vehicle Status Taxed
Wheelplan 2 AXLE RIGID BODY	MOT Status Valid
Ulez Compliance Check TFL	

Mot & Mileage Summary

Total Test 18	✓ Pass Rate 83%
✓ Test Passed 15	! Pass Rate With Advisory 33%
! Passed With Advisory 5	✓ Pass Rate Without Advisory 67%
! Total Items Advised 15	✓ Mileage Issues No
! Advisory Average/Per MOT 1.00	Last MOT Mileage 44685 MI
✗ Test Failed 3	Est Current Mileage 44703 MI
✗ Total Items Failed 11	Average Mileage 2628 Miles/Year
✓ Taxi/Rent a Car Use Might not	✓ Mileage Status Below Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
27-Jun-25	 PASS	44685 MI	21	356	Failures(0) Advisories(0)
06-Jul-24	 PASS	44664 MI	1156	367	Failures(0) Advisories(0)
05-Jul-23	 PASS	43508 MI	0	1	Failures(0) Advisories(0)
04-Jul-23	 FAIL	43508 MI	233	363	Failures(2) Advisories(0)
06-Jul-22	 PASS	43275 MI	490	380	Failures(0) Advisories(2)
21-Jun-21	 PASS	42785 MI	52	369	Failures(0) Advisories(0)
17-Jun-20	 PASS	42733 MI	415	357	Failures(0) Advisories(0)
26-Jun-19	 PASS	42318 MI	667	357	Failures(0) Advisories(0)
04-Jul-18	 PASS	41651 MI	897	372	Failures(0) Advisories(0)
27-Jun-17	 PASS	40754 MI	999	356	Failures(0) Advisories(0)
06-Jul-16	 PASS	39755 MI	604	372	Failures(0) Advisories(1)
30-Jun-15	 FAIL	39151 MI	1946	356	Failures(0) Advisories(3)
30-Jun-15	 PASS	39151 MI	0	0	Failures(0) Advisories(3)
09-Jul-14	 PASS	37205 MI	3944	379	Failures(0) Advisories(0)

25-Jun-13	 PASS	33261 MI	5191	361	Failures(0) Advisories(5)
29-Jun-12	 PASS	28070 MI	0	1	Failures(0) Advisories(4)
28-Jun-12	 FAIL	28070 MI	2756	356	Failures(1) Advisories(4)
10-Aug-11	 KEEPER 2				
08-Jul-11	 PASS	25314 MI	0	0	Failures(0) Advisories(0)
11-Jun-08	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
18	27-Jun-25	44685 MI	21 MI	356
17	06-Jul-24	44664 MI	1156 MI	367
16	05-Jul-23	43508 MI	0	1
15	04-Jul-23	43508 MI	233 MI	363
14	06-Jul-22	43275 MI	490 MI	380
13	21-Jun-21	42785 MI	52 MI	369
12	17-Jun-20	42733 MI	415 MI	357
11	26-Jun-19	42318 MI	667 MI	357
10	04-Jul-18	41651 MI	897 MI	372
9	27-Jun-17	40754 MI	999 MI	356
8	06-Jul-16	39755 MI	604 MI	372
7	30-Jun-15	39151 MI	0	356

6	30-Jun-15	39151 MI	1946 MI	0
5	09-Jul-14	37205 MI	3944 MI	379
4	25-Jun-13	33261 MI	5191 MI	361
3	29-Jun-12	28070 MI	0	1
2	28-Jun-12	28070 MI	2756 MI	356
Keeper		10-Aug-11		
1	08-Jul-11	25314 MI		0
Keeper		11-Jun-08		



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	LM08NKH	Make & Model	VOLKSWAGEN EOS TDI A
Make	VOLKSWAGEN	Model	EOS TDI A
Engine Capacity	1968	Year of Manufacture	2008
Fuel	***	Date First Registered	11-Jun-08
Premium Vehicle Year 2 to 6 - Twelve Month	***	Date of 1st Registration in UK	11-Jun-08
Colour	GREY	Year-Month 1st Registered	2008-06
CO2 Emissions	177	Transmission	AUTO 6 GEARS
Gear Count	6	Transmission Type	Automatic
Engine Number	BMM 229120	Transmission Code	A
Gross Weight	2040	Door Plan Code	***
Maximum Permissible Mass	***	MVRIS Model Code	***
Seating Capacity	4	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	12-May-24 19:49:58		

General Information			
Make	Volkswagen Cars	Euro Status	4
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	96
Valve Gear	DOHC	Location	FRONT
Description	1F7/140BHP	Bore	81
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	***
Series Description	1F7	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers			
Total Keepers	2	Keeper Data Count	1
Keeper 2 (Current Keeper)			10-Aug-11
Keeper 1 (First Keeper)			11-Jun-08

V5C Certificate issue details			
V5C Certificate Count	1	Certificate Dates	14-Oct-11

Vehicle Tax & CO2 Emissions			
Standard Six Month	198	Per Month	33
Standard Twelve Month	360	Per Month	30
First Year Six Month	---	Per Month	---
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	---	Per Month	---
Premium Vehicle Year 2 to 6 - Twelve Month	---	Per Month	---
VED CO? Emissions	177	VED Band	I
VED CO? Band	I		

Performance Information

Torque FtLb	236.2	Power Rpm	4000
Torque Rpm	1800	Power Bhp	140
Torque Nm	320	Power Kw	104.4
Co?	177	NoiseLevel	***
Max Speed Mph	126	Particles	***
Max Speed Kph	203	Data Version Number	***
Acceleration Zero To 60Mph	10.3	Acceleration Mph	10.3
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	42.2	Combined Lkm	6.7
ExtraUrban Mpg	51.4	ExtraUrban Lkm	5.5
UrbanCold Mpg	31.7	UrbanCold Lkm	8.9

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	GREY	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	GREY		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----










Dimensions			
Gross Vehicle Weight	2040	Height	1437
Gross Combined Weight	2040	Width	1791
Kerb Weight	1570	Car Length	4407
Unladen Weight	1570	Wheel Base	2578
Fuel Tank Capacity	55	Pay Load Weight	***
Number Of Doors	2	Gross Train Weight	***
Number Of Seats	4	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety			
Adult	***	Child	***
Pedestrian	***		

Classification Details			
SMMT Make	Volkswagen	DVLA Make	VOLKSWAGEN
SMMT Range	Eos	DVLA Model	EOS TDI A
SMMT Trim	Eos TDI Auto	Is Electric Vehicle	
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details			
Marque	Volkswagen	Range	Eos
Model Variant	Eos TDI Auto	Fuel Type	Diesel
Nominal Engine Capacity	2	Transmission	Automatic
Engine Capacity	1968	Number Of Doors	2
Body Style	Convertible	Number Of Gears	6
DriveType	4x2	SysSetup Date	01-Jan-70
Country Of Origin	Portugal	Visibility Date	01-Jan-70
Series	1F7	TerminateDate	06-Feb-09
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
27-Jun-25	 PASS	44685 MI	235116844291
06-Jul-24	 PASS	44664 MI	794710792826
05-Jul-23	 PASS	43508 MI	307924121643
04-Jul-23	 FAIL	43508 MI	859858774955
Failures			
DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))			
DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))			
06-Jul-22	 PASS	43275 MI	148572027031
Advisories			
ADVISORY Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))			
ADVISORY Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))			
21-Jun-21	 PASS	42785 MI	672650185549
17-Jun-20	 PASS	42733 MI	183657474636
26-Jun-19	 PASS	42318 MI	523280475039
04-Jul-18	 PASS	41651 MI	516877181729
27-Jun-17	 PASS	40754 MI	836404655960

06-Jul-16



PASS

39755 MI

960669987105

Advisories

ADVISORY brake servo rod under dash is damp not visably leaking

30-Jun-15



FAIL

39151 MI

265931885461

Advisories

ADVISORY Nearside Rear Brake pad(s) wearing thin (3.5.1g)

USER ENTERED o/s/f tyre outter sidewall perishing and poor condition.

USER ENTERED n/s/f tyre outter sidewall perishing and poor condition.

Failures

PRS Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

PRS Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

30-Jun-15



PASS

39151 MI

206891485153

Advisories

ADVISORY Nearside Rear Brake pad(s) wearing thin (3.5.1g)

USER ENTERED o/s/f tyre outter sidewall perishing and poor condition.

USER ENTERED n/s/f tyre outter sidewall perishing and poor condition.

09-Jul-14



PASS

37205 MI

277650494477

25-Jun-13



PASS

33261 MI

158236273104

Advisories

USER ENTERED The front wiper blades are smeering the windscreen.

USER ENTERED The offside rear seatbelt is twisted.

USER ENTERED The nearside front seatbelt is twisted.

USER ENTERED Under-trays fitted obscuring some underside components

USER ENTERED The nearside front outer CV boot is weeping grease slightly passed the larger end clip.

29-Jun-12



PASS

28070 MI

647161782183

Advisories

USER ENTERED The front wiper blades are smeering the windscreen.

USER ENTERED The vehicle judders when driving forwards or backwards.

USER ENTERED The nearside rear tyre tread is slightly feathered on the inner edge.

USER ENTERED The offside rear tyre tread is slightly feathered on the inner edge.

28-Jun-12



FAIL

28070 MI

285900082468

Advisories

- USER ENTERED** The front wiper blades are smearing the windscreen.
- USER ENTERED** The vehicle judders when driving forwards or backwards.
- USER ENTERED** The nearside rear tyre tread is slightly feathered on the inner edge.
- USER ENTERED** The offside rear tyre tread is slightly feathered on the inner edge.

Failures

- Failed** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

08-Jul-11



PASS

25314 MI

206739381456

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.