

YOUR VEHICLE DATA

Scrapped	Exported	Imported	Plate Change	Colour Change
✗	✓	✓	!	✗
Mileage	Taxi	Recall	Keepers	Keeper
✗	✗	✓	16	07-Aug-21 14-Oct-20 27-May-20 16-Feb-20 23-Oct-19 10-Feb-18 30-Sep-06

## Mot & Mileage Summary




Total Test	34	! Pass Rate	70%
✓ Test Passed	24	! Pass Rate With Advisory	29%
! Passed With Advisory	7	✓ Pass Rate Without Advisory	71%
! Total Items Advised	27	✗ Mileage Issues	Yes
! Advisory Average/Per MOT	1.13	Last MOT Mileage	152609 MI
✗ Test Failed	10	Est Current Mileage	243418 MI
✗ Total Items Failed	28	Average Mileage	10173 Miles/Year
✗ Taxi/Rent a Car Use	Might be	✗ Mileage Status	Above Average

## MOT Test List

Date	Result	Mileage	Difference	Days	Reason
18-Nov-21	✓ PASS	152609 MI	0	0	Failures(0) Advisories(8)
18-Nov-21	✗ FAIL	152609 MI	20987	364	Failures(2) Advisories(8)
07-Aug-21	! KEEPER 16				
19-Nov-20	✓ PASS	131622 MI	75	1	Failures(0) Advisories(0)
18-Nov-20	✗ FAIL	131547 MI	12418	547	Failures(1) Advisories(0)
14-Oct-20	! KEEPER 15				
27-May-20	! KEEPER 14				

16-Feb-20	!	KEEPER 13				
23-Oct-19	!	KEEPER 12				
21-May-19	✓	PASS	119129 MI	3961	398	Failures(0) Advisories(10)
18-Apr-18	✓	PASS	115168 MI	3714	365	Failures(0) Advisories(1)
10-Feb-18	!	KEEPER 11				
18-Apr-17	✓	PASS	111454 MI	100222	6	Failures(0) Advisories(0)
12-Apr-17	✗	FAIL	11232 MI	-85924	386	Failures(2) Advisories(0)
22-Mar-16	✓	PASS	97156 MI	197	5	Failures(0) Advisories(3)
17-Mar-16	✗	FAIL	96959 MI	96959	363	Failures(5) Advisories(3)
10-Feb-16	!	PLATE	<div> <div>GB</div> <div>T200YEL</div> </div> → <div> <div>GB</div> <div>LT56THK</div> </div>			
20-Mar-15	✓	PASS		-82115	16	Failures(0) Advisories(0)
04-Mar-15	✓	PASS	82115 MI	9961	141	Failures(0) Advisories(0)
14-Oct-14	✓	PASS	72154 MI	4	0	Failures(0) Advisories(0)
14-Oct-14	✗	FAIL	72150 MI	9130	181	Failures(4) Advisories(0)
16-Apr-14	✓	PASS	63020 MI	12863	162	Failures(0) Advisories(0)
16-Apr-14	✗	FAIL	63020 MI	0	0	Failures(0) Advisories(0)

05-Nov-13	 PASS	50157 MI	-170634	216	Failures(0) Advisories(0)
03-Apr-13	 PASS	220791 MI	29585	168	Failures(0) Advisories(0)
17-Oct-12	 PASS	191206 MI	0	0	Failures(0) Advisories(0)
17-Oct-12	 FAIL	191206 MI	30310	183	Failures(5) Advisories(2)
17-Apr-12	 PASS	160896 MI	464	19	Failures(0) Advisories(0)
29-Mar-12	 PASS	160432 MI	0	1	Failures(0) Advisories(0)
28-Mar-12	 FAIL	160432 MI	24615	181	Failures(2) Advisories(0)
29-Sep-11	 PASS	135817 MI	21784	180	Failures(0) Advisories(0)
02-Apr-11	 FAIL	114033 MI	14603	169	Failures(0) Advisories(1)
02-Apr-11	 PASS	114033 MI	0	0	Failures(0) Advisories(1)
15-Oct-10	 PASS	99430 MI	12278	185	Failures(0) Advisories(1)
13-Apr-10	 PASS	87152 MI	22	4	Failures(0) Advisories(0)
09-Apr-10	 FAIL	87130 MI	10627	176	Failures(4) Advisories(0)
15-Oct-09	 PASS	76503 MI	9815	167	Failures(0) Advisories(3)
01-May-09	 PASS	66688 MI	15203	196	Failures(0) Advisories(0)
17-Oct-08	 PASS	51485 MI	15808	169	Failures(0) Advisories(0)

01-May-08	 PASS	35677 MI	11566	181	Failures(0) Advisories(0)
02-Nov-07	 PASS	24111 MI	0	0	Failures(0) Advisories(0)
30-Sep-06	 KEEPER 1				

## Mileage History

S No.	Date	Mileage	Difference	Days
34	18-Nov-21	152609 MI	0	0
33	18-Nov-21	152609 MI	20987 MI	364
Keeper	07-Aug-21			
32	19-Nov-20	131622 MI	75 MI	1
31	18-Nov-20	131547 MI	12418 MI	547
Keeper	14-Oct-20			
Keeper	27-May-20			
Keeper	16-Feb-20			
Keeper	23-Oct-19			
30	21-May-19	119129 MI	3961 MI	398
29	18-Apr-18	115168 MI	3714 MI	365
Keeper	10-Feb-18			
28	18-Apr-17	111454 MI	100222 MI	6
27	12-Apr-17	11232 MI	-85924 MI	386
26	22-Mar-16	97156 MI	197 MI	5
25	17-Mar-16	96959 MI	14844 MI	363

Plate 1

10-Feb-16



T200YEL



LT56THK

24

20-Mar-15

16

23

04-Mar-15

82115 MI

9961 MI

141

22

14-Oct-14

72154 MI

4 MI

0

21

14-Oct-14

72150 MI

9130 MI

181

20

16-Apr-14

63020 MI

0

162

19

16-Apr-14

63020 MI

12863 MI

0

18

05-Nov-13

50157 MI

-170634 MI

216

17

03-Apr-13

220791 MI

29585 MI

168

16

17-Oct-12

191206 MI

0

0

15

17-Oct-12

191206 MI

30310 MI

183

14

17-Apr-12

160896 MI

464 MI

19

13

29-Mar-12

160432 MI

0

1

12

28-Mar-12

160432 MI

24615 MI

181

11

29-Sep-11

135817 MI

21784 MI

180

10

02-Apr-11

114033 MI

0

169

9

02-Apr-11

114033 MI

14603 MI

0

8

15-Oct-10

99430 MI

12278 MI

185

7

13-Apr-10

87152 MI

22 MI

4

6

09-Apr-10

87130 MI

10627 MI

176

5

15-Oct-09

76503 MI

9815 MI

167

4	01-May-09	66688 MI	15203 MI	196
3	17-Oct-08	51485 MI	15808 MI	169
2	01-May-08	35677 MI	11566 MI	181
1	02-Nov-07	24111 MI		0
Keeper	30-Sep-06			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

#### Mileage Reverse

A discrepancy in mileage has been detected in the MOT history.

#### Taxi MOT gaps

This vehicle may have been used commercially (3 consecutive 6-month MOTs).

## Vehicle Information

Vehicle Registration Mark	LT56THK	Make & Model	TOYOTA PRIUS T3 VVT-I AUTO
Make	TOYOTA	Model	PRIUS T3 VVT-I AUTO
Engine Capacity	1497	Year of Manufacture	2006
Fuel	***	Date First Registered	30-Sep-06
Premium Vehicle Year 2 to 6 - Twelve Month	***	Date of 1st Registration in UK	30-Sep-06
Colour	BLACK	Year-Month 1st Registered	2006-09
CO2 Emissions	104	Transmission	AUTO VARIABLE 4 GEARS
Gear Count	4	Transmission Type	Automatic
Engine Number	1NZ4117883	Transmission Code	A
Gross Weight	1725	Door Plan Code	***
Maximum Permissible Mass	***	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	06-Oct-25 22:15:34		

## General Information

Make	Toyota	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	85
Valve Gear	DOHC	Location	FRONT
Description	***	Bore	75
Power Delivery	Electric Hybrid	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	***
Series Description	XW20	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

## Previous Keepers

Total Keepers	16	Keeper Data Count	6
Keeper 16 (Current Keeper)			07-Aug-21
Keeper 15			14-Oct-20
Keeper 14			27-May-20
Keeper 13			16-Feb-20
Keeper 12			23-Oct-19
Keeper 11			10-Feb-18
Keeper 1 (First Keeper)			30-Sep-06

## V5C Certificate issue details

V5C Certificate Count	6	Certificate Dates	12-Aug-21 04-Nov-20 21-Sep-20 17-Feb-20 06-Nov-19 11-Feb-19
-----------------------	---	-------------------	--



## Vehicle Tax & CO2 Emissions

Standard Six Month	***	Per Month	0
Standard Twelve Month	20	Per Month	1.67
First Year Six Month	---	Per Month	---
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	---	Per Month	---
Premium Vehicle Year 2 to 6 - Twelve Month	---	Per Month	---
VED CO? Emissions	104	VED Band	B
VED CO? Band	B		

## Performance Information

Torque FtLb	84.9	Power Rpm	5000
Torque Rpm	4000	Power Bhp	76.4
Torque Nm	115	Power Kw	57
Co?	104	NoiseLevel	***
Max Speed Mph	106	Particles	***
Max Speed Kph	170	Data Version Number	***
Acceleration Zero To 60Mph	10.9	Acceleration Mph	10.9
Acceleration Zero To 100Kph	***	Acceleration Kph	***

## Consumption

Combined Mpg	65.7	Combined Lkm	4.3
ExtraUrban Mpg	67.3	ExtraUrban Lkm	4.2
UrbanCold Mpg	56.5	UrbanCold Lkm	5

## ! Plate Change History

Plate Change Count	1		
1	10-Feb-16	 T200YEL         →  LT56THK	

## ✓ Import/Export

Exported	No	Export Date	***
Imported	No		

## Scrap Destructions

Scrapped	Yes	Date of Scrapped	16-Dec-22
Certificate of Destruction Issued	Yes	Vehicle ID Check Count	0

## Colour Changes

Current Colour	BLACK	Number Of Previous Colours	2
Last Colour	YELLOW	Date Of Last Colour Change	10-Feb-16
Original Colour	BLACK		

## Previous VRM

Previous Northern Ireland	***	Previous UK VRM	T200YEL
---------------------------	-----	-----------------	---------

## Dimensions

Gross Vehicle Weight	1725	Height	1490
Gross Combined Weight	1725	Width	1725
Kerb Weight	1325	Car Length	4450
Unladen Weight	1325	Wheel Base	2700
Fuel Tank Capacity	45	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

## Safety

Adult	***	Child	***
Pedestrian	***		


## Classification Details

SMMT Make	Toyota	DVLA Make	TOYOTA
SMMT Range	Prius	DVLA Model	PRIUS T3 VVT-I AUTO
SMMT Trim	Prius T3 VVT-I Auto	Is Electric Vehicle	
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

## Smmt Details

Marque	Toyota	Range	Prius
Model Variant	Prius T3 VVT-I Auto	Fuel Type	Petrol/Electric
Nominal Engine Capacity	1.5	Transmission	CVT
Engine Capacity	1497	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	4
DriveType	4x2	SysSetup Date	01-Sep-04
Country Of Origin	Japan	Visibility Date	01-Sep-04
Series	XW20	TerminateDate	11-May-13
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

## MOT Test List

Date	Result	Mileage	Test Number
18-Nov-21	 <b>PASS</b>	152609 MI	575704003810

### Advisories

- ADVISORY** Front Headlamp has a product on the lens but not seriously reducing light output BOTH (4.1.4 (b))
- ADVISORY** Nearside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Exhaust silencer slightly loose (8.1.1 (b) (i))
- ADVISORY** Front Suspension arm ball joint has slight play BOTH (5.3.4 (a) (i))
- ADVISORY** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- ADVISORY** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- ADVISORY** Nearside Rear STOP LAMP LENS DAMAGED
- MINOR** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

18-Nov-21	 <b>FAIL</b>	152609 MI	438805665801
-----------	---	-----------	--------------

#### Advisories

- ADVISORY** Front Headlamp has a product on the lens but not seriously reducing light output BOTH (4.1.4 (b))
- ADVISORY** Nearside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Exhaust silencer slightly loose (8.1.1 (b) (i))
- ADVISORY** Front Suspension arm ball joint has slight play BOTH (5.3.4 (a) (i))
- ADVISORY** Rear Brake disc worn, pitted or scored, but not seriously weakened BOTH (1.1.14 (a) (ii))
- ADVISORY** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- ADVISORY** Nearside Rear STOP LAMP LENS DAMAGED
- MINOR** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

#### Failures

- MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Offside Front Anti-roll bar damaged and seriously weakened (5.3.3 (b) (i))

19-Nov-20



**PASS**

131622 MI

337032505918

18-Nov-20



**FAIL**

131547 MI

798406472113

#### Failures

- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

21-May-19



**PASS**

119129 MI

876086758818

#### Advisories

- ADVISORY** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- ADVISORY** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- ADVISORY** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- ADVISORY** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- ADVISORY** Nearside Rear Bumper mountings corroded but not likely to become detached (6.1.4 (a) (i))
- MINOR** Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- MINOR** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- MINOR** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

18-Apr-18



**PASS**

115168 MI

984987733327

#### Advisories

- ADVISORY** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

18-Apr-17



**PASS**

111454 MI

531025886048

12-Apr-17

**FAIL**

11232 MI

834278533304

**Failures****Failed** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Failed** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

22-Mar-16

**PASS**

97156 MI

790060025821

**Advisories****ADVISORY** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**ADVISORY** Offside Front Tyre worn close to the legal limit (4.1.E.1)**ADVISORY** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

17-Mar-16

**FAIL**

96959 MI

460083076318

**Advisories****ADVISORY** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**ADVISORY** Offside Front Tyre worn close to the legal limit (4.1.E.1)**ADVISORY** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Failures****Failed** Offside Rear position lamp(s) not working (1.1.A.3b)**Failed** Rear fog lamp not working (1.3.2b)**Failed** Windscreen washer provides insufficient washer liquid (8.2.3)**Failed** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Failed** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

20-Mar-15

**PASS**

\*\*\*

968969675036

04-Mar-15

**PASS**

82115 MI

856503265015

14-Oct-14

**PASS**

72154 MI

228157984286

14-Oct-14

**FAIL**

72150 MI

275927784294

#### Failures

- Failed** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Failed** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Failed** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Failed** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

16-Apr-14



**PASS**

63020 MI

647456204150

16-Apr-14



**FAIL**

63020 MI

895666904140

#### Failures

- PRS** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

05-Nov-13



**PASS**

50157 MI

866199903339

03-Apr-13



**PASS**

220791 MI

895233993094

17-Oct-12



**PASS**

191206 MI

145171592243

17-Oct-12



**FAIL**

191206 MI

948041192280

#### Advisories

- ADVISORY** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- ADVISORY** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

#### Failures

- Failed** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Failed** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Failed** Offside Rear position lamp(s) not working (1.1.A.3b)
- Failed** Nearside Registration plate lamp not working (1.1.C.1d)
- Failed** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

17-Apr-12



**PASS**

160896 MI

326248702147

29-Mar-12



**PASS**

160432 MI

136189382481

28-Mar-12



**FAIL**

160432 MI

345708982046

**Failures**

- Failed** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Failed** Front brake disc in such a condition that it is seriously weakened (3.5.1i)

29-Sep-11



**PASS**

135817 MI

375752771253

02-Apr-11



**FAIL**

114033 MI

276362191007

**Advisories**

- ADVISORY** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Failures**

- PRS** Nearside Front position lamp(s) not working (1.1.A.3b)
- PRS** Offside Registration plate lamp not working (1.1.C.1d)

02-Apr-11



**PASS**

114033 MI

988712691009

**Advisories**

- ADVISORY** Offside Front Brake pad(s) wearing thin (3.5.1g)

15-Oct-10



**PASS**

99430 MI

901198080259

**Advisories**

- ADVISORY** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

13-Apr-10



**PASS**

87152 MI

233193800135

09-Apr-10



**FAIL**

87130 MI

123589290021

**Failures**

- Failed** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Failed** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Failed** Nearside Headlamp not working on main beam (1.7.5a)
- Failed** Windscreen washer provides insufficient washer liquid (8.2.3)

15-Oct-09



**PASS**

76503 MI

253638089266

#### Advisories

**ADVISORY** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**ADVISORY** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**ADVISORY** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

01-May-09



**PASS**

66688 MI

580501029123

17-Oct-08



**PASS**

51485 MI

363681898291

01-May-08



**PASS**

35677 MI

953482028122

02-Nov-07



**PASS**

24111 MI

542506007308

#### Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.