

YOUR VEHICLE DATA

Scrapped

Exported

Imported

Plate Change

!

Colour Change

Mileage

Taxi

Recall

Keepers

5

Keeper

28-Sep-24
20-Jul-24
19-Jul-21
24-Jun-16
26-Feb-15

Taxed

Tax due: 01-Sep-26

Vehicle Make	SKODA
Fuel Type	DIESEL
Cylinder Capacity	1598
Vehicle Colour	SILVER
Euro Stats	***
Co2 Emissions	102
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

MOT Status

Expires 01-Mar-27



















Year Of Manufacture	2015
Date Of First Registration	Feb-15
Date Of Last V5C (logbook) Issued	01-Oct-24
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	1870
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	10	✓ Pass Rate	90%
✓ Test Passed	9	! Pass Rate With Advisory	77%
! Passed With Advisory	7	✓ Pass Rate Without Advisory	23%
! Total Items Advised	21	✓ Mileage Issues	No
! Advisory Average/Per MOT	2.33	Last MOT Mileage	142177 MI
✗ Test Failed	1	Est Current Mileage	144734 MI
✗ Total Items Failed	2	Average Mileage	12925 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✗ Mileage Status	Above Average






MOT Test List

Date	Result	Mileage	Difference	Days	Reason
17-Feb-26	✓ PASS	142177 MI	11952	355	Failures(0) Advisories(3)
27-Feb-25	✓ PASS	130225 MI	0	1	Failures(0) Advisories(3)
26-Feb-25	✗ FAIL	130225 MI	10597	364	Failures(2) Advisories(3)
28-Sep-24	! KEEPER 5				
20-Jul-24	! KEEPER 4				
03-Jul-24	! PLATE	<div> <div>GB</div> <div>E19DYG</div> </div> → <div> <div>GB</div> <div>SR64AUT</div> </div>			
28-Feb-24	✓ PASS	119628 MI	13810	365	Failures(0) Advisories(3)

28-Feb-23	 PASS	105818 MI	14079	364	Failures(0) Advisories(4)
06-Jan-23	 PLATE	 SR64AUT →  E19DYG			
31-Dec-22	 PLATE	 E4OYS →  SR64AUT			
01-Mar-22	 PASS	91739 MI	13471	378	Failures(0) Advisories(2)
06-Aug-21	 PLATE	 SR64AUT →  E4OYS			
19-Jul-21	 KEEPER 3				
16-Feb-21	 PASS	78268 MI	3608	351	Failures(0) Advisories(1)
02-Mar-20	 PASS	74660 MI	13033	381	Failures(0) Advisories(5)
15-Feb-19	 PASS	61627 MI	18136	360	Failures(0) Advisories(0)
20-Feb-18	 PASS	43491 MI	0	0	Failures(0) Advisories(0)
24-Jun-16	 KEEPER 2				
26-Feb-15	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
14	17-Feb-26	142177 MI	11952 MI	355
13	27-Feb-25	130225 MI	0	1
12	26-Feb-25	130225 MI	10597 MI	364

Keeper		28-Sep-24		
Keeper		20-Jul-24		
11	03-Jul-24	 E19DYG	→	 SR64AUT
10	28-Feb-24	119628 MI	13810 MI	365
9	28-Feb-23	105818 MI	14079 MI	364
8	06-Jan-23	 SR64AUT	→	 E19DYG
7	31-Dec-22	 E4OYS	→	 SR64AUT
6	01-Mar-22	91739 MI	13471 MI	378
5	06-Aug-21	 SR64AUT	→	 E4OYS
Keeper		19-Jul-21		
4	16-Feb-21	78268 MI	3608 MI	351
3	02-Mar-20	74660 MI	13033 MI	381
2	15-Feb-19	61627 MI	18136 MI	360
1	20-Feb-18	43491 MI		0
Keeper		24-Jun-16		
Keeper		26-Feb-15		



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information			
Vehicle Registration Mark	SR64AUT	Make & Model	SKODA OCTAVIA SE TDI CR S-A
Make	SKODA	Model	OCTAVIA SE TDI CR S-A
Engine Capacity	1598	Year of Manufacture	2015
Fuel	***	Date First Registered	26-Feb-15
Premium Vehicle Year 2 to 6 - Twelve Month	***	Date of 1st Registration in UK	26-Feb-15
Colour	SILVER	Year-Month 1st Registered	2015-02
CO2 Emissions	102	Transmission	AUTO 7 GEARS
Gear Count	7	Transmission Type	Semi Auto
Engine Number	CLHAC84981	Transmission Code	S
Gross Weight	1870	Door Plan Code	***
Maximum Permissible Mass	***	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	01-Feb-25 05:33:40		

General Information			
Make	Skoda Auto UK Ltd	Euro Status	5b
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	High Pressure Direct Injection
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	80
Valve Gear	DOHC	Location	FRONT
Description	1.6 TDI 105PS-E	Bore	80
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	***
Series Description	5E	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	5	Keeper Data Count	4
Keeper 5 (Current Keeper)			28-Sep-24
Keeper 4			20-Jul-24
Keeper 3			19-Jul-21
Keeper 2			24-Jun-16
Keeper 1 (First Keeper)			26-Feb-15

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	01-Oct-24 20-Jul-24 06-Jan-23 05-Jul-16
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	***	Per Month	0
Standard Twelve Month	20	Per Month	1.67
First Year Six Month	---	Per Month	---
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	---	Per Month	---
Premium Vehicle Year 2 to 6 - Twelve Month	---	Per Month	---
VED CO? Emissions	102	VED Band	B
VED CO? Band	B		









Performance Information

Torque FtLb	184	Power Rpm	4000
Torque Rpm	2750	Power Bhp	103.3
Torque Nm	250	Power Kw	77
Co?	102	NoiseLevel	***
Max Speed Mph	121	Particles	***
Max Speed Kph	194	Data Version Number	***
Acceleration Zero To 60Mph	***	Acceleration Mph	***
Acceleration Zero To 100Kph	10.9	Acceleration Kph	10.9

Consumption

Combined Mpg	72.4	Combined Lkm	3.9
ExtraUrban Mpg	80.7	ExtraUrban Lkm	3.5
UrbanCold Mpg	61.4	UrbanCold Lkm	4.6

! Plate Change History

Plate Change Count	4	
1	03-Jul-24	 E19DYG →  SR64AUT
2	06-Jan-23	 SR64AUT →  E19DYG
3	31-Dec-22	 E4OYS →  SR64AUT
4	06-Aug-21	 SR64AUT →  E4OYS

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	SILVER	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	SILVER		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	E19DYG
---------------------------	-----	-----------------	--------

Dimensions			
Gross Vehicle Weight	1870	Height	1461
Gross Combined Weight	***	Width	2017
Kerb Weight	1320	Car Length	4659
Unladen Weight	1320	Wheel Base	2686
Fuel Tank Capacity	50	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	1.58
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety			
Adult	93	Child	86
Pedestrian	66		

Classification Details			
SMMT Make	Skoda	DVLA Make	SKODA
SMMT Range	Octavia	DVLA Model	OCTAVIA SE TDI CR S-A
SMMT Trim	Octavia SE TDI CR Semi-Auto	Is Electric Vehicle	
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Skoda	Range	Octavia
Model Variant	Octavia SE TDI CR Semi-Auto	Fuel Type	Diesel
Nominal Engine Capacity	1.6	Transmission	Semi Automatic
Engine Capacity	1598	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	7
DriveType	4x2	SysSetup Date	03-Jan-13
Country Of Origin	Czech Republic	Visibility Date	03-Jan-13
Series	5E	TerminateDate	03-Mar-16
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

17-Feb-26



PASS

142177 MI

988914858192

Advisories

- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened both front discs (1.1.14 (a) (ii))
- ADVISORY** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- MINOR** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

27-Feb-25



PASS

130225 MI

601234444998

Advisories

- ADVISORY** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MINOR** Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i))

26-Feb-25



FAIL

130225 MI

601910502864

Advisories

- ADVISORY** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MINOR** Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i))

Failures

- MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

28-Feb-24



PASS

119628 MI

211601982376

Advisories

ADVISORY Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Child Seat fitted not allowing full inspection of adult belt

28-Feb-23



PASS

105818 MI

592943459095

Advisories

ADVISORY Nearside Rear Child Seat fitted not allowing full inspection of adult belt

ADVISORY Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

ADVISORY Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

ADVISORY Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

01-Mar-22



PASS

91739 MI

485309698354

Advisories

ADVISORY Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

ADVISORY Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

16-Feb-21



PASS

78268 MI

174897716347

Advisories

MINOR Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

02-Mar-20



PASS

74660 MI

510637797922

Advisories

ADVISORY Offside Rear Service brake binding but not excessively (1.2.1 (f))

ADVISORY Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

ADVISORY Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MINOR Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

15-Feb-19



PASS

61627 MI

373077200454

20-Feb-18



PASS

43491 MI

722234103215

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.