

YOUR VEHICLE DATA

Scrapped

Exported

Imported

Plate Change

Colour Change

Mileage

Taxi

Recall

Keepers

9

Keeper

30-Nov-19
20-Jul-18
01-Apr-16
25-Feb-12
28-May-10
24-Apr-09
27-Aug-08
09-May-07
09-May-07

Taxed

Tax due: 28-Apr-26

Vehicle Make

MAZDA

Fuel Type

DIESEL

Cylinder Capacity

2490

Vehicle Colour

WHITE

Euro Stats

Co2 Emissions

Real Driving Emissions (RDE)

Wheelplan

2 AXLE RIGID BODY

Ulez Compliance

[Check TFL](#)

MOT Status

Expires 20-Nov-26

Year Of Manufacture

1999

Date Of First Registration

Mar-99

Date Of Last V5C (logbook) Issued

05-May-26

Export Marker

Vehicle Type Approval

Revenue Weight

Vehicle Status

Untaxed

MOT Status


Valid

Mot & Mileage Summary

Total Test	28	! Pass Rate	75%
✓ Test Passed	21	! Pass Rate With Advisory	47%
! Passed With Advisory	10	✓ Pass Rate Without Advisory	53%
! Total Items Advised	25	✓ Mileage Issues	No
! Advisory Average/Per MOT	1.19	Last MOT Mileage	127806 KM
✗ Test Failed	7	Est Current Mileage	129550 KM
✗ Total Items Failed	9	Average Mileage	4915 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✓ Mileage Status	Below Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
13-Nov-25	✓ PASS	127806 KM	19	7	Failures(0) Advisories(3)
06-Nov-25	✗ FAIL	127787 KM	3721	366	Failures(1) Advisories(3)
05-Nov-24	✓ PASS	124066 KM	3205	363	Failures(0) Advisories(2)
08-Nov-23	✓ PASS	120861 KM	1	1	Failures(0) Advisories(2)
07-Nov-23	✗ FAIL	120860 KM	2491	354	Failures(3) Advisories(2)
18-Nov-22	✓ PASS	118369 KM	2845	374	Failures(0) Advisories(1)
09-Nov-21	✓ PASS	115524 MI	2461	361	Failures(0) Advisories(6)

13-Nov-20	 PASS	113063 MI	1908	358	Failures(0) Advisories(3)
30-Nov-19	 KEEPER 9				
21-Nov-19	 PASS	111155 KM	4892	275	Failures(0) Advisories(0)
19-Feb-19	 PASS	106263 KM	1183	340	Failures(0) Advisories(3)
20-Jul-18	 KEEPER 8				
16-Mar-18	 PASS	105080 MI	1	7	Failures(0) Advisories(0)
09-Mar-18	 FAIL	105079 MI	974	388	Failures(1) Advisories(0)
14-Feb-17	 PASS	104105 MI	0	0	Failures(0) Advisories(0)
14-Feb-17	 FAIL	104105 MI	3819	350	Failures(0) Advisories(0)
01-Apr-16	 KEEPER 7				
01-Mar-16	 PASS	100286 MI	0	0	Failures(0) Advisories(1)
01-Mar-16	 FAIL	100286 MI	1624	368	Failures(0) Advisories(1)
27-Feb-15	 PASS	98662 MI	0	1	Failures(0) Advisories(0)
26-Feb-15	 FAIL	98662 MI	1740	365	Failures(1) Advisories(0)
26-Feb-14	 PASS	96922 MI	4343	355	Failures(0) Advisories(3)
08-Mar-13	 PASS	92579 MI	3918	399	Failures(0) Advisories(0)

25-Feb-12	!	KEEPER 6				
03-Feb-12	✓	PASS	88661 MI	2106	263	Failures(0) Advisories(0)
16-May-11	✓	PASS	86555 KM	3962	361	Failures(0) Advisories(1)
28-May-10	!	KEEPER 5				
20-May-10	✓	PASS	82593 MI	1525	281	Failures(0) Advisories(0)
12-Aug-09	✓	PASS	81068 MI	5155	359	Failures(0) Advisories(0)
24-Apr-09	!	KEEPER 4				
27-Aug-08	!	KEEPER 3				
18-Aug-08	✓	PASS	75913 KM	0	0	Failures(0) Advisories(0)
18-Aug-08	✗	FAIL	75913 MI	4377	460	Failures(1) Advisories(0)
16-May-07	✓	PASS	71536 KM	33	205	Failures(0) Advisories(0)
09-May-07	!	KEEPER 2				
09-May-07	!	KEEPER 1				
23-Oct-06	✓	PASS	71503 KM	0	0	Failures(0) Advisories(0)

Mileage History

S No.	Date	Mileage	Difference	Days
28	13-Nov-25	127806 KM	19 MI	7

27	06-Nov-25	127787 KM	3721 MI	366
26	05-Nov-24	124066 KM	3205 MI	363
25	08-Nov-23	120861 KM	1 MI	1
24	07-Nov-23	120860 KM	2491 MI	354
23	18-Nov-22	118369 KM	2845 MI	374
22	09-Nov-21	115524 MI	2461 MI	361
21	13-Nov-20	113063 MI	1908 MI	358
Keeper	30-Nov-19			
20	21-Nov-19	111155 KM	4892 MI	275
19	19-Feb-19	106263 KM	1183 MI	340
Keeper	20-Jul-18			
18	16-Mar-18	105080 MI	1 MI	7
17	09-Mar-18	105079 MI	974 MI	388
16	14-Feb-17	104105 MI	0	0
15	14-Feb-17	104105 MI	3819 MI	350
Keeper	01-Apr-16			
14	01-Mar-16	100286 MI	0	0
13	01-Mar-16	100286 MI	1624 MI	368
12	27-Feb-15	98662 MI	0	1
11	26-Feb-15	98662 MI	1740 MI	365
10	26-Feb-14	96922 MI	4343 MI	355
9	08-Mar-13	92579 MI	3918 MI	399

Keeper		25-Feb-12		
8	03-Feb-12	88661 MI	2106 MI	263
7	16-May-11	86555 KM	3962 MI	361
Keeper		28-May-10		
6	20-May-10	82593 MI	1525 MI	281
5	12-Aug-09	81068 MI	5155 MI	359
Keeper		24-Apr-09		
Keeper		27-Aug-08		
4	18-Aug-08	75913 KM	0	0
3	18-Aug-08	75913 MI	4377 MI	460
2	16-May-07	71536 KM	33 MI	205
Keeper		09-May-07		
Keeper		09-May-07		
Keeper		09-May-07		
Keeper		09-May-07		
1	23-Oct-06	71503 KM		0



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Miles / KMs Warning

A mixture of Miles and KMs has been detected in the MOT history.

Vehicle Information			
Vehicle Registration Mark	T503BDV	Make & Model	MAZDA
Make	MAZDA	Model	
Engine Capacity	***	Year of Manufacture	1999
Fuel	***	Date First Registered	09-May-07
Premium Vehicle Year 2 to 6 - Twelve Month	***	Date of 1st Registration in UK	09-May-07
Colour	WHITE AND SILVER	Year-Month 1st Registered	2007-05
CO2 Emissions	***	Transmission	***
Gear Count	***	Transmission Type	***
Engine Number	NOT KNOWN	Transmission Code	***
Gross Weight	***	Door Plan Code	***
Maximum Permissible Mass	***	MVRIS Model Code	***
Seating Capacity	4	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	***	Vin Confirmation Flag	***
Date Of Last Update	12-Jun-24 23:31:47		

General Information			
Make	***	Euro Status	***
Aspiration	***	Fuel System	
Number Of Cylinders	***	Fuel Delivery	
Valves Per Cylinder	***	Fuel Catalyst	***
Cylinder Arrangement	***	Stroke	***
Valve Gear	***	Location	***
Description	***	Bore	***
Power Delivery	Normal	Type Approval Category	***
Driving Axle	***	Primary Fuel Flag	***
Series Description	***	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	9	Keeper Data Count	8
Keeper 9 (Current Keeper)			30-Nov-19
Keeper 8			20-Jul-18
Keeper 7			01-Apr-16
Keeper 6			25-Feb-12
Keeper 5			28-May-10
Keeper 4			24-Apr-09
Keeper 3			27-Aug-08
Keeper 2			09-May-07
Keeper 1 (First Keeper)			09-May-07

V5C Certificate issue details

V5C Certificate Count	5	Certificate Dates	05-Dec-19 23-Jul-18 27-Jul-10 06-May-09 28-May-07
-----------------------	---	-------------------	---

Vehicle Tax & CO2 Emissions

Standard Six Month	***	Per Month	0
Standard Twelve Month	0	Per Month	0
First Year Six Month	---	Per Month	---
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	---	Per Month	---
Premium Vehicle Year 2 to 6 - Twelve Month	---	Per Month	---
VED CO? Emissions	N/A	VED Band	N/A
VED CO? Band	N/A		

Performance Information

Torque FtLb	***	Power Rpm	***
Torque Rpm	***	Power Bhp	***
Torque Nm	***	Power Kw	***
Co?	***	NoiseLevel	***
Max Speed Mph	***	Particles	***
Max Speed Kph	***	Data Version Number	***
Acceleration Zero To 60Mph	***	Acceleration Mph	***
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	***	Combined Lkm	***
ExtraUrban Mpg	***	ExtraUrban Lkm	***
UrbanCold Mpg	***	UrbanCold Lkm	***

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✗ Import/Export

Exported	No	Export Date	***
Imported	Yes		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✗ Colour Changes

Current Colour	WHITE AND SILVER	Number Of Previous Colours	1
Last Colour	WHITE	Date Of Last Colour Change	25-Sep-07
Original Colour	WHITE		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	***	Height	***
Gross Combined Weight	***	Width	***
Kerb Weight	***	Car Length	***
Unladen Weight	***	Wheel Base	***
Fuel Tank Capacity	***	Pay Load Weight	***
Number Of Doors	***	Gross Train Weight	***
Number Of Seats	4	Payload Volume	***
Rigid Artic	***	Load Length	***
Number Of Axles	***	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	***	DVLA Make	MAZDA
SMMT Range	***	DVLA Model	
SMMT Trim	***	Is Electric Vehicle	
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	***	Range	***
Model Variant	***	Fuel Type	***
Nominal Engine Capacity	***	Transmission	***
Engine Capacity	***	Number Of Doors	***
Body Style	***	Number Of Gears	***
DriveType	***	SysSetup Date	***
Country Of Origin	***	Visibility Date	***
Series	***	TerminateDate	***
Marque Code	***	Cab Type	NA
Market Sector Code	***	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

13-Nov-25



PASS

127806 KM

213073396280

Advisories

ADVISORY outer sills rusted n/s and o/s

ADVISORY o/s/r lamp damaged

MINOR Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

06-Nov-25



FAIL

127787 KM

363210201273

Advisories

ADVISORY outer sills rusted n/s and o/s

ADVISORY o/s/r lamp damaged

MINOR Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Failures

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))

05-Nov-24



PASS

124066 KM

389163460701

Advisories

ADVISORY outer sills rusted n/s and o/s

MINOR Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

08-Nov-23



PASS

120861 KM

402270400421

Advisories

ADVISORY o/s outer sill rusted

MINOR Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

07-Nov-23



FAIL

120860 KM

240938952440

Advisories

ADVISORY o/s outer sill rusted

MINOR Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Failures

MAJOR Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt upper and lower (5.3.4 (b) (ii))

MAJOR Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt upper and lower (5.3.4 (b) (ii))

MAJOR Nearside Rear Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced rear arch (6.1.1 (c) (i))

18-Nov-22



PASS

118369 KM

326214733465

Advisories

MINOR Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

09-Nov-21



PASS

115524 MI

239067369229

Advisories

ADVISORY Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

ADVISORY Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

ADVISORY Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

ADVISORY Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MINOR Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

13-Nov-20



PASS

113063 MI

243470430753

Advisories

ADVISORY Oil leak, but not excessive (8.4.1 (a) (i))

ADVISORY Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

21-Nov-19



PASS

111155 KM

979540622033

19-Feb-19



PASS

106263 KM

303990948166

Advisories

ADVISORY Front Cross member rusty.

ADVISORY Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

ADVISORY Nearside Rear Outer sill and sill end.

16-Mar-18



PASS

105080 MI

287123431362

09-Mar-18



FAIL

105079 MI

397205241911

Failures

Failed Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

14-Feb-17



PASS

104105 MI

123316999892

14-Feb-17



FAIL

104105 MI

844565221513

Failures

PRS Windscreen wiper does not clear the windscreen effectively both (8.2.2)

01-Mar-16



PASS

100286 MI

611228455899

Advisories

ADVISORY Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

01-Mar-16



FAIL

100286 MI

863938723229

Advisories

ADVISORY Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Failures

PRS Headlamp aim beam image obviously incorrect both (1.8.A.1b)

27-Feb-15



PASS

98662 MI

775668855067

26-Feb-15



FAIL

98662 MI

967637555001

Failures

Failed Nearside Outer Rear Body has a projection caused by corrosion (6.1.C.1)

26-Feb-14



PASS

96922 MI

275207054042

Advisories

ADVISORY Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

ADVISORY Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)

ADVISORY Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)

08-Mar-13



PASS

92579 MI

168087663418

03-Feb-12



PASS

88661 MI

586284532029

16-May-11

**PASS**

86555 KM

766626231111

Advisories**USER ENTERED**

both track rod end boots perished, but no play in joints

20-May-10

**PASS**

82593 MI

910660840101

12-Aug-09

**PASS**

81068 MI

993704529284

18-Aug-08

**PASS**

75913 KM

654231438246

18-Aug-08

**FAIL**

75913 MI

344901038448

Failures**Failed**

Fuel cap/sealing device sealing washer missing (7.2.4c)

16-May-07

**PASS**

71536 KM

863756237104

23-Oct-06

**PASS**

71503 KM

842706896266

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.