

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✓	Keepers	1	Keeper	02-Feb-01

<div>✓</div> Taxed Tax due: 01-Aug-26	<div>✓</div> MOT Status Expires 31-Jan-27
Vehicle Make	AUDI
Fuel Type	PETROL
Cylinder Capacity	1781
Vehicle Colour	SILVER
Euro Stats	***
Co2 Emissions	***
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL
Year Of Manufacture	2001
Date Of First Registration	Feb-01
Date Of Last V5C (logbook) Issued	20-Feb-12
Export Marker	***
Vehicle Type Approval	***
Revenue Weight	1040
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	27	! Pass Rate	77%
✓ Test Passed	21	! Pass Rate With Advisory	66%
! Passed With Advisory	14	✓ Pass Rate Without Advisory	34%
! Total Items Advised	39	✓ Mileage Issues	No
! Advisory Average/Per MOT	1.86	Last MOT Mileage	89932 MI
✗ Test Failed	6	Est Current Mileage	90129 MI
✗ Total Items Failed	19	Average Mileage	3597 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✓ Mileage Status	Below Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
27-Jan-26	 PASS	89932 MI	694	362	Failures(0) Advisories(3)
30-Jan-25	 PASS	89238 MI	2	0	Failures(0) Advisories(3)
30-Jan-25	 FAIL	89236 MI	651	372	Failures(1) Advisories(3)
24-Jan-24	 PASS	88585 MI	944	363	Failures(0) Advisories(2)
26-Jan-23	 PASS	87641 MI	473	373	Failures(0) Advisories(2)
18-Jan-22	 PASS	87168 MI	1416	357	Failures(0) Advisories(2)
26-Jan-21	 PASS	85752 MI	2043	372	Failures(0) Advisories(4)
20-Jan-20	 PASS	83709 MI	0	0	Failures(0) Advisories(3)
20-Jan-20	 FAIL	83709 MI	2460	357	Failures(0) Advisories(3)
28-Jan-19	 PASS	81249 MI	3047	363	Failures(0) Advisories(1)
30-Jan-18	 PASS	78202 MI	1960	378	Failures(0) Advisories(2)
17-Jan-17	 PASS	76242 MI	4943	364	Failures(0) Advisories(3)
19-Jan-16	 PASS	71299 MI	3169	357	Failures(0) Advisories(1)
27-Jan-15	 PASS	68130 MI	3	1	Failures(0) Advisories(3)

26-Jan-15	 FAIL	68127 MI	3869	363	Failures(2) Advisories(5)
28-Jan-14	 PASS	64258 MI	4	1	Failures(0) Advisories(5)
27-Jan-14	 FAIL	64254 MI	4295	363	Failures(2) Advisories(5)
29-Jan-13	 PASS	59959 MI	3	1	Failures(0) Advisories(5)
28-Jan-13	 FAIL	59956 MI	6770	374	Failures(3) Advisories(5)
20-Jan-12	 PASS	53186 MI	2919	359	Failures(0) Advisories(0)
26-Jan-11	 PASS	50267 MI	5302	363	Failures(0) Advisories(0)
28-Jan-10	 PASS	44965 MI	3964	367	Failures(0) Advisories(0)
28-Jan-10	 FAIL	44965 MI	0	0	Failures(0) Advisories(0)
26-Jan-09	 PASS	41001 MI	4530	362	Failures(0) Advisories(0)
30-Jan-08	 PASS	36471 MI	2442	369	Failures(0) Advisories(0)
26-Jan-07	 PASS	34029 MI	2831	364	Failures(0) Advisories(0)
27-Jan-06	 PASS	31198 MI	0	0	Failures(0) Advisories(0)
02-Feb-01	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
27	27-Jan-26	89932 MI	694 MI	362

26	30-Jan-25	89238 MI	2 MI	0
25	30-Jan-25	89236 MI	651 MI	372
24	24-Jan-24	88585 MI	944 MI	363
23	26-Jan-23	87641 MI	473 MI	373
22	18-Jan-22	87168 MI	1416 MI	357
21	26-Jan-21	85752 MI	2043 MI	372
20	20-Jan-20	83709 MI	0	0
19	20-Jan-20	83709 MI	2460 MI	357
18	28-Jan-19	81249 MI	3047 MI	363
17	30-Jan-18	78202 MI	1960 MI	378
16	17-Jan-17	76242 MI	4943 MI	364
15	19-Jan-16	71299 MI	3169 MI	357
14	27-Jan-15	68130 MI	3 MI	1
13	26-Jan-15	68127 MI	3869 MI	363
12	28-Jan-14	64258 MI	4 MI	1
11	27-Jan-14	64254 MI	4295 MI	363
10	29-Jan-13	59959 MI	3 MI	1
9	28-Jan-13	59956 MI	6770 MI	374
8	20-Jan-12	53186 MI	2919 MI	359
7	26-Jan-11	50267 MI	5302 MI	363
6	28-Jan-10	44965 MI	0	367
5	28-Jan-10	44965 MI	3964 MI	0

4	26-Jan-09	41001 MI	4530 MI	362
3	30-Jan-08	36471 MI	2442 MI	369
2	26-Jan-07	34029 MI	2831 MI	364
1	27-Jan-06	31198 MI		0
Keeper02-Feb-01				



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information			
Vehicle Registration Mark	X965CSG	Make & Model	AUDI
Make	AUDI	Model	
Engine Capacity	***	Year of Manufacture	2001
Fuel	***	Date First Registered	02-Feb-01
Premium Vehicle Year 2 to 6 - Twelve Month	***	Date of 1st Registration in UK	02-Feb-01
Colour	SILVER	Year-Month 1st Registered	2001-02
CO2 Emissions	***	Transmission	***
Gear Count	***	Transmission Type	***
Engine Number	1008906	Transmission Code	***
Gross Weight	1040	Door Plan Code	***
Maximum Permissible Mass	***	MVRIS Model Code	***
Seating Capacity	***	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	***	Vin Confirmation Flag	***
Date Of Last Update	09-Sep-25 22:37:25		

General Information			
Make	***	Euro Status	***
Aspiration	***	Fuel System	
Number Of Cylinders	***	Fuel Delivery	
Valves Per Cylinder	***	Fuel Catalyst	***
Cylinder Arrangement	***	Stroke	***
Valve Gear	***	Location	***
Description	***	Bore	***
Power Delivery	Normal	Type Approval Category	***
Driving Axle	***	Primary Fuel Flag	***
Series Description	***	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers			
Total Keepers	1	Keeper Data Count	0
Keeper 1 (First Keeper)			02-Feb-01

V5C Certificate issue details			
V5C Certificate Count	1	Certificate Dates	20-Feb-12

Vehicle Tax & CO2 Emissions			
Standard Six Month	***	Per Month	0
Standard Twelve Month	0	Per Month	0
First Year Six Month	---	Per Month	---
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	---	Per Month	---
Premium Vehicle Year 2 to 6 - Twelve Month	---	Per Month	---
VED CO? Emissions	N/A	VED Band	N/A
VED CO? Band	N/A		

Performance Information

Torque FtLb	***	Power Rpm	***
Torque Rpm	***	Power Bhp	***
Torque Nm	***	Power Kw	***
Co?	***	NoiseLevel	***
Max Speed Mph	***	Particles	***
Max Speed Kph	***	Data Version Number	***
Acceleration Zero To 60Mph	***	Acceleration Mph	***
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	***	Combined Lkm	***
ExtraUrban Mpg	***	ExtraUrban Lkm	***
UrbanCold Mpg	***	UrbanCold Lkm	***

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	SILVER	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	SILVER		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	***	Height	***
Gross Combined Weight	***	Width	***
Kerb Weight	***	Car Length	***
Unladen Weight	***	Wheel Base	***
Fuel Tank Capacity	***	Pay Load Weight	***
Number Of Doors	***	Gross Train Weight	***
Number Of Seats	***	Payload Volume	***
Rigid Artic	***	Load Length	***
Number Of Axles	***	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	***	DVLA Make	AUDI
SMMT Range	***	DVLA Model	
SMMT Trim	***	Is Electric Vehicle	
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	***	Range	***
Model Variant	***	Fuel Type	***
Nominal Engine Capacity	***	Transmission	***
Engine Capacity	***	Number Of Doors	***
Body Style	***	Number Of Gears	***
DriveType	***	SysSetup Date	***
Country Of Origin	***	Visibility Date	***
Series	***	TerminateDate	***
Marque Code	***	Cab Type	NA
Market Sector Code	***	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

27-Jan-26



PASS

89932 MI

413215522003

Advisories

- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Offside Rear Shock absorbers has slight external damage to the casing Corroded (5.3.2 (b))

30-Jan-25



PASS

89238 MI

681588832115

Advisories

- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Offside Rear Upper Shock absorbers has slight external damage to the casing (5.3.2 (b))

30-Jan-25



FAIL

89236 MI

867312955619

Advisories

- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Offside Rear Upper Shock absorbers has slight external damage to the casing (5.3.2 (b))

Failures

- DANGEROUS** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

24-Jan-24



PASS

88585 MI

823177160520

Advisories

- ADVISORY** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- ADVISORY** Undertrays fitted

26-Jan-23



PASS

87641 MI

335534996524

Advisories

- ADVISORY** engine & under tray sill cover fitted
- ADVISORY** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

18-Jan-22



PASS

87168 MI

380952529999

Advisories

- ADVISORY** under trays fitted
- ADVISORY** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

26-Jan-21



PASS

85752 MI

649417163540

Advisories

- ADVISORY** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- ADVISORY** under trays fitted
- ADVISORY** offside rear shock casing corroded

20-Jan-20



PASS

83709 MI

374267933347

Advisories

- ADVISORY** under trays fitted
- ADVISORY** offside rear shock casing corroded
- ADVISORY** Oil leak, but not excessive engine (8.4.1 (a) (i))

20-Jan-20



FAIL

83709 MI

426530155076

Advisories

- ADVISORY** under trays fitted
- ADVISORY** offside rear shock casing corroded
- ADVISORY** Oil leak, but not excessive engine (8.4.1 (a) (i))

Failures

- PRS** Nearside Front Headlamp aim too low (4.1.2 (a))
- PRS** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

28-Jan-19



PASS

81249 MI

424466047906

Advisories

- ADVISORY** engine covers & under trays fitted

30-Jan-18



PASS

78202 MI

661766140104

Advisories

- ADVISORY** Nearside Rear Service brake grabbing slightly (3.7.C.2)
- ADVISORY** Oil leak

17-Jan-17



PASS

76242 MI

791377088439

Advisories

- ADVISORY** under trays fitted
- ADVISORY** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- ADVISORY** Offside Front Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)

19-Jan-16



PASS

71299 MI

419614571699

Advisories

- ADVISORY** Top and bottom tray fitted

27-Jan-15



PASS

68130 MI

509677925053

Advisories

- ADVISORY** Front Power steering component(s) has slight seepage from a component (2.3.3b)
- USER ENTERED** Under-trays fitted obscuring some underside components
- USER ENTERED** Engine covers fitted obscuring some components in the engine bay

26-Jan-15



FAIL

68127 MI

115926525093

Advisories

- ADVISORY** Front Power steering component(s) has slight seepage from a component (2.3.3b)
- ADVISORY** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- USER ENTERED** Under-trays fitted obscuring some underside components
- USER ENTERED** Engine covers fitted obscuring some components in the engine bay

Failures

- Failed** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Failed** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

28-Jan-14



PASS

64258 MI

197978424056

Advisories

- ADVISORY** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- USER ENTERED** Under-trays fitted obscuring some underside components
- USER ENTERED** Engine covers fitted obscuring some components in the engine bay
- USER ENTERED** Offside and nearside rear Tyres wearing on inner edges.

27-Jan-14



FAIL

64254 MI

998997224067

Advisories

- ADVISORY** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- USER ENTERED** Under-trays fitted obscuring some underside components
- USER ENTERED** Engine covers fitted obscuring some components in the engine bay
- USER ENTERED** Offside and nearside rear Tyres wearing on inner edges.

Failures

- Failed** Front Headlamp cleaning device inoperative (1.7.2)
- Failed** Battery insecure (1.9.1)

29-Jan-13



PASS

59959 MI

419119923056

Advisories

- ADVISORY** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- USER ENTERED** Under-trays fitted obscuring some underside components
- USER ENTERED** Engine covers fitted obscuring some components in the engine bay
- USER ENTERED** Offside rear Tyre has a cut on inner sidewall but not reaching cords.

28-Jan-13



FAIL

59956 MI

476088023006

Advisories

- ADVISORY** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- USER ENTERED** Under-trays fitted obscuring some underside components
- USER ENTERED** Engine covers fitted obscuring some components in the engine bay
- USER ENTERED** Offside rear Tyre has a cut on inner sidewall but not reaching cords.

Failures

- Failed** Nearside Rear coil spring incomplete (2.4.C.1a)
- Failed** Offside Rear coil spring incomplete (2.4.C.1a)
- Failed** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

20-Jan-12



PASS

53186 MI

807940222042

26-Jan-11



PASS

50267 MI

786946521060

28-Jan-10



PASS

44965 MI

782098020051

28-Jan-10



FAIL

44965 MI

161478220485

Failures

PRS

Registration plate lamp not working (1.1.5c)

26-Jan-09



PASS

41001 MI

913146529004

30-Jan-08



PASS

36471 MI

763140938012

26-Jan-07



PASS

34029 MI

281696427018

27-Jan-06



PASS

31198 MI

491967026019

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.