

YOUR VEHICLE DATA

Scrapped

Exported

Imported

Plate Change

Colour Change

Mileage

Taxi

Recall

Keepers

3

Keeper

26-Jun-25
08-Jul-24
09-May-07

Taxed

Tax due: 01-Jan-27

Vehicle Make	FORD
Fuel Type	PETROL
Cylinder Capacity	1596
Vehicle Colour	BLUE
Euro Stats	***
Co2 Emissions	184 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

MOT Status

Expires 07-Jul-26

Year Of Manufacture	2007
Date Of First Registration	May-07
Date Of Last V5C (logbook) Issued	27-Jun-25
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	***
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	23	✗ Pass Rate	69%
✓ Test Passed	16	! Pass Rate With Advisory	31%
! Passed With Advisory	5	✓ Pass Rate Without Advisory	69%
! Total Items Advised	14	✓ Mileage Issues	No
! Advisory Average/Per MOT	0.88	Last MOT Mileage	92072 MI
✗ Test Failed	7	Est Current Mileage	92860 MI
✗ Total Items Failed	15	Average Mileage	5115 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✓ Mileage Status	Below Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
08-Jul-25	✓ PASS	92072 MI	4	3	Failures(0) Advisories(2)
05-Jul-25	✗ FAIL	92068 MI	816	362	Failures(1) Advisories(2)
26-Jun-25	! KEEPER 3				
08-Jul-24	✓ PASS	91252 MI	2246	284	Failures(0) Advisories(0)
08-Jul-24	! KEEPER 2				
28-Sep-23	✓ PASS	89006 MI	0	0	Failures(0) Advisories(1)
28-Sep-23	✗ FAIL	89006 MI	4067	357	Failures(2) Advisories(1)

06-Oct-22	 PASS	84939 MI	0	0	Failures(0) Advisories(3)
06-Oct-22	 FAIL	84939 MI	4953	367	Failures(5) Advisories(4)
04-Oct-21	 PASS	79986 MI	3452	364	Failures(0) Advisories(0)
05-Oct-20	 PASS	76534 MI	0	0	Failures(0) Advisories(3)
05-Oct-20	 FAIL	76534 MI	4369	517	Failures(0) Advisories(3)
07-May-19	 PASS	72165 MI	3	0	Failures(0) Advisories(0)
07-May-19	 FAIL	72162 MI	4747	368	Failures(1) Advisories(0)
04-May-18	 PASS	67415 MI	0	0	Failures(0) Advisories(0)
04-May-18	 FAIL	67415 MI	4850	380	Failures(0) Advisories(0)
19-Apr-17	 PASS	62565 MI	4443	364	Failures(0) Advisories(5)
20-Apr-16	 PASS	58122 MI	3563	355	Failures(0) Advisories(0)
01-May-15	 PASS	54559 MI	4238	354	Failures(0) Advisories(0)
12-May-14	 PASS	50321 MI	5577	375	Failures(0) Advisories(0)
02-May-13	 PASS	44744 MI	8496	353	Failures(0) Advisories(0)
14-May-12	 PASS	36248 MI	5430	363	Failures(0) Advisories(0)
17-May-11	 PASS	30818 MI	0	0	Failures(0) Advisories(0)

17-May-11	✖ FAIL	30818 MI	6692	385	Failures(2) Advisories(4)
27-Apr-10	✔ PASS	24126 MI	0	0	Failures(0) Advisories(0)
09-May-07	! KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
23	08-Jul-25	92072 MI	4 MI	3
22	05-Jul-25	92068 MI	816 MI	362
Keeper	26-Jun-25			
21	08-Jul-24	91252 MI	2246 MI	284
Keeper	08-Jul-24			
20	28-Sep-23	89006 MI	0	0
19	28-Sep-23	89006 MI	4067 MI	357
18	06-Oct-22	84939 MI	0	0
17	06-Oct-22	84939 MI	4953 MI	367
16	04-Oct-21	79986 MI	3452 MI	364
15	05-Oct-20	76534 MI	0	0
14	05-Oct-20	76534 MI	4369 MI	517
13	07-May-19	72165 MI	3 MI	0
12	07-May-19	72162 MI	4747 MI	368
11	04-May-18	67415 MI	0	0
10	04-May-18	67415 MI	4850 MI	380

9	19-Apr-17	62565 MI	4443 MI	364
8	20-Apr-16	58122 MI	3563 MI	355
7	01-May-15	54559 MI	4238 MI	354
6	12-May-14	50321 MI	5577 MI	375
5	02-May-13	44744 MI	8496 MI	353
4	14-May-12	36248 MI	5430 MI	363
3	17-May-11	30818 MI	0	0
2	17-May-11	30818 MI	6692 MI	385
1	27-Apr-10	24126 MI		0
Keeper	09-May-07			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	BJ07WJA	Make & Model	FORD FOCUS ZETEC CLIMATE AUTO
Make	FORD	Model	FOCUS ZETEC CLIMATE AUTO
Engine Capacity	1596	Year of Manufacture	2007
Fuel Type	PETROL	Date First Registered	09-May-07
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	09-May-07
Colour	BLUE	Year-Month 1st Registered	2007-05
CO2 Emissions	184 g/km	Transmission	AUTO 4 GEARS
Gear Count	4	Transmission Type	Automatic
Engine Number	7D78375	Transmission Code	A
Gross Weight	1755	Door Plan Code	14
Maximum Permissible Mass	1755	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	04-Oct-25 15:31:18		

General Information

Make	Ford	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	81
Valve Gear	DOHC	Location	FRONT
Description	DURA/1.6/16V/101BHP	Bore	79
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	C307	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	3	Keeper Data Count	2
Keeper 3 (Current Keeper)			26-Jun-25
Keeper 2			08-Jul-24
Keeper 1 (First Keeper)			09-May-07

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	27-Jun-25 29-Nov-24 28-May-12 09-May-07
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	198	Per Month	33
Standard Twelve Month	360	Per Month	30
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	184 g/km	VED Band	I
VED CO2 Band	I		

Performance Information

Torque FtLb	107.7	Power Rpm	6000
Torque Rpm	4000	Power Bhp	101
Torque Nm	145.9	Power Kw	75.3
CO2	***	NoiseLevel	***
Max Speed Mph	107	Particles	***
Max Speed Kph	172	Data Version Number	***
Acceleration Zero To 60Mph	13.6	Acceleration Mph	13.6
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	36.7	Combined Lkm	7.7
ExtraUrban Mpg	47.1	ExtraUrban Lkm	6
UrbanCold Mpg	26.7	UrbanCold Lkm	10.6

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	BLUE	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	BLUE		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1755	Height	1497
Gross Combined Weight	1755	Width	1840
Kerb Weight	1314	Car Length	4342
Unladen Weight	1314	Wheel Base	2640
Fuel Tank Capacity	55	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Ford	DVLA Make	FORD
SMMT Range	Focus	DVLA Model	FOCUS ZETEC CLIMATE AUTO
SMMT Trim	Focus Zetec Climate Auto	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Ford	Range	Focus
Model Variant	Focus Zetec Climate Auto	Fuel Type	Petrol
Nominal Engine Capacity	1.6	Transmission	Automatic
Engine Capacity	1596	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	4
DriveType	4x2	SysSetup Date	16-Mar-05
Country Of Origin	Spain	Visibility Date	16-Mar-05
Series	C307	Terminate Date	09-Feb-11
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

08-Jul-25	 PASS	92072 MI	642754540186
-----------	---	----------	--------------

Advisories

- ADVISORY** Front Exhaust mounting defective (6.1.2 (a))
- ADVISORY** Front Both front brake discs corroded

05-Jul-25	 FAIL	92068 MI	724869277723
-----------	---	----------	--------------

Advisories

- ADVISORY** Front Exhaust mounting defective (6.1.2 (a))
- ADVISORY** Front Both front brake discs corroded

Failures

- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

08-Jul-24	 PASS	91252 MI	210585903140
-----------	--	----------	--------------

28-Sep-23	 PASS	89006 MI	891569540298
-----------	---	----------	--------------

Advisories

- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing Deep cracks in tread (5.2.3 (d) (ii))

28-Sep-23	 FAIL	89006 MI	704616076173
-----------	---	----------	--------------

Advisories

- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing Deep cracks in tread (5.2.3 (d) (ii))

Failures

- MAJOR** Offside Headlamp aim too far to the left (4.1.2 (a))
- MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

06-Oct-22	 PASS	84939 MI	680663183573
-----------	---	----------	--------------

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing cracks in tread (5.2.3 (d) (ii))

06-Oct-22



FAIL

84939 MI

320202944666

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing cracks in tread (5.2.3 (d) (ii))
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing cracks in tread (5.2.3 (d) (ii))

Failures

- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))

04-Oct-21



PASS

79986 MI

749691549039

05-Oct-20



PASS

76534 MI

544563497249

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

05-Oct-20



FAIL

76534 MI

176396180993

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Failures

- PRS** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

07-May-19



PASS

72165 MI

744142435060

07-May-19



FAIL

72162 MI

457822603692

Failures

- MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

04-May-18	 PASS	67415 MI	855177521528
-----------	---	----------	--------------

04-May-18	 FAIL	67415 MI	814096992248
-----------	---	----------	--------------

Failures

PRS Offside Front Headlamp aim too high (1.8)

19-Apr-17	 PASS	62565 MI	929410222474
-----------	---	----------	--------------

Advisories

ADVISORY Rear registration plate delaminated but not likely to be misread (6.3.1d)

ADVISORY Nearside Rear coil spring corroded (2.4.C.1b)

ADVISORY Offside Rear coil spring corroded (2.4.C.1b)

ADVISORY Nearside Front tyre worn on outer edge

ADVISORY Offside Front tyre worn on outer edge

20-Apr-16	 PASS	58122 MI	685921639843
-----------	--	----------	--------------

01-May-15	 PASS	54559 MI	268721025117
-----------	---	----------	--------------

12-May-14	 PASS	50321 MI	998162234170
-----------	---	----------	--------------

02-May-13	 PASS	44744 MI	168202023189
-----------	---	----------	--------------

14-May-12	 PASS	36248 MI	858625132194
-----------	---	----------	--------------

17-May-11	 PASS	30818 MI	659477331155
-----------	---	----------	--------------

17-May-11	 FAIL	30818 MI	907467431153
-----------	---	----------	--------------

Advisories

- ADVISORY** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- ADVISORY** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- USER ENTERED** Nail in offside front tyre
- USER ENTERED** Child seat fitted not allowing full inspection of adult belt

Failures

- Failed** Offside Stop lamp not working (1.2.1b)
- Failed** Parking brake: efficiency below requirements (3.7.B.7)

27-Apr-10



PASS

24126 MI

232997510495

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.