

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	!	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✓	Keepers	5	Keeper	14-May-25 01-Mar-19 15-Feb-14 09-May-11 26-Jan-11

**Taxed**

Tax due: 01-May-27

Vehicle Make	MERCEDES-BENZ
Fuel Type	PETROL
Cylinder Capacity	1796
Vehicle Colour	WHITE
Euro Stats	***
Co2 Emissions	191 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

**MOT Status**

Expires 16-Mar-27

Year Of Manufacture	2011
Date Of First Registration	Jan-11
Date Of Last V5C (logbook) Issued	11-Jun-25
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	1945
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	17	! Pass Rate	76%
✓ Test Passed	13	! Pass Rate With Advisory	69%
! Passed With Advisory	9	✓ Pass Rate Without Advisory	31%
! Total Items Advised	19	✓ Mileage Issues	No
! Advisory Average/Per MOT	1.46	Last MOT Mileage	182225 MI
✗ Test Failed	4	Est Current Mileage	184958 MI
✗ Total Items Failed	12	Average Mileage	12148 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✗ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
17-Mar-26	✓ PASS	182225 MI	12771	425	Failures(0) Advisories(0)
14-May-25	! KEEPER 5				
16-Jan-25	✓ PASS	169454 MI	15850	346	Failures(0) Advisories(6)
05-Feb-24	✓ PASS	153604 MI	16413	363	Failures(0) Advisories(1)
07-Feb-23	✓ PASS	137191 MI	16057	336	Failures(0) Advisories(1)
08-Mar-22	✓ PASS	121134 MI	1	0	Failures(0) Advisories(2)
08-Mar-22	✗ FAIL	121133 MI	13360	374	Failures(3) Advisories(4)

27-Feb-21	 PASS	107773 MI	0	1	Failures(0) Advisories(1)
26-Feb-21	 FAIL	107773 MI	8202	359	Failures(1) Advisories(2)
04-Mar-20	 PASS	99571 MI	141	2	Failures(0) Advisories(3)
02-Mar-20	 FAIL	99430 MI	16935	404	Failures(4) Advisories(3)
01-Mar-19	 KEEPER 4				
01-Feb-19	 PLATE	 JO51GSY →  DA60JJY			
23-Jan-19	 PASS	82495 MI	12518	361	Failures(0) Advisories(1)
27-Jan-18	 PASS	69977 MI	11310	381	Failures(0) Advisories(1)
11-Jan-17	 PASS	58667 MI	0	0	Failures(0) Advisories(0)
11-Jan-17	 FAIL	58667 MI	11483	350	Failures(4) Advisories(2)
27-Jan-16	 PASS	47184 MI	12092	370	Failures(0) Advisories(0)
22-Jan-15	 PASS	35092 MI	12897	366	Failures(0) Advisories(0)
07-Apr-14	 PLATE	 DA60JJY →  JO51GSY			
15-Feb-14	 KEEPER 3				
30-Jan-14	 PLATE	 207ASV →  DA60JJY			
21-Jan-14	 PASS	22195 MI	0	0	Failures(0) Advisories(3)

17-May-11



PLATE



DA60JJY



207ASV

09-May-11



KEEPER 2

26-Jan-11



KEEPER 1

Mileage History

S No.	Date	Mileage	Difference	Days
17	17-Mar-26	182225 MI	12771 MI	425
Keeper	14-May-25			
16	16-Jan-25	169454 MI	15850 MI	346
15	05-Feb-24	153604 MI	16413 MI	363
14	07-Feb-23	137191 MI	16057 MI	336
13	08-Mar-22	121134 MI	1 MI	0
12	08-Mar-22	121133 MI	13360 MI	374
11	27-Feb-21	107773 MI	0	1
10	26-Feb-21	107773 MI	8202 MI	359
9	04-Mar-20	99571 MI	141 MI	2
8	02-Mar-20	99430 MI	16935 MI	404
Keeper	01-Mar-19			
Plate 4	01-Feb-19	JO51GSY		DA60JJY
7	23-Jan-19	82495 MI	12518 MI	361
6	27-Jan-18	69977 MI	11310 MI	381
5	11-Jan-17	58667 MI	0	0

4	11-Jan-17	58667 MI	11483 MI	350
3	27-Jan-16	47184 MI	12092 MI	370
2	22-Jan-15	35092 MI	12897 MI	366
Plate 3	07-Apr-14	 DA60JJY →  JO51GSY		
Keeper	15-Feb-14			
Plate 2	30-Jan-14	 207ASV →  DA60JJY		
1	21-Jan-14	22195 MI		0
Plate 1	17-May-11	 DA60JJY →  207ASV		
Keeper	09-May-11			
Keeper	26-Jan-11			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	DA60JJY	Make & Model	MERCEDES-BENZ CLC180 KOMP SPORT AUTO
Make	MERCEDES-BENZ	Model	CLC180 KOMP SPORT AUTO
Engine Capacity	1796	Year of Manufacture	2011
Fuel Type	PETROL	Date First Registered	26-Jan-11
Door Plan	COUPE	Date of 1st Registration in UK	26-Jan-11
Colour	WHITE	Year-Month 1st Registered	2011-01
CO2 Emissions	191 g/km	Transmission	AUTO 6 GEARS
Gear Count	6	Transmission Type	Automatic
Engine Number	27194631334614	Transmission Code	A
Gross Weight	1945	Door Plan Code	05
Maximum Permissible Mass	1945	MVRIS Model Code	***
Seating Capacity	4	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	08-Aug-25 00:59:56		

General Information

Make	Mercedes Cars	Euro Status	5a
Aspiration	Supercharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	85
Valve Gear	DOHC	Location	FRONT
Description	M271 E18ML RED E4	Bore	82
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	RWD	Primary Fuel Flag	Y
Series Description	CL203	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	5	Keeper Data Count	4
Keeper 5 (Current Keeper)			14-May-25
Keeper 4			01-Mar-19
Keeper 3			15-Feb-14
Keeper 2			09-May-11
Keeper 1 (First Keeper)			26-Jan-11

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	11-Jun-25 11-Mar-19 07-Apr-14 26-Jan-11
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	225.5	Per Month	37.58
Standard Twelve Month	410	Per Month	34.17
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	191 g/km	VED Band	J
VED CO2 Band	J		

Performance Information

Torque FtLb	162	Power Rpm	5200
Torque Rpm	2500	Power Bhp	143
Torque Nm	220	Power Kw	105
CO2	198	NoiseLevel	***
Max Speed Mph	137	Particles	***
Max Speed Kph	221	Data Version Number	***
Acceleration Zero To 60Mph	9.9	Acceleration Mph	9.9
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	34	Combined Lkm	8.3
ExtraUrban Mpg	44.1	ExtraUrban Lkm	6.4
UrbanCold Mpg	24.1	UrbanCold Lkm	11.7

! Plate Change History

Plate Change Count	4		
1	01-Feb-19	 JO51GSY	→  DA60JJY
2	07-Apr-14	 DA60JJY	→  JO51GSY
3	30-Jan-14	 207ASV	→  DA60JJY
4	17-May-11	 DA60JJY	→  207ASV

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	WHITE	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	WHITE		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	JO51GSY
---------------------------	-----	-----------------	---------

Dimensions

Gross Vehicle Weight	1945	Height	1405
Gross Combined Weight	1945	Width	2078
Kerb Weight	1495	Car Length	4448
Unladen Weight	1495	Wheel Base	2715
Fuel Tank Capacity	62	Pay Load Weight	***
Number Of Doors	3	Gross Train Weight	***
Number Of Seats	4	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Mercedes-Benz	DVLA Make	MERCEDES-BENZ
SMMT Range	CLC-Class	DVLA Model	CLC180 KOMP SPORT AUTO
SMMT Trim	CLC 180 Kompressor Sport Auto	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

SmmT Details

Marque	Mercedes-Benz	Range	CLC-Class
Model Variant	CLC 180 Kompressor Sport Auto	Fuel Type	Petrol
Nominal Engine Capacity	1.8	Transmission	Automatic
Engine Capacity	1796	Number Of Doors	3
Body Style	Coupe	Number Of Gears	6
DriveType	4x2	SysSetup Date	27-May-08
Country Of Origin	Brazil	Visibility Date	27-May-08
Series	CL203	Terminate Date	29-Dec-11
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

17-Mar-26



PASS

182225 MI

994476479810

16-Jan-25



PASS

169454 MI

732151567900

Advisories

- ADVISORY** Front Exhaust mounting defective (6.1.2 (a))
- ADVISORY** Play in steering rack inner joint(s)
- ADVISORY** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- ADVISORY** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- ADVISORY** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

05-Feb-24



PASS

153604 MI

443336323922

Advisories

ADVISORY Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

07-Feb-23



PASS

137191 MI

125833180234

Advisories

ADVISORY offside front tyre worn on edges

08-Mar-22



PASS

121134 MI

988814703758

Advisories

ADVISORY Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

ADVISORY parking brake effort just passed at 16%

08-Mar-22



FAIL

121133 MI

822424888211

Advisories

ADVISORY Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

ADVISORY Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

ADVISORY parking brake effort just passed at 16%

MINOR Offside Windscreen wiper blade defective (3.4 (b) (i))

Failures

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

27-Feb-21



PASS

107773 MI

861149920080

Advisories

MINOR Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

26-Feb-21



FAIL

107773 MI

229407372235

Advisories

ADVISORY Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MINOR Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Failures

MAJOR Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

04-Mar-20



PASS

99571 MI

485946139094

Advisories

- ADVISORY** Tyre worn close to legal limit/worn on edge both sides rear (5.2.3 (e))
- ADVISORY** Brake pipe corroded, covered in grease or other material both pipes n/s/r (1.1.11 (c))
- ADVISORY** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

02-Mar-20



FAIL

99430 MI

131748600824

Advisories

- ADVISORY** Tyre worn close to legal limit/worn on edge both sides rear (5.2.3 (e))
- ADVISORY** Brake pipe corroded, covered in grease or other material both pipes n/s/r (1.1.11 (c))
- ADVISORY** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Failures

- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Front Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Exhaust silencer insecure front mount (8.1.1 (b) (i))

23-Jan-19



PASS

82495 MI

834123606049

Advisories

- ADVISORY** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

27-Jan-18



PASS

69977 MI

500200044054

Advisories

- ADVISORY** Offside Rear Direction indicators has light sources not illuminating, but not more than 50% (1.4.A.2c)

11-Jan-17



PASS

58667 MI

280237079798

11-Jan-17



FAIL

58667 MI

558652191433

Advisories

- ADVISORY** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- ADVISORY** Offside Front Tyre worn close to the legal limit (4.1.E.1)

Failures

- Failed** Offside Headlamp aim too high (1.8)
- Failed** Nearside Headlamp aim too low and too far to the right. (1.8)
- Failed** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Failed** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

27-Jan-16



PASS

47184 MI

848605664072

22-Jan-15



PASS

35092 MI

789492025000

21-Jan-14



PASS

22195 MI

476141524013

Advisories

- ADVISORY** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- ADVISORY** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- USER ENTERED** Under-trays fitted obscuring some underside components

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.