

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	!	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✗	Keepers	5	Keeper	30-Dec-16 20-Apr-06

**Taxed**

Tax due: 01-Jan-27

Vehicle Make	HONDA
Fuel Type	PETROL
Cylinder Capacity	1339
Vehicle Colour	RED
Euro Stats	***
Co2 Emissions	139 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

**MOT Status**

Expires 04-Sep-26

Year Of Manufacture	2006
Date Of First Registration	Apr-06
Date Of Last V5C (logbook) Issued	08-Jun-17
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	***
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	24	! Pass Rate	70%
✓ Test Passed	17	! Pass Rate With Advisory	52%
! Passed With Advisory	9	✓ Pass Rate Without Advisory	48%
! Total Items Advised	18	✓ Mileage Issues	No
! Advisory Average/Per MOT	1.06	Last MOT Mileage	116896 MI
✗ Test Failed	7	Est Current Mileage	117959 MI
✗ Total Items Failed	13	Average Mileage	6152 Miles/Year
✓ Taxi/Rent a Car Use	Might not	icon Mileage Status	Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
23-Aug-25	✓ PASS	116896 MI	0	0	Failures(0) Advisories(1)
23-Aug-25	✗ FAIL	116896 MI	1347	357	Failures(0) Advisories(1)
31-Aug-24	✓ PASS	115549 MI	0	0	Failures(0) Advisories(0)
31-Aug-24	✗ FAIL	115549 MI	1411	374	Failures(0) Advisories(0)
23-Aug-23	✓ PASS	114138 MI	0	0	Failures(0) Advisories(0)
23-Aug-23	✗ FAIL	114138 MI	1358	356	Failures(0) Advisories(0)
01-Sep-22	✓ PASS	112780 MI	0	0	Failures(0) Advisories(1)

01-Sep-22	 FAIL	112780 MI	1772	369	Failures(0) Advisories(1)
28-Aug-21	 PASS	111008 MI	1765	357	Failures(0) Advisories(0)
05-Sep-20	 PASS	109243 MI	0	0	Failures(0) Advisories(0)
05-Sep-20	 FAIL	109243 MI	1979	477	Failures(0) Advisories(0)
17-May-19	 PASS	107264 MI	1882	351	Failures(0) Advisories(2)
31-May-18	 PASS	105382 MI	2819	390	Failures(0) Advisories(0)
06-May-17	 PASS	102563 MI	3380	339	Failures(0) Advisories(0)
30-Dec-16	 KEEPER 5				
01-Jun-16	 PASS	99183 MI	0	1	Failures(0) Advisories(3)
31-May-16	 FAIL	99183 MI	14773	371	Failures(2) Advisories(3)
26-May-15	 PASS	84410 MI	0	0	Failures(0) Advisories(1)
26-May-15	 FAIL	84410 MI	9159	364	Failures(3) Advisories(1)
24-Jul-14	 PLATE	 K2TMY →  DE06MGO			
27-May-14	 PASS	75251 MI	7687	300	Failures(0) Advisories(2)
31-Jul-13	 PASS	67564 MI	16544	418	Failures(0) Advisories(3)
08-Jun-12	 PASS	51020 MI	19587	368	Failures(0) Advisories(1)

06-Jun-11	 PASS	31433 MI	11958	364	Failures(0) Advisories(4)
07-Jun-10	 PASS	19475 MI	5450	380	Failures(0) Advisories(0)
23-May-09	 PASS	14025 MI	0	0	Failures(0) Advisories(0)
20-Apr-06	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
24	23-Aug-25	116896 MI	0	0
23	23-Aug-25	116896 MI	1347 MI	357
22	31-Aug-24	115549 MI	0	0
21	31-Aug-24	115549 MI	1411 MI	374
20	23-Aug-23	114138 MI	0	0
19	23-Aug-23	114138 MI	1358 MI	356
18	01-Sep-22	112780 MI	0	0
17	01-Sep-22	112780 MI	1772 MI	369
16	28-Aug-21	111008 MI	1765 MI	357
15	05-Sep-20	109243 MI	0	0
14	05-Sep-20	109243 MI	1979 MI	477
13	17-May-19	107264 MI	1882 MI	351
12	31-May-18	105382 MI	2819 MI	390
11	06-May-17	102563 MI	3380 MI	339

Keeper		30-Dec-16		
10	01-Jun-16	99183 MI	0	1
9	31-May-16	99183 MI	14773 MI	371
8	26-May-15	84410 MI	0	0
7	26-May-15	84410 MI	9159 MI	364
Plate 1 24-Jul-14 GB K2TMY → GB DE06MGO				
6	27-May-14	75251 MI	7687 MI	300
5	31-Jul-13	67564 MI	16544 MI	418
4	08-Jun-12	51020 MI	19587 MI	368
3	06-Jun-11	31433 MI	11958 MI	364
2	07-Jun-10	19475 MI	5450 MI	380
1	23-May-09	14025 MI		0
Keeper		20-Apr-06		

Km / Mileage
Mileage Reverse
Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	DE06MGO	Make & Model	HONDA JAZZ SE CVT
Make	HONDA	Model	JAZZ SE CVT
Engine Capacity	1339	Year of Manufacture	2006
Fuel Type	PETROL	Date First Registered	20-Apr-06
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	20-Apr-06
Colour	RED	Year-Month 1st Registered	2006-04
CO2 Emissions	139 g/km	Transmission	AUTO VARIABLE 1 GEAR
Gear Count	1	Transmission Type	Automatic
Engine Number	L13A15011606	Transmission Code	A
Gross Weight	1510	Door Plan Code	14
Maximum Permissible Mass	1510	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	09-May-24 01:23:11		

General Information

Make	Honda Cars	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	2	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	80
Valve Gear	SOHC	Location	FRONT
Description	L13A1	Bore	73
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	GD/GE	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	5	Keeper Data Count	1
Keeper 5 (Current Keeper)	30-Dec-16		
Keeper 1 (First Keeper)	20-Apr-06		

V5C Certificate issue details

V5C Certificate Count	1	Certificate Dates	08-Jun-17
-----------------------	---	-------------------	-----------

Vehicle Tax & CO2 Emissions

Standard Six Month	110	Per Month	18.33
Standard Twelve Month	200	Per Month	16.67
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	139 g/km	VED Band	E
VED CO2 Band	E		

Performance Information

Torque FtLb	87.8	Power Rpm	5700
Torque Rpm	2800	Power Bhp	81.8
Torque Nm	119	Power Kw	61
CO2	***	NoiseLevel	***
Max Speed Mph	99	Particles	***
Max Speed Kph	160	Data Version Number	***
Acceleration Zero To 60Mph	14.5	Acceleration Mph	14.5
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	47.9	Combined Lkm	5.9
ExtraUrban Mpg	55.4	ExtraUrban Lkm	5.1
UrbanCold Mpg	39.2	UrbanCold Lkm	7.2

! Plate Change History

Plate Change Count	1
--------------------	---

1	24-Jul-14
---	-----------

 K2TMY



 DE06MGO

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	RED	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	RED		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	K2TMY
---------------------------	-----	-----------------	-------

Dimensions

Gross Vehicle Weight	1510	Height	1525
Gross Combined Weight	1510	Width	1675
Kerb Weight	1066	Car Length	3845
Unladen Weight	1066	Wheel Base	2450
Fuel Tank Capacity	42	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Honda	DVLA Make	HONDA
SMMT Range	Jazz	DVLA Model	JAZZ SE CVT
SMMT Trim	Jazz SE CVT	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Honda	Range	Jazz
Model Variant	Jazz SE CVT	Fuel Type	Petrol
Nominal Engine Capacity	1.3	Transmission	CVT
Engine Capacity	1339	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	1
DriveType	4x2	SysSetup Date	08-Feb-06
Country Of Origin	Japan	Visibility Date	08-Feb-06
Series	GD/GE	Terminate Date	01-Jul-19
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

23-Aug-25



PASS

116896 MI

673131193101

Advisories

ADVISORY nearside front wing dented with no sharp egde

23-Aug-25



FAIL

116896 MI

338083358883

Advisories

ADVISORY nearside front wing dented with no sharp egde

Failures

PRS Windscreen washer provides insufficient washer liquid (3.5 (a))

31-Aug-24



PASS

115549 MI

481739497035

31-Aug-24



FAIL

115549 MI

346002424443

Failures

PRS Nearside Front Body insecure to the extent that stability is seriously impaired wing (6.2.2 (a) (ii))

PRS Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))

PRS Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))

23-Aug-23



PASS

114138 MI

676590268209

23-Aug-23



FAIL

114138 MI

194732274386

Failures

PRS Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

01-Sep-22



PASS

112780 MI

456697650925

Advisories

ADVISORY Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

01-Sep-22



FAIL

112780 MI

166313639235

Advisories

ADVISORY Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Failures

PRS Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

28-Aug-21



PASS

111008 MI

139507265037

05-Sep-20



PASS

109243 MI

956718037046

05-Sep-20



FAIL

109243 MI

310783213596

Failures

PRS Nearside Headlamp aim too high (4.1.2 (a))

PRS Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

17-May-19



PASS

107264 MI

556240930684

Advisories

- ADVISORY** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

31-May-18



PASS

105382 MI

919445235769

06-May-17



PASS

102563 MI

760625757937

01-Jun-16



PASS

99183 MI

946125803581

Advisories

- ADVISORY** Nearside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

31-May-16



FAIL

99183 MI

154054005800

Advisories

- ADVISORY** Nearside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)
- ADVISORY** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Failures

- Failed** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Failed** Exhaust has a major leak of exhaust gases centre box (7.1.2)

26-May-15



PASS

84410 MI

707446445146

Advisories

- ADVISORY** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

26-May-15



FAIL

84410 MI

635926045192

Advisories

- ADVISORY** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Failures

- Failed** Nearside Rear Stop lamp not working (1.2.1b)
- Failed** Centre Rear Stop lamp not working (1.2.1b)
- Failed** Offside Front Headlamp aim too low (1.8)

27-May-14



PASS

75251 MI

415987644147

Advisories

ADVISORY Offside Front Tyre worn close to the legal limit (4.1.E.1)

ADVISORY Rear Tyre worn close to the legal limit (4.1.E.1)

31-Jul-13



PASS

67564 MI

525872313219

Advisories

ADVISORY Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

USER ENTERED anti-slip provision slightly worn

USER ENTERED Offside Rear bumper slightly damaged

08-Jun-12



PASS

51020 MI

945380762172

Advisories

ADVISORY Rear Brake pad(s) wearing thin (3.5.1g)

06-Jun-11



PASS

31433 MI

226677451152

Advisories

ADVISORY Steering system has slight free play detected at steering wheel (2.2.A.1b)

ADVISORY Nearside Front Brake pad(s) wearing thin (3.5.1g)

ADVISORY Offside Front Brake pad(s) wearing thin (3.5.1g)

USER ENTERED front and rear brake disc slightly worn.

07-Jun-10



PASS

19475 MI

971468150108

23-May-09



PASS

14025 MI

123773749135

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.