

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✓	Keepers	4	Keeper	23-Dec-25 10-Apr-19 31-Jan-13 29-Oct-12

**Taxed**

Tax due: 01-Dec-26

Vehicle Make	HYUNDAI
Fuel Type	DIESEL
Cylinder Capacity	2199
Vehicle Colour	BLUE
Euro Stats	***
Co2 Emissions	197 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

**MOT Status**

Expires 16-Nov-26

Year Of Manufacture	2012
Date Of First Registration	Oct-12
Date Of Last V5C (logbook) Issued	27-Dec-25
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	1972
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	17	✗ Pass Rate	64%
✓ Test Passed	11	! Pass Rate With Advisory	72%
! Passed With Advisory	8	✓ Pass Rate Without Advisory	28%
! Total Items Advised	21	✓ Mileage Issues	No
! Advisory Average/Per MOT	1.91	Last MOT Mileage	116210 MI
✗ Test Failed	6	Est Current Mileage	121415 MI
✗ Total Items Failed	11	Average Mileage	8939 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✗ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
23-Dec-25	! KEEPER 4				
17-Nov-25	✓ PASS	116210 MI	6192	245	Failures(0) Advisories(1)
17-Mar-25	✓ PASS	110018 MI	10010	371	Failures(0) Advisories(3)
11-Mar-24	✓ PASS	100008 MI	0	0	Failures(0) Advisories(3)
11-Mar-24	✗ FAIL	100008 MI	10927	375	Failures(0) Advisories(3)
02-Mar-23	✓ PASS	89081 MI	7822	352	Failures(0) Advisories(2)
15-Mar-22	✓ PASS	81259 MI	72	4	Failures(0) Advisories(5)

11-Mar-22	 FAIL	81187 MI	6942	361	Failures(3) Advisories(4)
15-Mar-21	 PASS	74245 MI	0	4	Failures(0) Advisories(3)
11-Mar-21	 FAIL	74245 MI	5545	376	Failures(2) Advisories(3)
29-Feb-20	 PASS	68700 MI	5	2	Failures(0) Advisories(3)
27-Feb-20	 FAIL	68695 MI	10806	525	Failures(1) Advisories(3)
10-Apr-19	 KEEPER 3				
20-Sep-18	 PASS	57889 MI	0	0	Failures(0) Advisories(0)
20-Sep-18	 FAIL	57889 MI	12488	369	Failures(2) Advisories(0)
16-Sep-17	 PASS	45401 MI	52	2	Failures(0) Advisories(1)
14-Sep-17	 FAIL	45349 MI	9371	353	Failures(1) Advisories(1)
26-Sep-16	 PASS	35978 MI	9744	361	Failures(0) Advisories(0)
01-Oct-15	 PASS	26234 MI	0	0	Failures(0) Advisories(0)
31-Jan-13	 KEEPER 2				
29-Oct-12	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
-------	------	---------	------------	------

Keeper	23-Dec-25			
--------	-----------	--	--	--

17	17-Nov-25	116210 MI	6192 MI	245
16	17-Mar-25	110018 MI	10010 MI	371
15	11-Mar-24	100008 MI	0	0
14	11-Mar-24	100008 MI	10927 MI	375
13	02-Mar-23	89081 MI	7822 MI	352
12	15-Mar-22	81259 MI	72 MI	4
11	11-Mar-22	81187 MI	6942 MI	361
10	15-Mar-21	74245 MI	0	4
9	11-Mar-21	74245 MI	5545 MI	376
8	29-Feb-20	68700 MI	5 MI	2
7	27-Feb-20	68695 MI	10806 MI	525
Keeper	10-Apr-19			
6	20-Sep-18	57889 MI	0	0
5	20-Sep-18	57889 MI	12488 MI	369
4	16-Sep-17	45401 MI	52 MI	2
3	14-Sep-17	45349 MI	9371 MI	353
2	26-Sep-16	35978 MI	9744 MI	361
1	01-Oct-15	26234 MI		0
Keeper	31-Jan-13			
Keeper	29-Oct-12			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	EA62WKE	Make & Model	HYUNDAI SANTA FE PREMIUM CRDI A
Make	HYUNDAI	Model	SANTA FE PREMIUM CRDI A
Engine Capacity	2199	Year of Manufacture	2012
Fuel Type	DIESEL	Date First Registered	29-Oct-12
Door Plan	ESTATE	Date of 1st Registration in UK	29-Oct-12
Colour	BLUE	Year-Month 1st Registered	2012-10
CO2 Emissions	197 g/km	Transmission	AUTO 6 GEARS
Gear Count	6	Transmission Type	Automatic
Engine Number	D4HBCU614831	Transmission Code	A
Gross Weight	1972	Door Plan Code	06
Maximum Permissible Mass	4570	MVRIS Model Code	***
Seating Capacity	7	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	04-Feb-26 04:51:26		

General Information

Make	Hyundai	Euro Status	5b
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	Common Rail Direct injection
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	96
Valve Gear	DOHC	Location	FRONT
Description	D4HB-A	Bore	85
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	4x4	Primary Fuel Flag	Y
Series Description	CM	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	4	Keeper Data Count	3
Keeper 4 (Current Keeper)			23-Dec-25
Keeper 3			10-Apr-19
Keeper 2			31-Jan-13
Keeper 1 (First Keeper)			29-Oct-12

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	27-Dec-25 20-Mar-25 08-Feb-13 29-Oct-12
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	225.5	Per Month	37.58
Standard Twelve Month	410	Per Month	34.17
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	197 g/km	VED Band	J
VED CO2 Band	J		

Performance Information

Torque FtLb	322	Power Rpm	3800
Torque Rpm	2500	Power Bhp	194
Torque Nm	436	Power Kw	145
CO2	197	NoiseLevel	***
Max Speed Mph	118	Particles	***
Max Speed Kph	190	Data Version Number	***
Acceleration Zero To 60Mph	9.8	Acceleration Mph	9.8
Acceleration Zero To 100Kph	10.2	Acceleration Kph	10.2

Consumption

Combined Mpg	38.2	Combined Lkm	7.4
ExtraUrban Mpg	44.8	ExtraUrban Lkm	6.3
UrbanCold Mpg	30.4	UrbanCold Lkm	9.3

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	BLUE	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	BLUE		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	2570	Height	1760
Gross Combined Weight	4570	Width	1890
Kerb Weight	1987	Car Length	4685
Unladen Weight	1987	Wheel Base	2700
Fuel Tank Capacity	70	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	4570
Number Of Seats	7	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Hyundai	DVLA Make	HYUNDAI
SMMT Range	Santa Fe	DVLA Model	SANTA FE PREMIUM CRDI A
SMMT Trim	Santa Fe Premium CRDi Auto	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Hyundai	Range	Santa Fe
Model Variant	Santa Fe Premium CRDi Auto	Fuel Type	Diesel
Nominal Engine Capacity	2.2	Transmission	Automatic
Engine Capacity	2199	Number Of Doors	5
Body Style	SUV	Number Of Gears	6
DriveType	4x4	SysSetup Date	05-Sep-11
Country Of Origin	South Korea	Visibility Date	05-Sep-11
Series	CM	Terminate Date	29-Jan-13
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

17-Nov-25	 PASS	116210 MI	394175957936
-----------	---	-----------	--------------

Advisories

ADVISORY undertrays fitted

17-Mar-25	 PASS	110018 MI	905667388918
-----------	---	-----------	--------------

Advisories

ADVISORY Offside Front Play in steering rack inner joint(s)

ADVISORY Parking brake only just met requirements.

MINOR Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

11-Mar-24	 PASS	100008 MI	967738149132
-----------	---	-----------	--------------

Advisories

ADVISORY Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

ADVISORY Front Tyre worn close to legal limit/worn on edge Both On Edges (5.2.3 (e))

ADVISORY Rear Tyres Slightly Out Of Shape

11-Mar-24	 FAIL	100008 MI	247144927433
-----------	---	-----------	--------------

Advisories

ADVISORY Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

ADVISORY Front Tyre worn close to legal limit/worn on edge Both On Edges (5.2.3 (e))

ADVISORY Rear Tyres Slightly Out Of Shape

Failures

PRS Offside Front Position lamp not working (4.2.1 (a) (ii))

02-Mar-23	 PASS	89081 MI	911446912238
-----------	---	----------	--------------

Advisories

ADVISORY Passenger seat(s) missing at time of test 3rd Row

ADVISORY Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

15-Mar-22	 PASS	81259 MI	506832248239
-----------	---	----------	--------------

Advisories

- ADVISORY** All direction indicators slightly discoloured All indicators light in colour (4.4.3 (a))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner and outer edges (5.2.3 (e))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Passenger seat(s) missing at time of test 3rd row seating not in place
- ADVISORY** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

11-Mar-22



FAIL

81187 MI

978480284521

Advisories

- ADVISORY** All direction indicators slightly discoloured All indicators light in colour (4.4.3 (a))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner and outer edges (5.2.3 (e))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Passenger seat(s) missing at time of test 3rd row seating not in place

Failures

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- MAJOR** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

15-Mar-21



PASS

74245 MI

900144902322

Advisories

- ADVISORY** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- ADVISORY** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- MINOR** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated Perished and weeping grease (6.1.7 (g) (i))

11-Mar-21



FAIL

74245 MI

405726486637

Advisories

- ADVISORY** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- ADVISORY** Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt
- MINOR** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated Perished and weeping grease (6.1.7 (g) (i))

Failures

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Nearside Side repeater missing (4.4.1 (a) (ii))

29-Feb-20



PASS

68700 MI

912288847142

Advisories

- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Outer Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

27-Feb-20



FAIL

68695 MI

586908649508

Advisories

ADVISORY Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

ADVISORY Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

ADVISORY Nearside Front Outer Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))

Failures

MAJOR Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

PRS Offside Front Headlamp aim projected beam image is obviously incorrect bulb was incorrectly fitted (4.1.2 (c))

20-Sep-18



PASS

57889 MI

774771546581

20-Sep-18



FAIL

57889 MI

632333886132

Failures

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick both sides of vehicle (1.1.13 (a) (ii))

MAJOR Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

16-Sep-17



PASS

45401 MI

499933335309

Advisories

ADVISORY Rear Brake pad(s) wearing thin (3.5.1g)

14-Sep-17



FAIL

45349 MI

888697599892

Advisories

ADVISORY Rear Brake pad(s) wearing thin (3.5.1g)

Failures

Failed Offside Side repeater not working (1.4.A.2c)

26-Sep-16



PASS

35978 MI

502805173090

01-Oct-15



PASS

26234 MI

877533831755

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.