

YOUR VEHICLE DATA

Scrapped 	Exported 	Imported 	Plate Change 	Colour Change 
Mileage 	Taxi 	Recall 	Keepers 4	Keeper 03-Dec-25 17-Aug-17 24-Jun-05



Taxed

Tax due: 01-Jan-27

Vehicle Make	CHRYSLER
Fuel Type	DIESEL
Cylinder Capacity	2776
Vehicle Colour	BLACK
Euro Stats	***
Co2 Emissions	225 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL



MOT Status

Expires 24-Jun-26

Year Of Manufacture	2005
Date Of First Registration	Jun-05
Date Of Last V5C (logbook) Issued	03-Dec-25
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	2225
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	23	✗ Pass Rate	60%
✓ Test Passed	14	! Pass Rate With Advisory	78%
! Passed With Advisory	11	✓ Pass Rate Without Advisory	22%
! Total Items Advised	34	✓ Mileage Issues	No
! Advisory Average/Per MOT	2.43	Last MOT Mileage	116929 MI
✗ Test Failed	9	Est Current Mileage	124707 MI
✗ Total Items Failed	33	Average Mileage	5846 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✓ Mileage Status	Below Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
03-Dec-25	! KEEPER 4				
25-Jun-25	✓ PASS	116929 MI	7908	369	Failures(0) Advisories(7)
21-Jun-24	✓ PASS	109021 MI	15	3	Failures(0) Advisories(7)
18-Jun-24	✗ FAIL	109006 MI	24	677	Failures(1) Advisories(9)
11-Aug-22	✗ FAIL	108982 MI	7218	1102	Failures(6) Advisories(7)
05-Aug-19	✓ PASS	101764 MI	28	3	Failures(0) Advisories(5)
02-Aug-19	✗ FAIL	101736 MI	6563	371	Failures(1) Advisories(5)

27-Jul-18	 PASS	95173 MI	8173	451	Failures(0) Advisories(3)
17-Aug-17	 KEEPER 3				
02-May-17	 PASS	87000 MI	0	0	Failures(0) Advisories(1)
02-May-17	 FAIL	87000 MI	4881	372	Failures(0) Advisories(1)
31-May-16	 PLATE	 N90LAG →  KH05ENF			
25-Apr-16	 PASS	82119 MI	12696	360	Failures(0) Advisories(2)
01-May-15	 PASS	69423 MI	44	1	Failures(0) Advisories(2)
30-Apr-15	 FAIL	69379 MI	18216	365	Failures(2) Advisories(3)
30-Apr-14	 PASS	51163 MI	2740	222	Failures(0) Advisories(3)
20-Sep-13	 PASS	48423 MI	194	16	Failures(0) Advisories(2)
04-Sep-13	 FAIL	48229 MI	6864	363	Failures(6) Advisories(1)
06-Sep-12	 PASS	41365 MI	114	6	Failures(0) Advisories(1)
31-Aug-12	 FAIL	41251 MI	7452	365	Failures(1) Advisories(1)
01-Sep-11	 PASS	33799 MI	8	1	Failures(0) Advisories(1)
31-Aug-11	 FAIL	33791 MI	6842	386	Failures(2) Advisories(1)
10-Aug-10	 PASS	26949 MI	7080	358	Failures(0) Advisories(0)

17-Aug-09	 PASS	19869 MI	6153	438	Failures(0) Advisories(0)
05-Jun-08	 PASS	13716 MI	0	3	Failures(0) Advisories(0)
02-Jun-08	 FAIL	13716 MI	0	0	Failures(7) Advisories(2)
24-Jun-05	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
Keeper 03-Dec-25				
23	25-Jun-25	116929 MI	7908 MI	369
22	21-Jun-24	109021 MI	15 MI	3
21	18-Jun-24	109006 MI	24 MI	677
20	11-Aug-22	108982 MI	7218 MI	1102
19	05-Aug-19	101764 MI	28 MI	3
18	02-Aug-19	101736 MI	6563 MI	371
17	27-Jul-18	95173 MI	8173 MI	451
Keeper 17-Aug-17				
16	02-May-17	87000 MI	0	0
15	02-May-17	87000 MI	4881 MI	372
Plate 1 31-May-16		 N90LAG →  KH05ENF		
14	25-Apr-16	82119 MI	12696 MI	360
13	01-May-15	69423 MI	44 MI	1

12	30-Apr-15	69379 MI	18216 MI	365
11	30-Apr-14	51163 MI	2740 MI	222
10	20-Sep-13	48423 MI	194 MI	16
9	04-Sep-13	48229 MI	6864 MI	363
8	06-Sep-12	41365 MI	114 MI	6
7	31-Aug-12	41251 MI	7452 MI	365
6	01-Sep-11	33799 MI	8 MI	1
5	31-Aug-11	33791 MI	6842 MI	386
4	10-Aug-10	26949 MI	7080 MI	358
3	17-Aug-09	19869 MI	6153 MI	438
2	05-Jun-08	13716 MI	0	3
1	02-Jun-08	13716 MI		0
Keeper	24-Jun-05			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	KH05ENF	Make & Model	CHRYSLER GRAND VOYAGER LTD AUTO
Make	CHRYSLER	Model	GRAND VOYAGER LTD AUTO
Engine Capacity	2776	Year of Manufacture	2005
Fuel Type	DIESEL	Date First Registered	24-Jun-05
Door Plan	ESTATE	Date of 1st Registration in UK	24-Jun-05
Colour	BLACK	Year-Month 1st Registered	2005-06
CO2 Emissions	225 g/km	Transmission	AUTO 4 GEARS
Gear Count	4	Transmission Type	Automatic
Engine Number	DIESEL	Transmission Code	A
Gross Weight	2225	Door Plan Code	06
Maximum Permissible Mass	2680	MVRIS Model Code	***
Seating Capacity	7	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	03-Feb-26 23:03:10		

General Information

Make	Chrysler Jeep	Euro Status	3
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	100
Valve Gear	DOHC	Location	FRONT
Description	2.8I CRD/150BHP	Bore	94
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	RG	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	4	Keeper Data Count	2
Keeper 4 (Current Keeper)			03-Dec-25
Keeper 3			17-Aug-17
Keeper 1 (First Keeper)			24-Jun-05

V5C Certificate issue details

V5C Certificate Count	2	Certificate Dates	03-Dec-25 13-Sep-17
-----------------------	---	-------------------	------------------------

Vehicle Tax & CO2 Emissions

Standard Six Month	244.75	Per Month	40.79
Standard Twelve Month	445	Per Month	37.08
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	225 g/km	VED Band	K
VED CO2 Band	K		

Performance Information

Torque FtLb	265	Power Rpm	3800
Torque Rpm	2100	Power Bhp	150
Torque Nm	359.1	Power Kw	111.9
CO2	***	NoiseLevel	***
Max Speed Mph	112	Particles	***
Max Speed Kph	180	Data Version Number	***
Acceleration Zero To 60Mph	12	Acceleration Mph	12
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	28.8	Combined Lkm	9.8
ExtraUrban Mpg	32.5	ExtraUrban Lkm	8.7
UrbanCold Mpg	24.6	UrbanCold Lkm	11.5

! Plate Change History

Plate Change Count

1

1

31-May-16

 N90LAG



 KH05ENF

✓ Import/Export

Exported

No

Export Date

Imported

No

✓ Scrap Destructions

Scrapped

No

Date of Scrapped

Certificate of Destruction Issued

No

Vehicle ID Check Count

0

✓ Colour Changes

Current Colour

BLACK

Number Of Previous Colours

0

Last Colour

Date Of Last Colour Change

Original Colour

BLACK

✓ Previous VRM

Previous Northern Ireland

Previous UK VRM

N90LAG

Dimensions

Gross Vehicle Weight

2680

Height

1749

Gross Combined Weight

2680

Width

1997

Kerb Weight

2150

Car Length

5096

Unladen Weight

2150

Wheel Base

3030

Fuel Tank Capacity

75

Pay Load Weight

Number Of Doors

5

Gross Train Weight

Number Of Seats

7

Payload Volume

Rigid Artic

RIGID

Load Length

Number Of Axles

2

Data Version Number

Body Shape

NA

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Chrysler	DVLA Make	CHRYSLER
SMMT Range	Voyager	DVLA Model	GRAND VOYAGER LTD AUTO
SMMT Trim	Grand Voyager Limited Auto	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Chrysler	Range	Voyager
Model Variant	Grand Voyager Limited Auto	Fuel Type	Diesel
Nominal Engine Capacity	2.8	Transmission	Automatic
Engine Capacity	2776	Number Of Doors	5
Body Style	MPV	Number Of Gears	4
DriveType	4x2	SysSetup Date	23-Apr-04
Country Of Origin	Austria	Visibility Date	23-Apr-04
Series	RG	Terminate Date	05-May-08
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		



MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

25-Jun-25



PASS

116929 MI

401485019727

Advisories

- ADVISORY** Nearside Front Play in steering rack inner joint(s)
- ADVISORY** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- ADVISORY** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Rear Leaf spring has slight wear in an anchor pin and/or bush front bush perishing (5.3.4 (a) (i))
- ADVISORY** Offside Rear Leaf spring has slight wear in an anchor pin and/or bush front bush perishing (5.3.4 (a) (i))

21-Jun-24



PASS

109021 MI

890609080675

Advisories

- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** steering slightly notchy
- ADVISORY** Nearside Play in steering rack inner joint(s)
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- ADVISORY** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- ADVISORY** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

18-Jun-24



FAIL

109006 MI

240473234229

Advisories

- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** steering slightly notchy
- ADVISORY** Nearside Play in steering rack inner joint(s)
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- ADVISORY** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- ADVISORY** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Failures

- MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

11-Aug-22



FAIL

108982 MI

223328000293

Advisories

- ADVISORY** nearside front top mount bearing slightly rough
- ADVISORY** offside front tyre perishing in tread in places and wearing low
- ADVISORY** nearside and offside front shock absorber lower spring cups are corroded
- ADVISORY** rear end of offside outer sill corroded
- ADVISORY** front brake pads worn very low
- ADVISORY** front brake disk inner faces in very poor condition
- MINOR** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Failures

- DANGEROUS** Offside Rear Tyre has ply or cords exposed tyre perished /cracked exposing cords in places (5.2.3 (d) (ii))
- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- MAJOR** Rear Seat belt buckle not functioning as intended 3rd row centre seat belt has lower mounting point missing /cut off (7.1.2 (d))
- MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill area (5.3.6 (a) (i))
- MAJOR** Offside Front Steering system excessively rough top mount bearing rough (2.1.1 (a))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn arm rear bush split/separated (5.3.4 (a) (i))

05-Aug-19



PASS

101764 MI

160730818114

Advisories

- ADVISORY** Nearside Rear Tyre worn close to legal limit/worn on edge tyre worn smooth on the shoulder areas (5.2.3 (e))
- ADVISORY** Corrosion to the offside outer sill area
- ADVISORY** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- ADVISORY** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

02-Aug-19



FAIL

101736 MI

478347137541

Advisories

- ADVISORY** Nearside Rear Tyre worn close to legal limit/worn on edge tyre worn smooth on the shoulder areas (5.2.3 (e))
- ADVISORY** Corrosion to the offside outer sill area
- ADVISORY** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- ADVISORY** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Failures

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

27-Jul-18



PASS

95173 MI

696230213963

Advisories

- ADVISORY** Corrosion to the offside outer sill in places
- ADVISORY** Front brake discs are corroded
- ADVISORY** Parking brake only just met the minimum performance readings

02-May-17



PASS

87000 MI

369020331546

Advisories

ADVISORY Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)

02-May-17



FAIL

87000 MI

986485383390

Advisories

ADVISORY Front brake disc worn, pitted or scored, but not seriously weakened nearside and offside (3.5.1i)

Failures

PRS Nearside Registration plate lamp not working (1.1.C.1d)

25-Apr-16



PASS

82119 MI

900767284155

Advisories

ADVISORY Front Brake pad(s) wearing thin (3.5.1g)

ADVISORY Rear seats removed from vehicle

01-May-15



PASS

69423 MI

765611325178

Advisories

USER ENTERED Play in steering rack inner joint(s)

USER ENTERED Coolant leak

30-Apr-15



FAIL

69379 MI

428670725102

Advisories

USER ENTERED Play in steering rack inner joint(s)

USER ENTERED Passenger seat(s) missing at time of test

USER ENTERED Coolant leak

Failures

Failed Parking brake lever has no reserve travel (3.1.6b)

Failed Parking brake: efficiency below requirements (3.7.B.7)

30-Apr-14



PASS

51163 MI

119260424135

Advisories

USER ENTERED Under-trays fitted obscuring some underside components

USER ENTERED Engine covers fitted obscuring some components in the engine bay

USER ENTERED Front wiper blades starting to deteriorate.

20-Sep-13



PASS

48423 MI

985553963261

Advisories

ADVISORY Offside rear brake fluctuating, but not excessively (3.7.B.3)

USER ENTERED low effort n/s handbrake

04-Sep-13



FAIL

48229 MI

586247243272

Advisories

USER ENTERED very low effort from n/s handbrake

Failures

Failed Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Failed Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

Failed Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Failed Nearside Headlamp not working on dipped beam (1.7.5a)

Failed Nearside Headlamp aim not tested (1.8.A.1c)

Failed Centre Stop lamp not working (1.2.1b)

06-Sep-12



PASS

41365 MI

786200652222

Advisories

USER ENTERED front brake pads and discs are very worn

31-Aug-12



FAIL

41251 MI

336394142452

Advisories

USER ENTERED front brake pads and discs are very worn

Failures

Failed Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

01-Sep-11



PASS

33799 MI

389294341485

Advisories

USER ENTERED n/s mirror is missing

31-Aug-11



FAIL

33791 MI

397053641422

Advisories

USER ENTERED n/s mirror is missing

Failures

Failed Nearside rear parking brake recording little or no effort (3.7.B.6a)

Failed Parking brake: efficiency below requirements (3.7.B.7)

10-Aug-10	 PASS	26949 MI	690472320214
17-Aug-09	 PASS	19869 MI	230349729203
05-Jun-08	 PASS	13716 MI	240897958167
02-Jun-08	 FAIL	13716 MI	480774858186

Advisories

- ADVISORY** Nearside Front brake disc slightly scored (3.5.1h)
- ADVISORY** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Failures

- Failed** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Failed** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Failed** Front Power steering component(s) leaking (2.3.3b)
- Failed** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Failed** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Failed** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Failed** Brakes imbalanced across an axle (3.7.B.5b)

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.