

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	!	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✓	Keepers	4	Keeper	12-Sep-20 28-Feb-17 01-Feb-13 02-Sep-11

**Taxed**

Tax due: 01-Jun-27

Vehicle Make	MERCEDES-BENZ
Fuel Type	DIESEL
Cylinder Capacity	2987
Vehicle Colour	SILVER
Euro Stats	***
Co2 Emissions	240 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

**MOT Status**

Expires 12-Mar-27

Year Of Manufacture	2011
Date Of First Registration	Sep-11
Date Of Last V5C (logbook) Issued	04-Jun-26
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	2910
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	17	! Pass Rate	76%
✓ Test Passed	13	! Pass Rate With Advisory	53%
! Passed With Advisory	7	✓ Pass Rate Without Advisory	47%
! Total Items Advised	16	✓ Mileage Issues	No
! Advisory Average/Per MOT	1.23	Last MOT Mileage	153401 MI
✗ Test Failed	4	Est Current Mileage	155036 MI
✗ Total Items Failed	4	Average Mileage	10226 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✗ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
16-May-26	! PLATE	GB M123TAP → GB KX61NHB			
13-Mar-26	✓ PASS	153401 MI	7019	386	Failures(0) Advisories(2)
20-Feb-25	✓ PASS	146382 MI	3693	350	Failures(0) Advisories(5)
07-Mar-24	✓ PASS	142689 MI	3344	367	Failures(0) Advisories(1)
06-Mar-23	✓ PASS	139345 MI	3623	378	Failures(0) Advisories(2)
21-Feb-22	✓ PASS	135722 MI	6918	352	Failures(0) Advisories(3)
06-Mar-21	✓ PASS	128804 MI	3469	364	Failures(0) Advisories(2)

30-Sep-20	! PLATE	GB KX61NHB → GB M123TAP				
12-Sep-20	! KEEPER 4					
07-Mar-20	✓ PASS	125335 MI	19	10	Failures(0) Advisories(0)	
26-Feb-20	✗ FAIL	125316 MI	11909	364	Failures(1) Advisories(0)	
27-Feb-19	✓ PASS	113407 MI	0	0	Failures(0) Advisories(0)	
27-Feb-19	✗ FAIL	113407 MI	17310	385	Failures(0) Advisories(0)	
07-Feb-18	✓ PASS	96097 MI	16698	344	Failures(0) Advisories(0)	
28-Feb-17	✓ PASS	79399 MI	0	0	Failures(0) Advisories(0)	
28-Feb-17	✗ FAIL	79399 MI	510	133	Failures(0) Advisories(0)	
28-Feb-17	! KEEPER 3					
21-Oct-16	! PLATE	GB E1ABS → GB KX61NHB				
18-Oct-16	✓ PASS	78889 MI	20217	421	Failures(0) Advisories(1)	
24-Aug-15	✓ PASS	58672 MI	15774	354	Failures(0) Advisories(0)	
04-Sep-14	✓ PASS	42898 MI	53	1	Failures(0) Advisories(0)	
03-Sep-14	✗ FAIL	42845 MI	0	0	Failures(1) Advisories(0)	
26-Feb-13	! PLATE	GB KX61NHB → GB E1ABS				

10-Feb-13



PLATE



N8TRF



KX61NHB

01-Feb-13



KEEPER 2

02-Sep-11



KEEPER 1

Mileage History

S No.	Date	Mileage	Difference	Days
Plate 5 16-May-26 M123TAP → KX61NHB				
17	13-Mar-26	153401 MI	7019 MI	386
16	20-Feb-25	146382 MI	3693 MI	350
15	07-Mar-24	142689 MI	3344 MI	367
14	06-Mar-23	139345 MI	3623 MI	378
13	21-Feb-22	135722 MI	6918 MI	352
12	06-Mar-21	128804 MI	3469 MI	364
Plate 4 30-Sep-20 KX61NHB → M123TAP				
Keeper 12-Sep-20				
11	07-Mar-20	125335 MI	19 MI	10
10	26-Feb-20	125316 MI	11909 MI	364
9	27-Feb-19	113407 MI	0	0
8	27-Feb-19	113407 MI	17310 MI	385
7	07-Feb-18	96097 MI	16698 MI	344
6	28-Feb-17	79399 MI	0	0

5	28-Feb-17	79399 MI	510 MI	133
Keeper	28-Feb-17			
Plate 3	21-Oct-16	 E1ABS →  KX61NHB		
4	18-Oct-16	78889 MI	20217 MI	421
3	24-Aug-15	58672 MI	15774 MI	354
2	04-Sep-14	42898 MI	53 MI	1
1	03-Sep-14	42845 MI		0
Plate 2	26-Feb-13	 KX61NHB →  E1ABS		
Plate 1	10-Feb-13	 N8TRF →  KX61NHB		
Keeper	01-Feb-13			
Keeper	02-Sep-11			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	KX61NHB	Make & Model	MERCEDES-BENZ ML350 SPT CDI BLUEEF-CY A
Make	MERCEDES-BENZ	Model	ML350 SPT CDI BLUEEF-CY A
Engine Capacity	2987	Year of Manufacture	2011
Fuel Type	DIESEL	Date First Registered	02-Sep-11
Door Plan	ESTATE	Date of 1st Registration in UK	02-Sep-11
Colour	SILVER	Year-Month 1st Registered	2011-09
CO2 Emissions	240 g/km	Transmission	AUTO 7 GEARS
Gear Count	7	Transmission Type	Automatic
Engine Number	64282041088996	Transmission Code	A
Gross Weight	2910	Door Plan Code	06
Maximum Permissible Mass	2910	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	21-May-26 15:51:59		

General Information

Make	Mercedes Cars	Euro Status	5a
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	6	Fuel Delivery	Common Rail Direct Injection
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	V	Stroke	92
Valve Gear	DOHC	Location	FRONT
Description	OM642 D30 EU5-C	Bore	83
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	4x4	Primary Fuel Flag	Y
Series Description	W164	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	4	Keeper Data Count	3
Keeper 4 (Current Keeper)			12-Sep-20
Keeper 3			28-Feb-17
Keeper 2			01-Feb-13
Keeper 1 (First Keeper)			02-Sep-11

V5C Certificate issue details

V5C Certificate Count	5	Certificate Dates	01-Oct-20 02-Mar-17 11-Feb-13 01-Oct-12 02-Sep-11
-----------------------	---	-------------------	---

Vehicle Tax & CO2 Emissions

Standard Six Month	418	Per Month	69.67
Standard Twelve Month	760	Per Month	63.33
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	240 g/km	VED Band	L
VED CO2 Band	L		

Performance Information

Torque FtLb	398.2	Power Rpm	3800
Torque Rpm	2400	Power Bhp	231
Torque Nm	540	Power Kw	170
CO2	246	NoiseLevel	***
Max Speed Mph	137	Particles	***
Max Speed Kph	220	Data Version Number	***
Acceleration Zero To 60Mph	***	Acceleration Mph	***
Acceleration Zero To 100Kph	7.6	Acceleration Kph	7.6

Consumption

Combined Mpg	32.5	Combined Lkm	8.7
ExtraUrban Mpg	38.2	ExtraUrban Lkm	7.4
UrbanCold Mpg	25.9	UrbanCold Lkm	10.9

! Plate Change History

Plate Change Count	5	
1	16-May-26	 M123TAP →  KX61NHB
2	30-Sep-20	 KX61NHB →  M123TAP
3	21-Oct-16	 E1ABS →  KX61NHB
4	26-Feb-13	 KX61NHB →  E1ABS
5	10-Feb-13	 N8TRF →  KX61NHB

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	SILVER	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	SILVER		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	M123TAP
---------------------------	-----	-----------------	---------

Dimensions

Gross Vehicle Weight	2910	Height	1815
Gross Combined Weight	***	Width	2170
Kerb Weight	2185	Car Length	4781
Unladen Weight	2185	Wheel Base	2915
Fuel Tank Capacity	70	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	2.05
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Mercedes-Benz	DVLA Make	MERCEDES-BENZ
SMMT Range	M-Class	DVLA Model	ML350 SPT CDI BLUEEF-CY A
SMMT Trim	ML350 Sport CDI BlueEfficiency Auto	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Mercedes-Benz	Range	M-Class
Model Variant	ML350 Sport CDI BlueEfficiency Auto	Fuel Type	Diesel
Nominal Engine Capacity	3	Transmission	Automatic
Engine Capacity	2987	Number Of Doors	5
Body Style	SUV	Number Of Gears	7
DriveType	4x4	SysSetup Date	01-Mar-10
Country Of Origin	USA	Visibility Date	01-Mar-10
Series	W164	Terminate Date	28-Jun-12
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

13-Mar-26



PASS

153401 MI

898184459976

Advisories

- ADVISORY** Sub-frame pin or bush worn but not resulting in excessive movement N/S and O/S front subframe rear bushes deteriorated (5.3.4 (a) (i))
- ADVISORY** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

20-Feb-25



PASS

146382 MI

619424935786

Advisories

- ADVISORY** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Offside Front Brake pipe corroded, covered in grease or other material to wheel (1.1.11 (c))
- ADVISORY** Nearside Front Sub-frame pin or bush worn but not resulting in excessive movement sub -frame rear bush (5.3.4 (a) (i))
- ADVISORY** Offside Front Sub-frame pin or bush worn but not resulting in excessive movement sub-frame rear bush (5.3.4 (a) (i))

07-Mar-24



PASS

142689 MI

291599415508

Advisories

- ADVISORY** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer side wall (5.2.3 (d) (i))

06-Mar-23



PASS

139345 MI

897295736538

Advisories

- ADVISORY** Sub-frame pin or bush worn but not resulting in excessive movement front subframe rear bushes slightly deteriorated (5.3.4 (a) (i))
- ADVISORY** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall damaged (5.2.3 (d) (i))

21-Feb-22

**PASS**

135722 MI

150768321261

Advisories

- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- ADVISORY** Sub-frame pin or bush worn but not resulting in excessive movement N/S and O/S front subframe rear bushes slightly deteriorated (5.3.4 (a) (i))

06-Mar-21

**PASS**

128804 MI

294931152035

Advisories

- ADVISORY** Suspension component pin or bush slightly worn n/s and o/s front subframe rear bushes starting to deteriorate (5.3.4 (a) (i))
- ADVISORY** Suspension component pin or bush slightly worn n/s and o/s front wishbone rear bushes slightly perishing (5.3.4 (a) (i))

07-Mar-20

**PASS**

125335 MI

222663329759

26-Feb-20

**FAIL**

125316 MI

845114128112

Failures

- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

27-Feb-19

**PASS**

113407 MI

519734047510

27-Feb-19

**FAIL**

113407 MI

509237485911

Failures

- PRS** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

07-Feb-18

**PASS**

96097 MI

489920618780

28-Feb-17

**PASS**

79399 MI

976953129227

28-Feb-17



FAIL

79399 MI

325956111331

Failures

PRS Offside Front position lamp(s) not working (1.1.A.3b)

18-Oct-16



PASS

78889 MI

107505611512

Advisories

ADVISORY Offside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

24-Aug-15



PASS

58672 MI

665758360440

04-Sep-14



PASS

42898 MI

175647944207

03-Sep-14



FAIL

42845 MI

576606644202

Failures

Failed Parking brake: efficiency below requirements (3.7.C.1b)

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.