

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✗	Taxi	✓	Recall	✓	Keepers	2	Keeper	02-Sep-22 20-Sep-16

✓ Taxed Tax due: 01-Sep-26		✓ MOT Status Expires 20-Apr-27	
Vehicle Make	VOLVO	Year Of Manufacture	2016
Fuel Type	DIESEL	Date Of First Registration	Sep-16
Cylinder Capacity	1969	Date Of Last V5C (logbook) Issued	16-Aug-25
Vehicle Colour	RED	Export Marker	***
Euro Stats	***	Vehicle Type Approval	M1
Co2 Emissions	99 g/km	Revenue Weight	***
Real Driving Emissions (RDE)	***	Vehicle Status	Taxed
Wheelplan	2 AXLE RIGID BODY	MOT Status	Valid
Ulez Compliance	Check TFL		

Mot & Mileage Summary

Total Test	11	! Pass Rate	72%
✓ Test Passed	8	! Pass Rate With Advisory	62%
! Passed With Advisory	5	✓ Pass Rate Without Advisory	38%
! Total Items Advised	8	✗ Mileage Issues	Yes
! Advisory Average/Per MOT	1.00	Last MOT Mileage	88277 MI
✗ Test Failed	3	Est Current Mileage	90257 MI
✗ Total Items Failed	5	Average Mileage	8827 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✗ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
30-Mar-26	✓ PASS	88277 MI	8158	354	Failures(0) Advisories(0)
10-Apr-25	✓ PASS	80119 MI	0	0	Failures(0) Advisories(0)
10-Apr-25	✗ FAIL	80119 MI	9779	356	Failures(1) Advisories(1)
19-Apr-24	✓ PASS	70340 MI	-42535	8	Failures(0) Advisories(1)
11-Apr-24	✗ FAIL	112875 KM	50559	359	Failures(2) Advisories(1)
18-Apr-23	✓ PASS	62316 MI	4425	362	Failures(0) Advisories(1)
02-Sep-22	! KEEPER 2				

21-Apr-22	 PASS	57891 MI	4072	260	Failures(0) Advisories(0)
04-Aug-21	 PASS	53819 MI	8056	350	Failures(0) Advisories(2)
19-Aug-20	 PASS	45763 MI	3	8	Failures(0) Advisories(1)
11-Aug-20	 FAIL	45760 MI	9487	363	Failures(2) Advisories(3)
14-Aug-19	 PASS	36273 MI	0	0	Failures(0) Advisories(3)
20-Sep-16	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
11	30-Mar-26	88277 MI	8158 MI	354
10	10-Apr-25	80119 MI	0	0
9	10-Apr-25	80119 MI	9779 MI	356
8	19-Apr-24	70340 MI	-42535 MI	8
7	11-Apr-24	112875 KM	50559 MI	359
6	18-Apr-23	62316 MI	4425 MI	362
Keeper	02-Sep-22			
5	21-Apr-22	57891 MI	4072 MI	260
4	04-Aug-21	53819 MI	8056 MI	350
3	19-Aug-20	45763 MI	3 MI	8
2	11-Aug-20	45760 MI	9487 MI	363
1	14-Aug-19	36273 MI		0

Keeper

20-Sep-16



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Miles / KMs Warning

A mixture of Miles and KMs has been detected in the MOT history.

Mileage Reverse

A discrepancy in mileage has been detected in the MOT history.

Vehicle Information

Vehicle Registration Mark	LN66KPZ	Make & Model	VOLVO V40 R-DESIGN PRO D3
Make	VOLVO	Model	V40 R-DESIGN PRO D3
Engine Capacity	1969	Year of Manufacture	2016
Fuel Type	DIESEL	Date First Registered	20-Sep-16
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	20-Sep-16
Colour	RED	Year-Month 1st Registered	2016-09
CO2 Emissions	99 g/km	Transmission	MANUAL 6 GEARS
Gear Count	6	Transmission Type	Manual
Engine Number	1674794	Transmission Code	M
Gross Weight	1980	Door Plan Code	14
Maximum Permissible Mass	1980	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	04-Feb-26 04:02:19		

General Information

Make	Volvo Cars	Euro Status	6b
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	93
Valve Gear	DOHC	Location	FRONT
Description	D4204T9	Bore	82
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	525, 526	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	2	Keeper Data Count	1
Keeper 2 (Current Keeper)			02-Sep-22
Keeper 1 (First Keeper)			20-Sep-16

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	16-Aug-25 21-Jan-22 01-Nov-16 20-Sep-16
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	***	Per Month	0
Standard Twelve Month	20	Per Month	1.67
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	99 g/km	VED Band	A
VED CO2 Band	A		

Performance Information

Torque FtLb	236.2	Power Rpm	3750
Torque Rpm	1750	Power Bhp	148
Torque Nm	320	Power Kw	110
CO2	99	NoiseLevel	***
Max Speed Mph	130	Particles	***
Max Speed Kph	209	Data Version Number	***
Acceleration Zero To 60Mph	7.9	Acceleration Mph	7.9
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	74.3	Combined Lkm	3.8
ExtraUrban Mpg	80.7	ExtraUrban Lkm	3.5
UrbanCold Mpg	64.2	UrbanCold Lkm	4.4

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	RED	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	RED		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1980	Height	1439
Gross Combined Weight	1980	Width	1857
Kerb Weight	1423	Car Length	4369
Unladen Weight	1423	Wheel Base	2647
Fuel Tank Capacity	62	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	98	Child	75
Pedestrian	88		

Classification Details

SMMT Make	Volvo	DVLA Make	VOLVO
SMMT Range	V40	DVLA Model	V40 R-DESIGN PRO D3
SMMT Trim	V40 R-Design Pro D3	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Volvo	Range	V40
Model Variant	V40 R-Design Pro D3	Fuel Type	Diesel
Nominal Engine Capacity	2	Transmission	Manual
Engine Capacity	1969	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	6
DriveType	4x2	SysSetup Date	09-May-16
Country Of Origin	Belgium	Visibility Date	09-May-16
Series	525, 526	Terminate Date	29-Dec-17
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

30-Mar-26	 PASS	88277 MI	179972497135
-----------	---	----------	--------------

10-Apr-25	 PASS	80119 MI	460388417577
-----------	---	----------	--------------

10-Apr-25	 FAIL	80119 MI	208294000409
-----------	---	----------	--------------

Advisories

ADVISORY Nearside Rear Tyre slightly damaged out of shape inner edge 225 40 18 (5.2.3 (d) (ii))

Failures

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

19-Apr-24	 PASS	70340 MI	101117188752
-----------	---	----------	--------------

Advisories

ADVISORY Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

11-Apr-24	 FAIL	112875 KM	243735257950
-----------	---	-----------	--------------

Advisories

ADVISORY Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Failures

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

18-Apr-23	 PASS	62316 MI	402172497475
-----------	---	----------	--------------

Advisories

ADVISORY Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

21-Apr-22	 PASS	57891 MI	788474546441
-----------	---	----------	--------------

04-Aug-21	 PASS	53819 MI	995729682425
-----------	---	----------	--------------

Advisories

- ADVISORY** Nearside Front Tyre slightly damaged outer wall (5.2.3 (d) (ii))
- ADVISORY** Offside Front Tyre slightly damaged outer wall (5.2.3 (d) (ii))

19-Aug-20



PASS

45763 MI

790242528955

Advisories

- ADVISORY** Offside Rear underguard insecure

11-Aug-20



FAIL

45760 MI

213385523752

Advisories

- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Offside Front Nail in tyre
- ADVISORY** Offside Rear underguard insecure

Failures

- MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

14-Aug-19



PASS

36273 MI

253146576359

Advisories

- ADVISORY** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Nail in tyre

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.