

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✗	Keepers	7	Keeper	21-May-23 05-May-23 27-Mar-23 17-Dec-19 01-Aug-15 20-Sep-11 09-May-09

✖

Untaxed

Tax due: N/A

Vehicle Make

BMW

Fuel Type

PETROL

Cylinder Capacity

2000

Vehicle Colour

BLACK

Euro Stats

Co2 Emissions

139 g/km

Real Driving Emissions (RDE)

Wheelplan

2 AXLE RIGID BODY

Ulez Compliance

[Check TFL](#)

✔

MOT Status

Expires 09-Feb-27

Year Of Manufacture

2009

Date Of First Registration

May-09

Date Of Last V5C (logbook) Issued

04-Apr-25

Export Marker

Vehicle Type Approval

M1

Revenue Weight

Vehicle Status

SORN

MOT Status

Valid

Mot & Mileage Summary

Total Test	23	✗ Pass Rate	60%
✓ Test Passed	14	! Pass Rate With Advisory	42%
! Passed With Advisory	6	✓ Pass Rate Without Advisory	58%
! Total Items Advised	21	✓ Mileage Issues	No
! Advisory Average/Per MOT	1.50	Last MOT Mileage	165486 MI
✗ Test Failed	9	Est Current Mileage	168452 MI
✗ Total Items Failed	17	Average Mileage	9734 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✗ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
09-Feb-26	✓ PASS	165486 MI	0	0	Failures(0) Advisories(5)
09-Feb-26	✗ FAIL	165486 MI	8277	371	Failures(0) Advisories(5)
03-Feb-25	✓ PASS	157209 MI	6029	359	Failures(0) Advisories(1)
10-Feb-24	✓ PASS	151180 MI	62	39	Failures(0) Advisories(0)
02-Jan-24	✗ FAIL	151118 MI	5625	342	Failures(1) Advisories(0)
21-May-23	! KEEPER 7				
05-May-23	! KEEPER 6				

27-Mar-23	!	KEEPER 5				
25-Jan-23	✓	PASS	145493 MI	0	8	Failures(0) Advisories(9)
17-Jan-23	✗	FAIL	145493 MI	7688	362	Failures(4) Advisories(9)
20-Jan-22	✓	PASS	137805 MI	3	0	Failures(0) Advisories(4)
20-Jan-22	✗	FAIL	137802 MI	9011	362	Failures(1) Advisories(4)
23-Jan-21	✓	PASS	128791 MI	3	1	Failures(0) Advisories(1)
22-Jan-21	✗	FAIL	128788 MI	18442	632	Failures(5) Advisories(1)
17-Dec-19	!	KEEPER 4				
01-May-19	✓	PASS	110346 MI	0	0	Failures(0) Advisories(1)
01-May-19	✗	FAIL	110346 MI	5913	356	Failures(1) Advisories(0)
10-May-18	✓	PASS	104433 MI	0	2	Failures(0) Advisories(0)
08-May-18	✗	FAIL	104433 MI	2885	369	Failures(1) Advisories(0)
04-May-17	✓	PASS	101548 MI	0	0	Failures(0) Advisories(0)
04-May-17	✗	FAIL	101548 MI	2747	363	Failures(0) Advisories(0)
06-May-16	✓	PASS	98801 MI	9	1	Failures(0) Advisories(0)
05-May-16	✗	FAIL	98792 MI	9218	383	Failures(2) Advisories(3)

01-Aug-15	!	KEEPER 3				
18-Apr-15	✓	PASS	89574 MI	13988	357	Failures(0) Advisories(0)
26-Apr-14	✓	PASS	75586 MI	20364	366	Failures(0) Advisories(0)
25-Apr-13	✓	PASS	55222 MI	21360	370	Failures(0) Advisories(0)
20-Apr-12	✓	PASS	33862 MI	0	0	Failures(0) Advisories(0)
20-Sep-11	!	KEEPER 2				
09-May-09	!	KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
23	09-Feb-26	165486 MI	0	0
22	09-Feb-26	165486 MI	8277 MI	371
21	03-Feb-25	157209 MI	6029 MI	359
20	10-Feb-24	151180 MI	62 MI	39
19	02-Jan-24	151118 MI	5625 MI	342
Keeper	21-May-23			
Keeper	05-May-23			
Keeper	27-Mar-23			
18	25-Jan-23	145493 MI	0	8
17	17-Jan-23	145493 MI	7688 MI	362

16	20-Jan-22	137805 MI	3 MI	0
15	20-Jan-22	137802 MI	9011 MI	362
14	23-Jan-21	128791 MI	3 MI	1
13	22-Jan-21	128788 MI	18442 MI	632
Keeper	17-Dec-19			
12	01-May-19	110346 MI	0	0
11	01-May-19	110346 MI	5913 MI	356
10	10-May-18	104433 MI	0	2
9	08-May-18	104433 MI	2885 MI	369
8	04-May-17	101548 MI	0	0
7	04-May-17	101548 MI	2747 MI	363
6	06-May-16	98801 MI	9 MI	1
5	05-May-16	98792 MI	9218 MI	383
Keeper	01-Aug-15			
4	18-Apr-15	89574 MI	13988 MI	357
3	26-Apr-14	75586 MI	20364 MI	366
2	25-Apr-13	55222 MI	21360 MI	370
1	20-Apr-12	33862 MI		0
Keeper	20-Sep-11			
Keeper	09-May-09			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	LS09ZWA	Make & Model	BMW 116I SPORT
Make	BMW	Model	116I SPORT
Engine Capacity	1995	Year of Manufacture	2009
Fuel Type	PETROL	Date First Registered	09-May-09
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	09-May-09
Colour	BLACK	Year-Month 1st Registered	2009-05
CO2 Emissions	139 g/km	Transmission	MANUAL 6 GEARS
Gear Count	6	Transmission Type	Manual
Engine Number	A941I434	Transmission Code	M
Gross Weight	1775	Door Plan Code	14
Maximum Permissible Mass	1775	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	07-Aug-25 21:42:11		

General Information

Make	BMW	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	90
Valve Gear	DOHC	Location	FRONT
Description	N43B20K0-EU4-A	Bore	84
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	RWD	Primary Fuel Flag	Y
Series Description	E87	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	7	Keeper Data Count	6
Keeper 7 (Current Keeper)			21-May-23
Keeper 6			05-May-23
Keeper 5			27-Mar-23
Keeper 4			17-Dec-19
Keeper 3			01-Aug-15
Keeper 2			20-Sep-11
Keeper 1 (First Keeper)			09-May-09

V5C Certificate issue details

V5C Certificate Count	5	Certificate Dates	04-Apr-25 05-May-23 27-Mar-23 18-Dec-19 13-Apr-18
-----------------------	---	-------------------	---

Vehicle Tax & CO2 Emissions

Standard Six Month	110	Per Month	18.33
Standard Twelve Month	200	Per Month	16.67
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	139 g/km	VED Band	E
VED CO2 Band	E		

Performance Information

Torque FtLb	136.5	Power Rpm	6000
Torque Rpm	3000	Power Bhp	120.7
Torque Nm	185	Power Kw	90
CO2	139	NoiseLevel	***
Max Speed Mph	127	Particles	***
Max Speed Kph	204	Data Version Number	***
Acceleration Zero To 60Mph	9.9	Acceleration Mph	9.9
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	48.7	Combined Lkm	5.8
ExtraUrban Mpg	58.9	ExtraUrban Lkm	4.8
UrbanCold Mpg	37.7	UrbanCold Lkm	7.5

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	BLACK	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	BLACK		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1775	Height	1421
Gross Combined Weight	1775	Width	1748
Kerb Weight	1275	Car Length	4239
Unladen Weight	1275	Wheel Base	2660
Fuel Tank Capacity	53	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	BMW	DVLA Make	BMW
SMMT Range	1 Series	DVLA Model	116i SPORT
SMMT Trim	116i Sport	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	BMW	Range	1 Series
Model Variant	116i Sport	Fuel Type	Petrol
Nominal Engine Capacity	2	Transmission	Manual
Engine Capacity	1995	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	6
DriveType	4x2	SysSetup Date	16-Mar-09
Country Of Origin	Germany	Visibility Date	16-Mar-09
Series	E87	Terminate Date	16-Apr-10
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

09-Feb-26	 PASS	165486 MI	538829351897
-----------	---	-----------	--------------

Advisories

- ADVISORY** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- ADVISORY** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- ADVISORY** Front Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

09-Feb-26	 FAIL	165486 MI	836576900330
-----------	---	-----------	--------------

Advisories

- ADVISORY** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- ADVISORY** Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- ADVISORY** Front Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Failures

- PRS** Front Position lamp not working (4.2.1 (a) (ii))

03-Feb-25	 PASS	157209 MI	723408396646
-----------	---	-----------	--------------

Advisories

- ADVISORY** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

10-Feb-24	 PASS	151180 MI	391748429199
-----------	---	-----------	--------------

02-Jan-24	 FAIL	151118 MI	744634346919
-----------	---	-----------	--------------

Failures

- MAJOR** Front Emissions unable to be completed (8.2.2.2 (e))

25-Jan-23	 PASS	145493 MI	622236006135
-----------	---	-----------	--------------

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- ADVISORY** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MINOR** Brake fluid warning lamp illuminated (1.1.10 (f))

17-Jan-23



FAIL

145493 MI

492972056668

Advisories

- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- ADVISORY** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MINOR** Brake fluid warning lamp illuminated (1.1.10 (f))

Failures

- MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))
- MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

20-Jan-22



PASS

137805 MI

240839051194

Advisories

- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

20-Jan-22



FAIL

137802 MI

608947843890

Advisories

- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Failures

- DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

23-Jan-21



PASS

128791 MI

615490168183

Advisories

- ADVISORY** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

22-Jan-21



FAIL

128788 MI

800961763691

Advisories

- ADVISORY** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Failures

- DANGEROUS** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

01-May-19



PASS

110346 MI

850840101755

Advisories

- ADVISORY** vehicle has no center stop lamp fitted

01-May-19



FAIL

110346 MI

207079682362

Failures

- MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))

10-May-18



PASS

104433 MI

213253969912

08-May-18



FAIL

104433 MI

501268393001

Failures

- Failed** Brake fluid warning lamp illuminated (3.6.G.2)

04-May-17



PASS

101548 MI

251316903631

04-May-17



FAIL

101548 MI

666468767587

Failures

PRS

Offside Headlamp not working on dipped beam (1.7.5a)

06-May-16



PASS

98801 MI

460257660190

05-May-16



FAIL

98792 MI

297109580667

Advisories

ADVISORY Offside Rear Tyre worn close to the legal limit nail in tyre (4.1.E.1)**ADVISORY** Tyre worn close to the legal limit both front low on edges (4.1.E.1)**ADVISORY** Front Brake pad(s) wearing thin and rear pad light on (3.5.1g)

Failures

Failed Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Failed** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

18-Apr-15



PASS

89574 MI

268328405105

26-Apr-14



PASS

75586 MI

115166914145

25-Apr-13



PASS

55222 MI

766905913110

20-Apr-12



PASS

33862 MI

235211912486

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.