

YOUR VEHICLE DATA

Scrapped	✓	Exported	✓	Imported	✓	Plate Change	✓	Colour Change	✓
Mileage	✓	Taxi	✓	Recall	✓	Keepers	7	Keeper	21-Sep-24 24-Aug-24 12-Feb-21 24-Aug-17 31-Mar-09

✓ Taxed Tax due: 01-Sep-26		✓ MOT Status Expires 02-Sep-26	
Vehicle Make	FIAT	Year Of Manufacture	2009
Fuel Type	PETROL	Date Of First Registration	Mar-09
Cylinder Capacity	1368	Date Of Last V5C (logbook) Issued	21-Sep-24
Vehicle Colour	BLACK	Export Marker	***
Euro Stats	***	Vehicle Type Approval	M1
Co2 Emissions	139 g/km	Revenue Weight	***
Real Driving Emissions (RDE)	***	Vehicle Status	Taxed
Wheelplan	2 AXLE RIGID BODY	MOT Status	Valid
Ulez Compliance	Check TFL		

Mot & Mileage Summary

Total Test	22	✖ Pass Rate	59%
✔ Test Passed	13	! Pass Rate With Advisory	69%
! Passed With Advisory	9	✔ Pass Rate Without Advisory	31%
! Total Items Advised	19	✔ Mileage Issues	No
! Advisory Average/Per MOT	1.46	Last MOT Mileage	158351 MI
✖ Test Failed	9	Est Current Mileage	172594 MI
✖ Total Items Failed	21	Average Mileage	9896 Miles/Year
✔ Taxi/Rent a Car Use	Might not	✖ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
01-Sep-25	✔ PASS	158351 MI	6	0	Failures(0) Advisories(2)
01-Sep-25	✖ FAIL	158345 MI	17583	363	Failures(3) Advisories(2)
21-Sep-24	! KEEPER 7				
03-Sep-24	✔ PASS	140762 MI	73	6	Failures(0) Advisories(0)
28-Aug-24	✖ FAIL	140689 MI	862	558	Failures(4) Advisories(0)
24-Aug-24	! KEEPER 6				
17-Feb-23	✔ PASS	139827 MI	0	0	Failures(0) Advisories(2)

17-Feb-23	 FAIL	139827 MI	2867	423	Failures(0) Advisories(2)
21-Dec-21	 PASS	136960 MI	0	40	Failures(0) Advisories(1)
11-Nov-21	 FAIL	136960 MI	5718	513	Failures(2) Advisories(0)
12-Feb-21	 KEEPER 5				
16-Jun-20	 PASS	131242 MI	0	1	Failures(0) Advisories(1)
15-Jun-20	 FAIL	131242 MI	11441	343	Failures(1) Advisories(1)
08-Jul-19	 PASS	119801 MI	19716	369	Failures(0) Advisories(2)
04-Jul-18	 PASS	100085 MI	11735	359	Failures(0) Advisories(0)
24-Aug-17	 KEEPER 4				
10-Jul-17	 PASS	88350 MI	0	12	Failures(0) Advisories(3)
28-Jun-17	 FAIL	88350 MI	9106	383	Failures(2) Advisories(2)
10-Jun-16	 PASS	79244 MI	10163	365	Failures(0) Advisories(5)
11-Jun-15	 PASS	69081 MI	0	0	Failures(0) Advisories(2)
11-Jun-15	 FAIL	69081 MI	10468	365	Failures(1) Advisories(2)
11-Jun-14	 FAIL	58613 MI	10220	365	Failures(0) Advisories(1)
11-Jun-14	 PASS	58613 MI	0	0	Failures(0) Advisories(1)

11-Jun-13	 PASS	48393 MI	11269	365	Failures(0) Advisories(0)
11-Jun-12	 PASS	37124 MI	304	10	Failures(0) Advisories(0)
01-Jun-12	 FAIL	36820 MI	0	0	Failures(4) Advisories(0)
31-Mar-09	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
22	01-Sep-25	158351 MI	6 MI	0
21	01-Sep-25	158345 MI	17583 MI	363
Keeper	21-Sep-24			
20	03-Sep-24	140762 MI	73 MI	6
19	28-Aug-24	140689 MI	862 MI	558
Keeper	24-Aug-24			
18	17-Feb-23	139827 MI	0	0
17	17-Feb-23	139827 MI	2867 MI	423
16	21-Dec-21	136960 MI	0	40
15	11-Nov-21	136960 MI	5718 MI	513
Keeper	12-Feb-21			
14	16-Jun-20	131242 MI	0	1
13	15-Jun-20	131242 MI	11441 MI	343
12	08-Jul-19	119801 MI	19716 MI	369

11	04-Jul-18	100085 MI	11735 MI	359
Keeper		24-Aug-17		
10	10-Jul-17	88350 MI	0	12
9	28-Jun-17	88350 MI	9106 MI	383
8	10-Jun-16	79244 MI	10163 MI	365
7	11-Jun-15	69081 MI	0	0
6	11-Jun-15	69081 MI	10468 MI	365
5	11-Jun-14	58613 MI	0	365
4	11-Jun-14	58613 MI	10220 MI	0
3	11-Jun-13	48393 MI	11269 MI	365
2	11-Jun-12	37124 MI	304 MI	10
1	01-Jun-12	36820 MI		0
Keeper		31-Mar-09		



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	MK09LKX	Make & Model	FIAT GRANDE PUNTO ACTIVE 77
Make	FIAT	Model	GRANDE PUNTO ACTIVE 77
Engine Capacity	1368	Year of Manufacture	2009
Fuel Type	PETROL	Date First Registered	31-Mar-09
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	31-Mar-09
Colour	BLACK	Year-Month 1st Registered	2009-03
CO2 Emissions	139 g/km	Transmission	MANUAL 5 GEARS
Gear Count	5	Transmission Type	Manual
Engine Number	4608482	Transmission Code	M
Gross Weight	1600	Door Plan Code	14
Maximum Permissible Mass	1600	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	01-Feb-25 04:58:36		

General Information

Make	Fiat	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	2	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	84
Valve Gear	SOHC	Location	FRONT
Description	350A1000-B	Bore	72
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	199	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	7	Keeper Data Count	4
Keeper 7 (Current Keeper)			21-Sep-24
Keeper 6			24-Aug-24
Keeper 5			12-Feb-21
Keeper 4			24-Aug-17
Keeper 1 (First Keeper)			31-Mar-09

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	21-Sep-24 24-Aug-24 26-Feb-21 26-Sep-17
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	110	Per Month	18.33
Standard Twelve Month	200	Per Month	16.67
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	139 g/km	VED Band	E
VED CO2 Band	E		

Performance Information

Torque FtLb	84.6	Power Rpm	6000
Torque Rpm	3000	Power Bhp	77
Torque Nm	115	Power Kw	57
CO2	139	NoiseLevel	***
Max Speed Mph	103	Particles	***
Max Speed Kph	165	Data Version Number	***
Acceleration Zero To 60Mph	13.2	Acceleration Mph	13.2
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	47.9	Combined Lkm	5.9
ExtraUrban Mpg	56.5	ExtraUrban Lkm	5
UrbanCold Mpg	37.7	UrbanCold Lkm	7.5

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	BLACK	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	BLACK		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1600	Height	1490
Gross Combined Weight	1600	Width	1687
Kerb Weight	1040	Car Length	4030
Unladen Weight	1040	Wheel Base	2510
Fuel Tank Capacity	45	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Fiat	DVLA Make	FIAT
SMMT Range	Grande Punto	DVLA Model	GRANDE PUNTO ACTIVE 77
SMMT Trim	Grande Punto Active 77	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Fiat	Range	Grande Punto
Model Variant	Grande Punto Active 77	Fuel Type	Petrol
Nominal Engine Capacity	1.4	Transmission	Manual
Engine Capacity	1368	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	5
DriveType	4x2	SysSetup Date	22-Jul-08
Country Of Origin	Italy	Visibility Date	22-Jul-08
Series	199	Terminate Date	24-Nov-10
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

01-Sep-25	 PASS	158351 MI	499850956184
-----------	---	-----------	--------------

Advisories

- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

01-Sep-25	 FAIL	158345 MI	186176870921
-----------	---	-----------	--------------

Advisories

- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Failures

- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- MAJOR** Exhaust system insecure held up with string, (6.1.2 (a))

03-Sep-24	 PASS	140762 MI	450886217049
-----------	---	-----------	--------------

28-Aug-24	 FAIL	140689 MI	580406319013
-----------	---	-----------	--------------

Failures

- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- MAJOR** Offside Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

17-Feb-23	 PASS	139827 MI	883228316830
-----------	---	-----------	--------------

Advisories

- ADVISORY** advise bonnet catch /condition
- ADVISORY** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

17-Feb-23	 FAIL	139827 MI	927171678932
-----------	---	-----------	--------------

Advisories

- ADVISORY** advise bonnet catch /condition
- ADVISORY** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Failures

- PRS** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

21-Dec-21



PASS

136960 MI

163659561439

Advisories

- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))

11-Nov-21



FAIL

136960 MI

218068173556

Failures

- MAJOR** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Oil leaking excessively from engine sump (8.4.1 (a) (i))

16-Jun-20



PASS

131242 MI

309893299916

Advisories

- ADVISORY** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

15-Jun-20



FAIL

131242 MI

835496134351

Advisories

- ADVISORY** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Failures

- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

08-Jul-19



PASS

119801 MI

280048860161

Advisories

- ADVISORY** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

04-Jul-18



PASS

100085 MI

799864117745

10-Jul-17



PASS

88350 MI

888609942903

Advisories

- ADVISORY** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- ADVISORY** engine oil leak.
- ADVISORY** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

28-Jun-17



FAIL

88350 MI

328258523660

Advisories

- ADVISORY** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- ADVISORY** engine oil leak.

Failures

- Failed** Windscreen washer provides insufficient washer liquid (8.2.3)
- Failed** Parking brake: efficiency below requirements (3.7.B.7)

10-Jun-16



PASS

79244 MI

654528915979

Advisories

- ADVISORY** slight damage to rear of vehicle
- ADVISORY** Nearside Rear coil spring corroded (2.4.C.1b)
- ADVISORY** Offside Rear coil spring corroded (2.4.C.1b)
- ADVISORY** front brake discs slightly lipped
- ADVISORY** exhaust rear section, outer skin corroding

11-Jun-15



PASS

69081 MI

958762365119

Advisories

- ADVISORY** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- USER ENTERED** tail pipe box outer casing corroded

11-Jun-15



FAIL

69081 MI

917752065196

Advisories

- ADVISORY** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- USER ENTERED** tail pipe box outer casing corroded

Failures

- Failed** Nearside Front coil spring broken (2.4.C.1a)

11-Jun-14



FAIL

58613 MI

228102164129

Advisories

USER ENTERED tail pipe box outer casing corroded

Failures

PRS Windscreen washer provides insufficient washer liquid (8.2.3)

11-Jun-14



PASS

58613 MI

239082964401

Advisories

USER ENTERED tail pipe box outer casing corroded

11-Jun-13



PASS

48393 MI

278012163158

11-Jun-12



PASS

37124 MI

865443562146

01-Jun-12



FAIL

36820 MI

749123952129

Failures

Failed Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Failed Nearside Front Tie bar/rod has excessive play in a ball joint (2.4.G.2)

Failed Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Failed Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.