

YOUR VEHICLE DATA

Scrapped 	Exported 	Imported 	Plate Change 	Colour Change 
Mileage 	Taxi 	Recall 	Keepers 4	Keeper 15-Mar-23 01-Aug-22 25-Feb-21 01-Sep-09



Taxed

Tax due: 01-Jul-27

Vehicle Make	TOYOTA
Fuel Type	PETROL
Cylinder Capacity	1986
Vehicle Colour	BLACK
Euro Stats	***
Co2 Emissions	177 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL



MOT Status

Expires 29-Apr-27

Year Of Manufacture	2009
Date Of First Registration	Sep-09
Date Of Last V5C (logbook) Issued	15-Jun-23
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	***
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	24	✖ Pass Rate	62%
✔ Test Passed	15	! Pass Rate With Advisory	60%
! Passed With Advisory	9	✔ Pass Rate Without Advisory	40%
! Total Items Advised	46	✔ Mileage Issues	No
! Advisory Average/Per MOT	3.07	Last MOT Mileage	141348 MI
✖ Test Failed	9	Est Current Mileage	142184 MI
✖ Total Items Failed	28	Average Mileage	8314 Miles/Year
✔ Taxi/Rent a Car Use	Might not	✖ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
20-Apr-26	✔ PASS	141348 MI	0	0	Failures(0) Advisories(14)
20-Apr-26	✖ FAIL	141348 MI	90	4	Failures(0) Advisories(14)
16-Apr-26	✖ FAIL	141258 MI	4552	351	Failures(13) Advisories(12)
30-Apr-25	✔ PASS	136706 MI	0	0	Failures(0) Advisories(10)
30-Apr-25	✖ FAIL	136706 MI	6392	431	Failures(0) Advisories(10)
24-Feb-24	✔ PASS	130314 MI	3001	371	Failures(0) Advisories(1)
15-Mar-23	! KEEPER 4				

18-Feb-23	 PASS	127313 MI	5135	360	Failures(0) Advisories(3)
01-Aug-22	 KEEPER 3				
23-Feb-22	 PASS	122178 MI	14	1	Failures(0) Advisories(2)
22-Feb-22	 FAIL	122164 MI	9098	362	Failures(2) Advisories(3)
25-Feb-21	 PASS	113066 MI	1	2	Failures(0) Advisories(0)
25-Feb-21	 KEEPER 2				
23-Feb-21	 FAIL	113065 MI	7	165	Failures(2) Advisories(0)
11-Sep-20	 PASS	113058 MI	0	1	Failures(0) Advisories(2)
10-Sep-20	 FAIL	113058 MI	6849	390	Failures(2) Advisories(2)
17-Aug-19	 PASS	106209 MI	9721	357	Failures(0) Advisories(9)
25-Aug-18	 PASS	96488 MI	0	0	Failures(0) Advisories(0)
25-Aug-18	 FAIL	96488 MI	10957	385	Failures(0) Advisories(0)
05-Aug-17	 PASS	85531 MI	10929	364	Failures(0) Advisories(2)
06-Aug-16	 PASS	74602 MI	0	0	Failures(0) Advisories(0)
06-Aug-16	 FAIL	74602 MI	11583	368	Failures(0) Advisories(0)
04-Aug-15	 PASS	63019 MI	10748	343	Failures(0) Advisories(3)

26-Aug-14	 PASS	52271 MI	1	3	Failures(0) Advisories(0)
23-Aug-14	 FAIL	52270 MI	12027	368	Failures(2) Advisories(2)
20-Aug-13	 PASS	40243 MI	12262	367	Failures(0) Advisories(0)
18-Aug-12	 PASS	27981 MI	0	0	Failures(0) Advisories(0)
01-Sep-09	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
24	20-Apr-26	141348 MI	0	0
23	20-Apr-26	141348 MI	90 MI	4
22	16-Apr-26	141258 MI	4552 MI	351
21	30-Apr-25	136706 MI	0	0
20	30-Apr-25	136706 MI	6392 MI	431
19	24-Feb-24	130314 MI	3001 MI	371
Keeper	15-Mar-23			
18	18-Feb-23	127313 MI	5135 MI	360
Keeper	01-Aug-22			
17	23-Feb-22	122178 MI	14 MI	1
16	22-Feb-22	122164 MI	9098 MI	362
15	25-Feb-21	113066 MI	1 MI	2
Keeper	25-Feb-21			

14	23-Feb-21	113065 MI	7 MI	165
13	11-Sep-20	113058 MI	0	1
12	10-Sep-20	113058 MI	6849 MI	390
11	17-Aug-19	106209 MI	9721 MI	357
10	25-Aug-18	96488 MI	0	0
9	25-Aug-18	96488 MI	10957 MI	385
8	05-Aug-17	85531 MI	10929 MI	364
7	06-Aug-16	74602 MI	0	0
6	06-Aug-16	74602 MI	11583 MI	368
5	04-Aug-15	63019 MI	10748 MI	343
4	26-Aug-14	52271 MI	1 MI	3
3	23-Aug-14	52270 MI	12027 MI	368
2	20-Aug-13	40243 MI	12262 MI	367
1	18-Aug-12	27981 MI		0
Keeper	01-Sep-09			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	MK59RFY	Make & Model	TOYOTA RAV4 XT-R VALVEMATIC CVT
Make	TOYOTA	Model	RAV4 XT-R VALVEMATIC CVT
Engine Capacity	1986	Year of Manufacture	2009
Fuel Type	PETROL	Date First Registered	01-Sep-09
Door Plan	ESTATE	Date of 1st Registration in UK	01-Sep-09
Colour	BLACK	Year-Month 1st Registered	2009-09
CO2 Emissions	177 g/km	Transmission	AUTO VARIABLE 7 GEARS
Gear Count	7	Transmission Type	Automatic
Engine Number	3ZRA339683	Transmission Code	A
Gross Weight	2125	Door Plan Code	06
Maximum Permissible Mass	2110	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	03-Oct-25 05:07:21		

General Information

Make	Toyota	Euro Status	4
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	98
Valve Gear	DOHC	Location	FRONT
Description	3ZR-FAE-B	Bore	80
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	4x4	Primary Fuel Flag	Y
Series Description	III (XA30)	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	4	Keeper Data Count	3
Keeper 4 (Current Keeper)			15-Mar-23
Keeper 3			01-Aug-22
Keeper 2			25-Feb-21
Keeper 1 (First Keeper)			01-Sep-09

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	15-Jun-23 01-Aug-22 20-Mar-21 02-Sep-13
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	198	Per Month	33
Standard Twelve Month	360	Per Month	30
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	177 g/km	VED Band	I
VED CO2 Band	I		

Performance Information

Torque FtLb	146	Power Rpm	6200
Torque Rpm	4000	Power Bhp	156
Torque Nm	198	Power Kw	116
CO2	177	NoiseLevel	***
Max Speed Mph	115	Particles	***
Max Speed Kph	185	Data Version Number	***
Acceleration Zero To 60Mph	11	Acceleration Mph	11
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	37.7	Combined Lkm	7.5
ExtraUrban Mpg	44.1	ExtraUrban Lkm	6.4
UrbanCold Mpg	29.7	UrbanCold Lkm	9.5

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	BLACK	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	BLACK		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	2125	Height	1685
Gross Combined Weight	2110	Width	1815
Kerb Weight	1565	Car Length	4335
Unladen Weight	1565	Wheel Base	2560
Fuel Tank Capacity	60	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Toyota	DVLA Make	TOYOTA
SMMT Range	RAV4	DVLA Model	RAV4 XT-R VALVEMATIC CVT
SMMT Trim	RAV4 XT-R Valvematic CVT	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Toyota	Range	RAV4
Model Variant	RAV4 XT-R Valvematic CVT	Fuel Type	Petrol
Nominal Engine Capacity	2	Transmission	CVT
Engine Capacity	1986	Number Of Doors	5
Body Style	SUV	Number Of Gears	7
DriveType	4x4	SysSetup Date	23-Apr-09
Country Of Origin	Japan	Visibility Date	23-Apr-09
Series	III (XA30)	Terminate Date	17-Jan-11
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

20-Apr-26	 PASS	141348 MI	476222548666
-----------	---	-----------	--------------

Advisories

- ADVISORY** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Nearside Integral body structure is modified but structural rigidity is not significantly reduced (6.1.1 (d) (i))
- ADVISORY** Offside Integral body structure is modified but structural rigidity is not significantly reduced (6.1.1 (d) (i))
- ADVISORY** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- ADVISORY** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- ADVISORY** Rear Anti-roll bar corroded but not seriously weakened both sides (5.3.3 (b) (i))
- ADVISORY** Rear Fuel Pipe/s corroded
- ADVISORY** Front Bonnet primary retaining device slightly deteriorated (3.1 (c))

20-Apr-26	 FAIL	141348 MI	960987669231
-----------	---	-----------	--------------

Advisories

- ADVISORY** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Nearside Integral body structure is modified but structural rigidity is not significantly reduced (6.1.1 (d) (i))
- ADVISORY** Offside Integral body structure is modified but structural rigidity is not significantly reduced (6.1.1 (d) (i))
- ADVISORY** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- ADVISORY** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- ADVISORY** Rear Anti-roll bar corroded but not seriously weakened both sides (5.3.3 (b) (i))
- ADVISORY** Rear Fuel Pipe/s corroded
- ADVISORY** Front Bonnet primary retaining device slightly deteriorated (3.1 (c))

Failures

- PRS** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- PRS** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- PRS** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

16-Apr-26



FAIL

141258 MI

185840699349

Advisories

- ADVISORY** Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))
- ADVISORY** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- ADVISORY** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))
- ADVISORY** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Fuel Pipe/s corroded
- ADVISORY** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- ADVISORY** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced under sill corroded both sides (6.1.1 (c) (i))
- ADVISORY** Front Bonnet primary retaining device slightly deteriorated (3.1 (c))
- MINOR** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Failures

- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Outer Body panel damaged and likely to cause injury wing (6.2.1 (a) (i))
- MAJOR** Offside Front Upper Body panel damaged and likely to cause injury wing (6.2.1 (a) (i))
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Offside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced inner sill central (6.1.1 (c) (i))
- MAJOR** Offside Front Headlamp light source and lamp not compatible (4.1.4 (c))
- MAJOR** Nearside Front Headlamp light source and lamp not compatible (4.1.4 (c))
- MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

30-Apr-25



PASS

136706 MI

759966558167

Advisories

- ADVISORY** Front Drive shaft joint worn, but not excessively both sides (6.1.7 (c) (i))
- ADVISORY** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Offside Rear under sill corroded
- ADVISORY** Rear Fuel Pipe/s corroded
- MINOR** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

30-Apr-25



FAIL

136706 MI

864827806362

Advisories

- ADVISORY** Front Drive shaft joint worn, but not excessively both sides (6.1.7 (c) (i))
- ADVISORY** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- ADVISORY** Offside Rear under sill corroded
- ADVISORY** Rear Fuel Pipe/s corroded
- MINOR** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Failures

- PRS** Front Registration plate inscription illegible (0.1 (b))

24-Feb-24



PASS

130314 MI

166269829625

Advisories

- MINOR** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

18-Feb-23



PASS

127313 MI

510905513179

Advisories

- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened BOTH SIDE (NSF&OSF) (1.1.14 (a) (ii))
- ADVISORY** Rear Brake disc worn, but not excessively BOTH SIDE (NSR&OSR) (1.1.14 (a) (i))
- ADVISORY** Rear Tyre slightly damaged/cracking or perishing BOTH SIDE (5.2.3 (d) (ii))

23-Feb-22



PASS

122178 MI

962646454415

Advisories

- ADVISORY** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

22-Feb-22



FAIL

122164 MI

274135683401

Advisories

- ADVISORY** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- ADVISORY** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- MINOR** Offside Windscreen wiper blade defective (3.4 (b) (i))

Failures

- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))

25-Feb-21



PASS

113066 MI

990660907884

23-Feb-21



FAIL

113065 MI

791624003776

Failures

- MAJOR** Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

11-Sep-20



PASS

113058 MI

274639136047

Advisories

- ADVISORY** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement marked yellow (5.3.4 (a) (i))
- ADVISORY** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement marked yellow (5.3.4 (a) (i))

10-Sep-20



FAIL

113058 MI

608369768256

Advisories

- ADVISORY** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement marked yellow (5.3.4 (a) (i))
- ADVISORY** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement marked yellow (5.3.4 (a) (i))

Failures

- DANGEROUS** Exhaust shield missing where fitted as original equipment creating a risk of fire hanging loose (6.1.3 (e))
- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- PRS** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

17-Aug-19



PASS

106209 MI

490515595216

Advisories

- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- ADVISORY** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- ADVISORY** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- ADVISORY** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- ADVISORY** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

25-Aug-18



PASS

96488 MI

127633840323

25-Aug-18



FAIL

96488 MI

582875195420

Failures

- PRS** Front Registration plate does not conform to the specified requirements (0.1 (d))

05-Aug-17



PASS

85531 MI

880744786752

Advisories

- ADVISORY** Front registration plate delaminated but not likely to be misread (6.3.1d)
- ADVISORY** Engine light on

06-Aug-16



PASS

74602 MI

621758916544

06-Aug-16



FAIL

74602 MI

775089229687

Failures

- PRS** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

04-Aug-15



PASS

63019 MI

435006615273

Advisories

- ADVISORY** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- ADVISORY** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

26-Aug-14



PASS

52271 MI

666398534291

23-Aug-14



FAIL

52270 MI

698535834254

Advisories

ADVISORY Offside Front Tyre worn close to the legal limit (4.1.E.1)

ADVISORY Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Failures

Failed Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Failed Electronic stability system warning lamp indicates a fault (3.4.1c)

20-Aug-13



PASS

40243 MI

349752033408

18-Aug-12



PASS

27981 MI

496801432285

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.