

YOUR VEHICLE DATA

Scrapped

Exported

Imported

Plate Change

Colour Change

Mileage

Taxi

Recall

Keepers

7

Keeper

30-Oct-24
19-Jul-21
12-Jul-21
13-Jul-19
15-May-17
26-Apr-12

Taxed

Tax due: 01-Dec-26

Vehicle Make	VAUXHALL
Fuel Type	PETROL
Cylinder Capacity	1398
Vehicle Colour	SILVER
Euro Stats	***
Co2 Emissions	129 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

MOT Status

Expires 21-Oct-26

Year Of Manufacture	2012
Date Of First Registration	Apr-12
Date Of Last V5C (logbook) Issued	04-Mar-26
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	***
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	17	! Pass Rate	70%
✓ Test Passed	12	! Pass Rate With Advisory	75%
! Passed With Advisory	9	✓ Pass Rate Without Advisory	25%
! Total Items Advised	24	✓ Mileage Issues	No
! Advisory Average/Per MOT	2.00	Last MOT Mileage	108532 MI
✗ Test Failed	5	Est Current Mileage	121229 MI
✗ Total Items Failed	15	Average Mileage	8348 Miles/Year
✓ Taxi/Rent a Car Use	Might not	✗ Mileage Status	Above Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
18-Oct-25	✓ PASS	108532 MI	19509	361	Failures(0) Advisories(1)
30-Oct-24	! KEEPER 7				
22-Oct-24	✓ PASS	89023 MI	1064	243	Failures(0) Advisories(0)
22-Feb-24	✓ PASS	87959 MI	2540	248	Failures(0) Advisories(0)
19-Jun-23	✓ PASS	85419 MI	13	6	Failures(0) Advisories(8)
13-Jun-23	✗ FAIL	85406 MI	3372	372	Failures(7) Advisories(8)
06-Jun-22	✓ PASS	82034 MI	1	0	Failures(0) Advisories(1)

06-Jun-22	 FAIL	82033 MI	2104	357	Failures(1) Advisories(1)
19-Jul-21	 KEEPER 6				
12-Jul-21	 KEEPER 5				
14-Jun-21	 PASS	79929 MI	0	4	Failures(0) Advisories(3)
10-Jun-21	 FAIL	79929 MI	3937	311	Failures(4) Advisories(3)
03-Aug-20	 PASS	75992 MI	18	3	Failures(0) Advisories(0)
31-Jul-20	 FAIL	75974 MI	5659	464	Failures(2) Advisories(0)
13-Jul-19	 KEEPER 4				
24-Apr-19	 PASS	70315 MI	4216	364	Failures(0) Advisories(3)
25-Apr-18	 PASS	66099 MI	8889	364	Failures(0) Advisories(1)
15-May-17	 KEEPER 3				
26-Apr-17	 PASS	57210 MI	10919	366	Failures(0) Advisories(4)
25-Apr-16	 PASS	46291 MI	0	0	Failures(0) Advisories(2)
25-Apr-16	 FAIL	46291 MI	11070	366	Failures(0) Advisories(2)
25-Apr-15	 PASS	35221 MI	0	0	Failures(0) Advisories(1)
26-Apr-12	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
17	18-Oct-25	108532 MI	19509 MI	361
Keeper	30-Oct-24			
16	22-Oct-24	89023 MI	1064 MI	243
15	22-Feb-24	87959 MI	2540 MI	248
14	19-Jun-23	85419 MI	13 MI	6
13	13-Jun-23	85406 MI	3372 MI	372
12	06-Jun-22	82034 MI	1 MI	0
11	06-Jun-22	82033 MI	2104 MI	357
Keeper	19-Jul-21			
Keeper	12-Jul-21			
10	14-Jun-21	79929 MI	0	4
9	10-Jun-21	79929 MI	3937 MI	311
8	03-Aug-20	75992 MI	18 MI	3
7	31-Jul-20	75974 MI	5659 MI	464
Keeper	13-Jul-19			
6	24-Apr-19	70315 MI	4216 MI	364
5	25-Apr-18	66099 MI	8889 MI	364
Keeper	15-May-17			
4	26-Apr-17	57210 MI	10919 MI	366
3	25-Apr-16	46291 MI	0	0

2	25-Apr-16	46291 MI	11070 MI	366
1	25-Apr-15	35221 MI		0
Keeper	26-Apr-12			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information			
Vehicle Registration Mark	RE12JYY	Make & Model	VAUXHALL CORSA ACTIVE AC
Make	VAUXHALL	Model	CORSA ACTIVE AC
Engine Capacity	1398	Year of Manufacture	2012
Fuel Type	PETROL	Date First Registered	26-Apr-12
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	26-Apr-12
Colour	SILVER	Year-Month 1st Registered	2012-04
CO2 Emissions	129 g/km	Transmission	MANUAL 5 GEARS
Gear Count	5	Transmission Type	Manual
Engine Number	19ZH9535	Transmission Code	M
Gross Weight	1640	Door Plan Code	14
Maximum Permissible Mass	1640	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	04-Oct-25 18:56:28		

General Information

Make	Vauxhall	Euro Status	5a
Aspiration	Naturally Aspirated	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	4	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	83
Valve Gear	DOHC	Location	FRONT
Description	A14XER-G	Bore	73
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	D (S07)	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	7	Keeper Data Count	5
Keeper 7 (Current Keeper)			30-Oct-24
Keeper 6			19-Jul-21
Keeper 5			12-Jul-21
Keeper 4			13-Jul-19
Keeper 3			15-May-17
Keeper 1 (First Keeper)			26-Apr-12

V5C Certificate issue details

V5C Certificate Count	5	Certificate Dates	30-Oct-24 20-Jul-21 13-Jul-21 13-Jul-19 21-Jun-18
-----------------------	---	-------------------	---

Vehicle Tax & CO2 Emissions

Standard Six Month	93.5	Per Month	15.58
Standard Twelve Month	170	Per Month	14.17
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	129 g/km	VED Band	D
VED CO2 Band	D		

Performance Information

Torque FtLb	96	Power Rpm	6000
Torque Rpm	4000	Power Bhp	98
Torque Nm	130	Power Kw	74
CO2	129	NoiseLevel	***
Max Speed Mph	112	Particles	***
Max Speed Kph	180	Data Version Number	***
Acceleration Zero To 60Mph	11.9	Acceleration Mph	11.9
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	51.4	Combined Lkm	5.5
ExtraUrban Mpg	61.4	ExtraUrban Lkm	4.6
UrbanCold Mpg	39.8	UrbanCold Lkm	7.1

✓ Plate Change History

Plate Change Count ***

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructutions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	SILVER	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	SILVER		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1640	Height	1488
Gross Combined Weight	1640	Width	1944
Kerb Weight	1103	Car Length	3999
Unladen Weight	1103	Wheel Base	2511
Fuel Tank Capacity	45	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	***	Child	***
Pedestrian	***		

Classification Details

SMMT Make	Vauxhall	DVLA Make	VAUXHALL
SMMT Range	Corsa	DVLA Model	CORSA ACTIVE AC
SMMT Trim	Corsa Active AC	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Vauxhall	Range	Corsa
Model Variant	Corsa Active AC	Fuel Type	Petrol
Nominal Engine Capacity	1.4	Transmission	Manual
Engine Capacity	1398	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	5
DriveType	4x2	SysSetup Date	19-Jan-12
Country Of Origin	Spain	Visibility Date	19-Jan-12
Series	D (S07)	Terminate Date	25-Jul-13
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

18-Oct-25



PASS

108532 MI

525518601041

Advisories

ADVISORY Oil leak, but not excessive (8.4.1 (a) (i))

22-Oct-24



PASS

89023 MI

299115747007

22-Feb-24



PASS

87959 MI

418492095853

19-Jun-23



PASS

85419 MI

633566273791

Advisories

ADVISORY Windscreen chipped

ADVISORY Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

ADVISORY Oil leak, but not excessive (8.4.1 (a) (i))

ADVISORY Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

ADVISORY Coil spring corroded offside front and both rear (5.3.1 (b) (i))

ADVISORY Both front shock absorbers corroded

ADVISORY Nearside Rear Tyre worn close to legal limit/worn on edge worn to 2.5mm (5.2.3 (e))

ADVISORY Nearside front and both rear tyres perishing

13-Jun-23



FAIL

85406 MI

404759986073

Advisories

- ADVISORY** Windscreen chipped
- ADVISORY** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Oil leak, but not excessive (8.4.1 (a) (i))
- ADVISORY** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- ADVISORY** Coil spring corroded offside front and both rear (5.3.1 (b) (i))
- ADVISORY** Both front shock absorbers corroded
- ADVISORY** Nearside Rear Tyre worn close to legal limit/worn on edge worn to 2.5mm (5.2.3 (e))
- ADVISORY** Nearside front and both rear tyres perishing

Failures

- MAJOR** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
- MAJOR** Exhaust has a major leak of exhaust gases front section (6.1.2 (a))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

06-Jun-22



PASS

82034 MI

675002031130

Advisories

- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

06-Jun-22



FAIL

82033 MI

167053472335

Advisories

- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Failures

- MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

14-Jun-21



PASS

79929 MI

606785528656

Advisories

- ADVISORY** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge worn outta edge (5.2.3 (e))
- ADVISORY** Brake pedal wearing smooth (1.1.2 (c))

10-Jun-21



FAIL

79929 MI

355198262069

Advisories

- ADVISORY** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge worn outta edge (5.2.3 (e))
- ADVISORY** Brake pedal wearing smooth (1.1.2 (c))

Failures

- DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Nearside Front Headlamp aim not tested (4.1.2 (b))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

03-Aug-20



PASS

75992 MI

813698186835

31-Jul-20



FAIL

75974 MI

291661636554

Failures

- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

24-Apr-19



PASS

70315 MI

978969736149

Advisories

- ADVISORY** Coolant level low
- ADVISORY** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- ADVISORY** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

25-Apr-18



PASS

66099 MI

651505954923

Advisories

- ADVISORY** Items removed from driver's view prior to test

26-Apr-17



PASS

57210 MI

253300948699

Advisories

- ADVISORY** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- ADVISORY** Offside Front outer edge wearing
- ADVISORY** Nearside Rear shock absorber bump stop deteriorated
- ADVISORY** Offside Rear shock absorber bump stop deteriorated

25-Apr-16



PASS

46291 MI

263630559355

Advisories

ADVISORY Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

ADVISORY Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

25-Apr-16



FAIL

46291 MI

327360894059

Advisories

ADVISORY Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

ADVISORY Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Failures

PRS Windscreen washer provides insufficient washer liquid (8.2.3)

25-Apr-15



PASS

35221 MI

165965315173

Advisories

ADVISORY Front Brake pad(s) wearing thin (3.5.1g)

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.