

YOUR VEHICLE DATA

Scrapped

Exported

Imported

Plate Change

Colour Change

Mileage

Taxi

Recall

Keepers

5

Keeper

06-May-25
19-Jan-24
06-Oct-19
12-Mar-15
30-Jan-15

Taxed

Tax due: 01-May-27

Vehicle Make	DACIA
Fuel Type	DIESEL
Cylinder Capacity	1461
Vehicle Colour	GREY
Euro Stats	***
Co2 Emissions	99 g/km
Real Driving Emissions (RDE)	***
Wheelplan	2 AXLE RIGID BODY
Ulez Compliance	Check TFL

MOT Status

Expires 02-May-27

Year Of Manufacture	2015
Date Of First Registration	Jan-15
Date Of Last V5C (logbook) Issued	06-May-25
Export Marker	***
Vehicle Type Approval	M1
Revenue Weight	1590
Vehicle Status	Taxed
MOT Status	Valid

Mot & Mileage Summary

Total Test	13	✗ Pass Rate	69%
✓ Test Passed	9	! Pass Rate With Advisory	44%
! Passed With Advisory	4	✓ Pass Rate Without Advisory	56%
! Total Items Advised	8	✓ Mileage Issues	No
! Advisory Average/Per MOT	0.89	Last MOT Mileage	71975 MI
✗ Test Failed	4	Est Current Mileage	72164 MI
✗ Total Items Failed	20	Average Mileage	6543 Miles/Year
✓ Taxi/Rent a Car Use	Might not	icon Mileage Status	Average

MOT Test List

Date	Result	Mileage	Difference	Days	Reason
30-Apr-26	✓ PASS	71975 MI	1806	362	Failures(0) Advisories(2)
06-May-25	! KEEPER 5				
03-May-25	✓ PASS	70169 MI	24	136	Failures(0) Advisories(0)
18-Dec-24	✗ FAIL	70145 MI	10327	505	Failures(15) Advisories(6)
19-Jan-24	! KEEPER 4				
01-Aug-23	✓ PASS	59818 MI	0	0	Failures(0) Advisories(1)
01-Aug-23	✗ FAIL	59818 MI	4590	370	Failures(3) Advisories(1)

27-Jul-22	 PASS	55228 MI	23	5	Failures(0) Advisories(0)
22-Jul-22	 FAIL	55205 MI	3904	360	Failures(1) Advisories(0)
27-Jul-21	 PASS	51301 MI	54	4	Failures(0) Advisories(0)
23-Jul-21	 FAIL	51247 MI	5522	357	Failures(1) Advisories(0)
31-Jul-20	 PASS	45725 MI	4496	353	Failures(0) Advisories(0)
06-Oct-19	 KEEPER 3				
13-Aug-19	 PASS	41229 MI	4884	200	Failures(0) Advisories(0)
25-Jan-19	 PASS	36345 MI	7573	360	Failures(0) Advisories(2)
30-Jan-18	 PASS	28772 MI	0	0	Failures(0) Advisories(3)
12-Mar-15	 KEEPER 2				
30-Jan-15	 KEEPER 1				

Mileage History

S No.	Date	Mileage	Difference	Days
13	30-Apr-26	71975 MI	1806 MI	362
Keeper	06-May-25			
12	03-May-25	70169 MI	24 MI	136
11	18-Dec-24	70145 MI	10327 MI	505
Keeper	19-Jan-24			

10	01-Aug-23	59818 MI	0	0
9	01-Aug-23	59818 MI	4590 MI	370
8	27-Jul-22	55228 MI	23 MI	5
7	22-Jul-22	55205 MI	3904 MI	360
6	27-Jul-21	51301 MI	54 MI	4
5	23-Jul-21	51247 MI	5522 MI	357
4	31-Jul-20	45725 MI	4496 MI	353
Keeper	06-Oct-19			
3	13-Aug-19	41229 MI	4884 MI	200
2	25-Jan-19	36345 MI	7573 MI	360
1	30-Jan-18	28772 MI		0
Keeper	12-Mar-15			
Keeper	30-Jan-15			



Km / Mileage



Mileage Reverse



Taxi MOT gaps

Vehicle Information

Vehicle Registration Mark	SE64UYM	Make & Model	DACIA SANDERO MIDNIGHT DCI
Make	DACIA	Model	SANDERO MIDNIGHT DCI
Engine Capacity	1461	Year of Manufacture	2015
Fuel Type	DIESEL	Date First Registered	30-Jan-15
Door Plan	5 DOOR HATCHBACK	Date of 1st Registration in UK	30-Jan-15
Colour	GREY	Year-Month 1st Registered	2015-01
CO2 Emissions	99 g/km	Transmission	MANUAL 5 GEARS
Gear Count	5	Transmission Type	Manual
Engine Number	D207465	Transmission Code	M
Gross Weight	1590	Door Plan Code	14
Maximum Permissible Mass	1590	MVRIS Model Code	***
Seating Capacity	5	MVRIS Make Code	***
Wheel Plan	2 AXLE RIGID BODY	Used Before First Registration	No
Vehicle Class	Car	Vin Confirmation Flag	***
Date Of Last Update	02-Oct-25 21:43:52		

General Information

Make	Renault Cars	Euro Status	5b
Aspiration	Turbocharged	Fuel System	
Number Of Cylinders	4	Fuel Delivery	
Valves Per Cylinder	2	Fuel Catalyst	C
Cylinder Arrangement	I	Stroke	80
Valve Gear	SOHC	Location	FRONT
Description	K9K 612	Bore	76
Power Delivery	Normal	Type Approval Category	M1
Driving Axle	FWD	Primary Fuel Flag	Y
Series Description	B52	Driver Position	R
Data Version Number	***	Is Limited Edition	No
EV Battery Capacity	***	EV Battery Charge Port	***
EV Battery Charge Time	***	EV Battery Type	***

Previous Keepers

Total Keepers	5	Keeper Data Count	4
Keeper 5 (Current Keeper)			06-May-25
Keeper 4			19-Jan-24
Keeper 3			06-Oct-19
Keeper 2			12-Mar-15
Keeper 1 (First Keeper)			30-Jan-15

V5C Certificate issue details

V5C Certificate Count	4	Certificate Dates	06-May-25 29-Jan-24 11-Oct-19 25-Mar-15
-----------------------	---	-------------------	--

Vehicle Tax & CO2 Emissions

Standard Six Month	***	Per Month	0
Standard Twelve Month	20	Per Month	1.67
First Year Six Month	***	Per Month	0
First Year Twelve Month	0	Per Month	0
Premium Vehicle Year 2 to 6 - Six Month	***	Per Month	0
Premium Vehicle Year 2 to 6 - Twelve Month	***	Per Month	0
VED CO2 Emissions	99 g/km	VED Band	A
VED CO2 Band	A		

Performance Information

Torque FtLb	162.4	Power Rpm	3750
Torque Rpm	1750	Power Bhp	90
Torque Nm	220	Power Kw	66
CO2	99	NoiseLevel	***
Max Speed Mph	104	Particles	***
Max Speed Kph	167	Data Version Number	***
Acceleration Zero To 60Mph	12.1	Acceleration Mph	12.1
Acceleration Zero To 100Kph	***	Acceleration Kph	***

Consumption

Combined Mpg	74.3	Combined Lkm	3.8
ExtraUrban Mpg	80.7	ExtraUrban Lkm	3.5
UrbanCold Mpg	65.7	UrbanCold Lkm	4.3

✓ Plate Change History

Plate Change Count	***
--------------------	-----

✓ Import/Export

Exported	No	Export Date	***
Imported	No		

✓ Scrap Destructions

Scrapped	No	Date of Scrapped	***
Certificate of Destruction Issued	No	Vehicle ID Check Count	0

✓ Colour Changes

Current Colour	GREY	Number Of Previous Colours	0
Last Colour	***	Date Of Last Colour Change	***
Original Colour	GREY		

✓ Previous VRM

Previous Northern Ireland	***	Previous UK VRM	***
---------------------------	-----	-----------------	-----

Dimensions

Gross Vehicle Weight	1590	Height	1523
Gross Combined Weight	1590	Width	1733
Kerb Weight	1033	Car Length	4057
Unladen Weight	1033	Wheel Base	2589
Fuel Tank Capacity	50	Pay Load Weight	***
Number Of Doors	5	Gross Train Weight	***
Number Of Seats	5	Payload Volume	***
Rigid Artic	RIGID	Load Length	***
Number Of Axles	2	Data Version Number	***
Body Shape	NA		

Safety

Adult	80	Child	79
Pedestrian	57		

Classification Details

SMMT Make	Dacia	DVLA Make	DACIA
SMMT Range	Sandero	DVLA Model	SANDERO MIDNIGHT DCI
SMMT Trim	Sandero Midnight dCi	Is Electric Vehicle	NO
SMMT Mvris MakeCode	***	Is GB General Format	***
SMMT Mvris ModelCode	***	Is NI General Format	***

Smmt Details

Marque	Dacia	Range	Sandero
Model Variant	Sandero Midnight dCi	Fuel Type	Diesel
Nominal Engine Capacity	1.5	Transmission	Manual
Engine Capacity	1461	Number Of Doors	5
Body Style	Hatchback	Number Of Gears	5
DriveType	4x2	SysSetup Date	31-Oct-14
Country Of Origin	Morocco	Visibility Date	31-Oct-14
Series	B52	Terminate Date	31-Dec-15
Marque Code	***	Cab Type	NA
Market Sector Code	AA	Data Version Number	***
Model Code	***		

MOT Test List

Date	Result	Mileage	Test Number
------	--------	---------	-------------

30-Apr-26



PASS

71975 MI

957499885312

Advisories

- ADVISORY** Front Sub-frame is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- ADVISORY** Integral body structure is corroded but structural rigidity is not significantly reduced general underbody and suspension components (6.1.1 (c) (i))

03-May-25



PASS

70169 MI

220475420662

18-Dec-24



FAIL

70145 MI

779364190822

Advisories

- ADVISORY** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- ADVISORY** Nearside Rear Tyre slightly damaged/cracking or perishing cracking through tread (5.2.3 (d) (ii))
- ADVISORY** Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall damaged (5.2.3 (d) (ii))
- ADVISORY** Nearside Play in steering rack inner joint(s)
- ADVISORY** Nearside Front Tyre worn close to legal limit/worn on edge on limit & scrubbed off inner & outer edges (5.2.3 (e))
- ADVISORY** Offside Front Tyre worn close to legal limit/worn on edge on limit & scrubbed off inner & outer edges (5.2.3 (e))

Failures

- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Offside Headlamp insecure bracket broken off (4.1.1 (c))
- MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Horn not working (7.7 (a))
- MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- MAJOR** Nearside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- MAJOR** Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- MAJOR** Offside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))
- MAJOR** Nearside Front Road wheel badly distorted inner rim (5.2.2 (c) (i))

01-Aug-23

**PASS**

59818 MI

602700974157

Advisories**ADVISORY** Offside Rear Service brake binding but not excessively (1.2.1 (f))

01-Aug-23

**FAIL**

59818 MI

847829735951

Advisories**ADVISORY** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Failures****DANGEROUS** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**DANGEROUS** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

27-Jul-22

**PASS**

55228 MI

736346838877

22-Jul-22

**FAIL**

55205 MI

185548889907

Failures**MAJOR** Nearside Front Outer Suspension arm ball joint excessively worn (5.3.4 (a) (i))

27-Jul-21

**PASS**

51301 MI

936395166941

23-Jul-21

**FAIL**

51247 MI

169845403866

Failures**DANGEROUS** Nearside Front Outer Anti-roll bar pin or bush likely to become detached (5.3.4 (a) (ii))

31-Jul-20

**PASS**

45725 MI

862009512151

13-Aug-19

**PASS**

41229 MI

438722808712

25-Jan-19

**PASS**

36345 MI

998490263617

Advisories**ADVISORY** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**ADVISORY** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

30-Jan-18



PASS

28772 MI

444511395343

Advisories

ADVISORY Nearside Front tyre tread cracked

ADVISORY Offside Front tyre tread cracked

ADVISORY Offside Rear tyre tread cracked

Disclaimer

CarBaBa provides free vehicle data but does not guarantee its precision. Although we strive to maintain up-to-date and accurate information, we are not responsible for any discrepancies, errors, or omissions. Users should independently verify details before making transactions and assume complete responsibility and liability for how they utilize the data.

Our platform is intended for general public use and not for commercial purposes. Traders should seek paid data services from providers like Experian or HPI.

We reserve the right to modify or discontinue vehicle data at any time. Users cannot demand continued access to this free service.

Additionally, our data cannot be used as legal evidence in any court or official capacity.

For any inaccuracies or suggestions, please contact us via our website. While we appreciate feedback, response times may vary due to high email volumes.

Our calculation of average mileage per year may be inaccurate if the MOT records include a combination of miles and kilometres.

If a vehicle has three consecutive 6-month MOTs, we classify it as being used for taxi or commercial purposes. However, in rare cases, this classification may be incorrect.